

**DLA Land and Maritime - VQ  
Supplemental Information Sheet for Electronic QPL-28804**

Date: 7/24/2018

**Specification Details:**

Specification: MIL-DTL-28804  
 Title: Connectors, Plug and Receptacle, Electric, Rectangular, High Density, Polarized Center Jackscrew  
 Federal Supply Class (FSC): 5935  
 Conventional: Yes  
 Specification contains quality assurance program: No  
 MIL-STD-790 Established Reliability & High Reliability: No  
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: No  
 Weibull Graded: No  
 Specification contains space level reliability requirements: No  
 Specification allows test optimization: No

**Contact Information:**

Office of Primary Involvement: Passive Devices Branch, DLA Land and Maritime - VQP  
 Primary Qualifying Activity Contact: 614-692-9389, e-mail: vqp.sy@dla.mil  
 Secondary Qualifying Activity Contact: 614-692-9519, e-mail: vqp.am@dla.mil

**Notes:**

N/A

**Part Configuration:**

M28804/1-1N

| Military Designator | Specification Sheet | Dash Number | Polarization |
|---------------------|---------------------|-------------|--------------|
| M                   | 28804/1             | -1          | N            |

**PART LISTINGS**

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/1-2N            | RB2A10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-2V            | RB2A10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-2W            | RB2A10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-2X            | RB2A10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-2Y            | RB2A10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-2Z            | RB2A10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3N            | RB2A12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3V            | RB2A12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3W            | RB2A12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3X            | RB2A12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3Y            | RB2A12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-3Z            | RB2A12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4N            | RB2A14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4V            | RB2A14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4W            | RB2A14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4X            | RB2A14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4Y            | RB2A14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-4Z            | RB2A14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5N            | RB2A16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5V            | RB2A16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5W            | RB2A16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5X            | RB2A16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5Y            | RB2A16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-5Z            | RB2A16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6N            | RB2A18C244SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6V            | RB2A18C244SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6W            | RB2A18C244SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6X            | RB2A18C244SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6Y            | RB2A18C244SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-6Z            | RB2A18C244SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-8N            | RK2A10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/1-8V            | RK2A10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-8W            | RK2A10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-8X            | RK2A10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-8Y            | RK2A10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-8Z            | RK2A10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9N            | RK2A12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9V            | RK2A12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9W            | RK2A12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9X            | RK2A12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9Y            | RK2A12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-9Z            | RK2A12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10N           | RK2A14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10V           | RK2A14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10W           | RK2A14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10X           | RK2A14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10Y           | RK2A14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-10Z           | RK2A14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11N           | RK2A16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11V           | RK2A16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11W           | RK2A16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11X           | RK2A16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11Y           | RK2A16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-11Z           | RK2A16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12N           | RK2A18C244SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12W           | RK2A18C244SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12X           | RK2A18C244SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12Y           | RK2A18C244SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12Z           | RK2A18C244SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/1-12V           | RK2A18C244SV000                           | 28804-463-75                    | Delphi Connection Systems              |
| M28804/2-2N            | RA9A10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-2V            | RA9A10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-2W            | RA9A10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-2X            | RA9A10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-2Y            | RA9A10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-2Z            | RA9A10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3N            | RA9A12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3V            | RA9A12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3W            | RA9A12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3X            | RA9A12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3Y            | RA9A12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-3Z            | RA9A12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4N            | RA9A14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4V            | RA9A14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4W            | RA9A14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4X            | RA9A14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4Y            | RA9A14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-4Z            | RA9A14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5N            | RA9A16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5V            | RA9A16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5W            | RA9A16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5X            | RA9A16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5Y            | RA9A16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-5Z            | RA9A16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-6N            | RA9A18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-6V            | RA9A18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-6W            | RA9A18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-6X            | RA9A18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/2-6Y            | RA9A18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-6Z            | RA9A18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8N            | RJ9A10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8V            | RJ9A10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8W            | RJ9A10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8X            | RJ9A10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8Y            | RJ9A10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-8Z            | RJ9A10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9N            | RJ9A12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9V            | RJ9A12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9W            | RJ9A12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9X            | RJ9A12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9Y            | RJ9A12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-9Z            | RJ9A12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10N           | RJ9A14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10V           | RJ9A14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10W           | RJ9A14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10X           | RJ9A14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10Y           | RJ9A14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-10Z           | RJ9A14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11N           | RJ9A16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11V           | RJ9A16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11W           | RJ9A16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11X           | RJ9A16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11Y           | RJ9A16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-11Z           | RJ9A16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12N           | RJ9A18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12V           | RJ9A18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12W           | RJ9A18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12X           | RJ9A18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12Y           | RJ9A18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/2-12Z           | RJ9A18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2N            | RB2E10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2V            | RB2E10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2W            | RB2E10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2X            | RB2E10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2Y            | RB2E10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-2Z            | RB2E10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3N            | RB2E12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3V            | RB2E12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3W            | RB2E12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3X            | RB2E12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3Y            | RB2E12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-3Z            | RB2E12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4N            | RB2E14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4V            | RB2E14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4W            | RB2E14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4X            | RB2E14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4Y            | RB2E14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-4Z            | RB2E14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5N            | RB2E16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5V            | RB2E16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5W            | RB2E16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5X            | RB2E16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5Y            | RB2E16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-5Z            | RB2E16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-6N            | RB2E18C244SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/3-6V            | RB2E18C244SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-6W            | RB2E18C244SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-6X            | RB2E18C244SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-6Y            | RB2E18C244SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-6Z            | RB2E18C244SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8N            | RK2E10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8V            | RK2E10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8W            | RK2E10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8X            | RK2E10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8Y            | RK2E10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-8Z            | RK2E10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9N            | RK2E12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9V            | RK2E12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9W            | RK2E12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9X            | RK2E12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9Y            | RK2E12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-9Z            | RK2E12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10N           | RK2E14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10V           | RK2E14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10W           | RK2E14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10X           | RK2E14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10Y           | RK2E14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-10Z           | RK2E14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11N           | RK2E16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11V           | RK2E16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11W           | RK2E16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11X           | RK2E16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11Y           | RK2E16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-11Z           | RK2E16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12N           | RK2E18C144SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12V           | RK2E18C144SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12W           | RK2E18C144SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12X           | RK2E18C144SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12Y           | RK2E18C144SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/3-12Z           | RK2E18C144SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2N            | RA9E10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2V            | RA9E10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2W            | RA9E10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2X            | RA9E10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2Y            | RA9E10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-2Z            | RA9E10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3N            | RA9E12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3V            | RA9E12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3W            | RA9E12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3X            | RA9E12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3Y            | RA9E12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-3Z            | RA9E12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4N            | RA9E14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4V            | RA9E14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4W            | RA9E14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4X            | RA9E14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4Y            | RA9E14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-4Z            | RA9E14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-5N            | RA9E16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-5V            | RA9E16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-5W            | RA9E16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-5X            | RA9E16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/4-5Y            | RA9E16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-5Z            | RA9E16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6N            | RA9E18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6V            | RA9E18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6W            | RA9E18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6X            | RA9E18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6Y            | RA9E18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-6Z            | RA9E18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8N            | RJ9E10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8V            | RJ9E10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8W            | RJ9E10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8X            | RJ9E10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8Y            | RJ9E10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-8Z            | RJ9E10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9N            | RJ9E12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9V            | RJ9E12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9W            | RJ9E12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9X            | RJ9E12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9Y            | RJ9E12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-9Z            | RJ9E12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10N           | RJ9E14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10V           | RJ9E14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10W           | RJ9E14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10X           | RJ9E14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10Y           | RJ9E14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-10Z           | RJ9E14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11N           | RJ9E16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11V           | RJ9E16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11W           | RJ9E16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11X           | RJ9E16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11Y           | RJ9E16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-11Z           | RJ9E16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12N           | RJ9E18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12V           | RJ9E18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12W           | RJ9E18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12X           | RJ9E18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12Y           | RJ9E18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/4-12Z           | RJ9E18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2N            | RB2P10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2V            | RB2P10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2W            | RB2P10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2X            | RB2P10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2Y            | RB2P10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-2Z            | RB2P10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3N            | RB2P12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3V            | RB2P12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3W            | RB2P12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3X            | RB2P12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3Y            | RB2P12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-3Z            | RB2P12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4N            | RB2P14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4V            | RB2P14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4W            | RB2P14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4X            | RB2P14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4Y            | RB2P14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-4Z            | RB2P14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-5N            | RB2P16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/5-5V            | RB2P16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-5W            | RB2P16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-5X            | RB2P16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-5Y            | RB2P16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-5Z            | RB2P16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6N            | RB2P18C244SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6V            | RB2P18C244SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6W            | RB2P18C244SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6X            | RB2P18C244SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6Y            | RB2P18C244SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-6Z            | RB2P18C244SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8N            | RK2P10C038SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8V            | RK2P10C038SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8W            | RK2P10C038SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8X            | RK2P10C038SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8Y            | RK2P10C038SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-8Z            | RK2P10C038SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9N            | RK2P12C088SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9V            | RK2P12C088SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9W            | RK2P12C088SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9X            | RK2P12C088SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9Y            | RK2P12C088SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-9Z            | RK2P12C088SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10N           | RK2P14C108SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10V           | RK2P14C108SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10W           | RK2P14C108SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10X           | RK2P14C108SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10Y           | RK2P14C108SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-10Z           | RK2P14C108SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11N           | RK2P16C132SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11V           | RK2P16C132SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11W           | RK2P16C132SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11X           | RK2P16C132SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11Y           | RK2P16C132SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-11Z           | RK2P16C132SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12N           | RK2P18C244SN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12V           | RK2P18C244SV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12W           | RK2P18C244SW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12X           | RK2P18C244SX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12Y           | RK2P18C244SY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/5-12Z           | RK2P18C244SZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2N            | RA9P10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2V            | RA9P10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2W            | RA9P10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2X            | RA9P10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2Y            | RA9P10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-2Z            | RA9P10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3N            | RA9P12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3V            | RA9P12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3W            | RA9P12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3X            | RA9P12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3Y            | RA9P12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-3Z            | RA9P12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-4N            | RA9P14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-4V            | RA9P14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-4W            | RA9P14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-4X            | RA9P14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/6-4Y            | RA9P14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-4Z            | RA9P14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5N            | RA9P16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5V            | RA9P16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5W            | RA9P16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5X            | RA9P16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5Y            | RA9P16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-5Z            | RA9P16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6N            | RA9P18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6V            | RA9P18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6W            | RA9P18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6X            | RA9P18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6Y            | RA9P18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-6Z            | RA9P18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8N            | RJ9P10C038PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8V            | RJ9P10C038PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8W            | RJ9P10C038PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8X            | RJ9P10C038PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8Y            | RJ9P10C038PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-8Z            | RJ9P10C038PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9N            | RJ9P12C088PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9V            | RJ9P12C088PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9W            | RJ9P12C088PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9X            | RJ9P12C088PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9Y            | RJ9P12C088PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-9Z            | RJ9P12C088PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10N           | RJ9P14C108PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10V           | RJ9P14C108PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10W           | RJ9P14C108PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10X           | RJ9P14C108PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10Y           | RJ9P14C108PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-10Z           | RJ9P14C108PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11N           | RJ9P16C132PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11V           | RJ9P16C132PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11W           | RJ9P16C132PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11X           | RJ9P16C132PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11Y           | RJ9P16C132PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-11Z           | RJ9P16C132PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12N           | RJ9P18C244PN000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12V           | RJ9P18C244PV000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12W           | RJ9P18C244PW000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12X           | RJ9P18C244PX000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12Y           | RJ9P18C244PY000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/6-12Z           | RJ9P18C244PZ000                           | 28804-463-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2N            | WNB038SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2V            | WNB038SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2W            | WNB038SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2X            | WNB038SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2Y            | WNB038SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2Z            | WNB038SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3N            | WNB088SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3V            | WNB088SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3W            | WNB088SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3X            | WNB088SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3Y            | WNB088SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-3Z            | WNB088SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-4N            | WNB108SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/7-4V            | WNB108SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-4W            | WNB108SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-4X            | WNB108SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-4Y            | WNB108SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-4Z            | WNB108SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5N            | WNB132SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5V            | WNB132SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5W            | WNB132SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5X            | WNB132SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5Y            | WNB132SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-5Z            | WNB132SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6N            | WNB244SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6V            | WNB244SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6W            | WNB244SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6X            | WNB244SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6Y            | WNB244SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-6Z            | WNB244SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8N            | WNK038SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8V            | WNK038SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8W            | WNK038SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8X            | WNK038SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8Y            | WNK038SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-8Z            | WNK038SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9N            | WNK088SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9V            | WNK088SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9W            | WNK088SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9X            | WNK088SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9Y            | WNK088SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-9Z            | WNK088SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10N           | WNK108SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10V           | WNK108SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10W           | WNK108SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10X           | WNK108SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10Y           | WNK108SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-10Z           | WNK108SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11N           | WNK132SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11V           | WNK132SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11W           | WNK132SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11X           | WNK132SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11Y           | WNK132SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-11Z           | WNK132SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12N           | WNK244SBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12V           | WNK244SBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12W           | WNK244SBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12X           | WNK244SBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12Y           | WNK244SBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-12Z           | WNK244SBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/7-2N            | CCM-022-038-1001                          | 28804-20-90                     | C W Industries                         |
| M28804/7-2V            | CCM-022-038-1002                          | 28804-20-90                     | C W Industries                         |
| M28804/7-2W            | CCM-022-038-1003                          | 28804-20-90                     | C W Industries                         |
| M28804/7-2X            | CCM-022-038-1004                          | 28804-20-90                     | C W Industries                         |
| M28804/7-2Y            | CCM-022-038-1005                          | 28804-20-90                     | C W Industries                         |
| M28804/7-2Z            | CCM-022-038-1006                          | 28804-20-90                     | C W Industries                         |
| M28804/7-3N            | CCM-022-088-1007                          | 28804-20-90                     | C W Industries                         |
| M28804/7-3V            | CCM-022-088-1008                          | 28804-20-90                     | C W Industries                         |
| M28804/7-3W            | CCM-022-088-1009                          | 28804-20-90                     | C W Industries                         |
| M28804/7-3X            | CM-022-088-1010                           | 28804-20-90                     | C W Industries                         |



## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/7-3Y            | CCM-022-088-1011                          | 28804-20-90                     | C W Industries                         |
| M28804/7-3Z            | CCM-022-088-1012                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5N            | CCM-022-132-1019                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5V            | CCM-022-132-1020                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5W            | CCM-022-132-1021                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5X            | CCM-022-132-1022                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5Y            | CCM-022-132-1023                          | 28804-20-90                     | C W Industries                         |
| M28804/7-5Z            | CCM-022-132-1024                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2N            | WNA038PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2V            | WNA038PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2W            | WNA038PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2X            | WNA038PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2Y            | WNA038PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2Z            | WNA038PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3N            | WNA088PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3V            | WNA088PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3W            | WNA088PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3X            | WNA088PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3Y            | WNA088PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-3Z            | WNA088PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4N            | WNA108PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4V            | WNA108PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4W            | WNA108PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4X            | WNA108PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4Y            | WNA108PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-4Z            | WNA108PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5N            | WNA132PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5V            | WNA132PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5W            | WNA132PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5X            | WNA132PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5Y            | WNA132PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-5Z            | WNA132PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6N            | WNA244PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6V            | WNA244PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6W            | WNA244PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6X            | WNA244PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6Y            | WNA244PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-6Z            | WNA244PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8N            | WNJ038PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8V            | WNJ038PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8W            | WNJ038PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8X            | WNJ038PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8Y            | WNJ038PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-8Z            | WNJ038PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9N            | WNJ088PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9V            | WNJ088PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9W            | WNJ088PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9X            | WNJ088PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9Y            | WNJ088PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-9Z            | WNJ088PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10N           | WNJ108PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10V           | WNJ108PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10W           | WNJ108PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10X           | WNJ108PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10Y           | WNJ108PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-10Z           | WNJ108PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-11N           | WNJ132PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/8-11V           | WNJ132PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-11W           | WNJ132PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-11X           | WNJ132PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-11Y           | WNJ132PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-11Z           | WNJ132PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12N           | WNJ244PBN001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12V           | WNJ244PBV001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12W           | WNJ244PBW001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12X           | WNJ244PBX001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12Y           | WNJ244PBY001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-12Z           | WNJ244PBZ001                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/8-2N            | CCM-024-038-1001                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2V            | CCM-024-038-1002                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2W            | CCM-024-038-1003                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2X            | CCM-024-038-1004                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2Y            | CCM-024-038-1005                          | 28804-20-90                     | C W Industries                         |
| M28804/8-2Z            | CCM-024-038-1006                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3N            | CCM-024-088-1007                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3V            | CCM-024-088-1008                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3W            | CCM-024-088-1009                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3X            | CCM-024-088-1010                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3Y            | CCM-024-088-1011                          | 28804-20-90                     | C W Industries                         |
| M28804/8-3Z            | CCM-024-088-1012                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5N            | CCM-024-132-1019                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5V            | CCM-024-132-1020                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5W            | CCM-024-132-1021                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5X            | CCM-024-132-1022                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5Y            | CCM-024-132-1023                          | 28804-20-90                     | C W Industries                         |
| M28804/8-5Z            | CCM-024-132-1024                          | 28804-20-90                     | C W Industries                         |
| M28804/9-1             | RP22D22                                   | 28804-465-75                    | Aptiv Services 3 US, LLC.              |
| M28804/10-1            | RS22D22                                   | 28804-465-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09N          | WNJ088PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09V          | WNJ088PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09W          | WNJ088PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09X          | WNJ088PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09Y          | WNJ088PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-09Z          | WNJ088PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10N          | WNJ108PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11N          | WNJ132PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12N          | WNJ244PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10V          | WNJ108PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11V          | WNJ132PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12V          | WNJ244PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10W          | WNJ108PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11W          | WNJ132PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12W          | WNJ244PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10X          | WNJ108PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11X          | WNJ132PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12X          | WNJ244PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10Y          | WNJ108PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11Y          | WNJ132PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12Y          | WNJ244PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-10Z          | WNJ108PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-11Z          | WNJ132PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-12Z          | WNJ244PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2N           | WNA038PBN                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M28804/11-2V           | WNA038PBV                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2W           | WNA038PBW                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2X           | WNA038PBX                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2Y           | WNA038PBY                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2Z           | WNA038PBZ                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3N           | WNA088PBN                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3V           | WNA088PBV                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3W           | WNA088PBW                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3X           | WNA088PBX                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3Y           | WNA088PBY                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-3Z           | WNA088PBZ                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4N           | WNA108PBN                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4V           | WNA108PBV                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4W           | WNA108PBW                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4X           | WNA108PBX                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4Y           | WNA108PBY                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-4Z           | WNA108PBZ                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5N           | WNA132PBN                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5V           | WNA132PBV                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5W           | WNA132PBW                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5X           | WNA132PBX                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5Y           | WNA132PBY                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-5Z           | WNA132PBZ                                 | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6N           | WNA244PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6V           | WNA244PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6W           | WNA244PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6X           | WNA244PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6Y           | WNA244PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-6Z           | WNA244PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8N           | WNJ038PBN000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8V           | WNJ038PBV000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8W           | WNJ038PBW000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8X           | WNJ038PBX000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8Y           | WNJ038PBY000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-8Z           | WNJ038PBZ000                              | 28804-464-75                    | Aptiv Services 3 US, LLC.              |
| M28804/11-2N           | CCM-020-038-1001                          | 28804-20-90                     | C W Industries                         |
| M28804/11-2V           | CCM-020-038-1002                          | 28804-20-90                     | C W Industries                         |
| M28804/11-2W           | CCM-020-038-1003                          | 28804-20-90                     | C W Industries                         |
| M28804/11-2X           | CCM-020-038-1004                          | 28804-20-90                     | C W Industries                         |
| M28804/11-2Y           | CCM-020-038-1005                          | 28804-20-90                     | C W Industries                         |
| M28804/11-2Z           | CCM-020-038-1006                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3N           | CCM-020-088-1007                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3V           | CCM-020-088-1008                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3W           | CCM-020-088-1009                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3X           | CCM-020-088-1010                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3Y           | CCM-020-088-1011                          | 28804-20-90                     | C W Industries                         |
| M28804/11-3Z           | CCM-020-088-1012                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5N           | CCM-020-132-1019                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5V           | CCM-020-132-1020                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5W           | CCM-020-132-1021                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5X           | CCM-020-132-1022                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5Y           | CCM-020-132-1023                          | 28804-20-90                     | C W Industries                         |
| M28804/11-5Z           | CCM-020-132-1024                          | 28804-20-90                     | C W Industries                         |
| M83446/36-01AG         | MLRF0603-0018AG                           |                                 |  |

---

**Manufacturer and Supplier Location Information**

---

**Manufacturer: Aptiv Services 3 US, LLC. (CAGE Code: 53669)**

Location: 30 Corporate Park Ste 303, Irvine, CA 92606-5133, US

## Plants:

1. Aptiv Contract Services Tijuana, S.A. de C.V., Blvd. Pacifico No. 8332, Parque Industrial Pacifico, Tijuana B.C. Mexico, C.P. 22643,

**Manufacturer: C W Industries (CAGE Code: 79727)**

Location: 130 James Way, Southampton, PA 18966-3838, US

## Plants:

1. Plant: Same Address as Manufacturer