



DEFENSE LOGISTICS AGENCY
DLA LAND AND MARITIME
POST OFFICE BOX 3990
COLUMBUS, OH 43218-3990

October 10, 2012

Mr. Don Huettenmueller
Design/Product Engineer
Airborn Interconnect Inc.
4321 Airborn Drive
Addison, Texas 75001-0519

Dear Mr. Huettenmueller:

Re: Qualification Testing of MIL-DTL-55302 epoxy design/construction change
Test Report Number: 55302-3544-12
Preparing Activity: DLA-CC, FSC 5395; Control Number: 037211; VQP-12-025124

This office has received your test report data (Test report #55302-3544-12) along with the request for the qualification of M55302 products with the use of a new epoxy. After review, the test results were found to meet the requirements of MIL-DTL-55302, and the use of the new epoxy is approved. Your listing on QPL M55302 will be maintained with the change in epoxy noted in our records.

Because we are held responsible for the accuracy and currency of the QPL, please let us know if your company discontinues production of these products. No changes are to be made in the design and construction of the qualified products without the approval of DLA LAND AND MARITIME.

If you have any questions please contact Ms. Sonya Taylor at Sonya.Taylor@dla.mil.

Sincerely,

/SIGNED/

JOSEPH GEMPERLINE
Chief
Sourcing and Qualifications Division