



DEFENSE LOGISTICS AGENCY  
LAND AND MARITIME  
POST OFFICE BOX 3990  
COLUMBUS, OH 43218-3990

October 11, 2013

Robert Wallick  
Reliability Engineer  
Winchester Electronics  
199 Park Road Extension  
Suite 104  
Middlebury, CT 06762

Dear Mr. Wallick:

Re: Qualification of M55302/1, /2, /4, /5, /6, /7, /8, /16, /17, /18, /21, /22, /55, /56, /57, /58,  
/59, /60, /61, /62, /63, /64, /65, /66

Test Report Number: 55302-3963-13; VQP-14-027128

Preparing Activity: DLA-CC, FSC 5935; Control Number: 040918

This office has received your email dated October 9, 2013 along with the test data for the re-qualification of the MIL-PRF-55302 slash sheets listed above. After review, the information was found to meet the requirements of MIL-PRF-55302. The next revision of the QPL-55302 will reflect the re-qualification of the following ; M55302/1, /2, /4, /5, /6, /7, /8, /16, /17, /18, /21, /22, /55, /56, /57, /58, /59, /60, /61, /62, /63, /64, /65, /66.

This qualification is subject to the conditions stated in DoD 4120.24-M and SD-6. Because we are held responsible for the accuracy and currency of this QPL, please let us know if your company discontinues production of these products.

If you have any questions concerning this letter, please contact Ms. Sonya Taylor at 614-692-2193 or Sonya.Taylor@dla.mil.

Sincerely,

/SIGNED/

JOSEPH GEMPERLINE  
Chief  
Sourcing and Qualifications Division