



DEFENSE LOGISTICS AGENCY
LAND AND MARITIME
POST OFFICE BOX 3990
COLUMBUS, OH 43218-3990

March 31, 2014

Don Huettenmueller
AirBorn Interconnect Inc.
4321 AirBorn Drive
Addison, Texas 75001-0519

Dear Mr. Huettenmueller:

Re: Qualification of M55302/119 design change using new epoxy
Test Report Number: 55302-3755-13; VQP-14-027784
Preparing Activity: DLA-CC, FSC 5935; Control Number: 042341

This office has received your email dated February 6, 2014 along with the test data for the re-qualification of MIL-DTL-55302/119. After review, the information was found to meet the requirements of MIL-DTL-55302. Therefore your qualification of the M55302/119 parts utilizing the new epoxy will be updated in our records, although the test report listed will continue to be that of the initial qualification for this part.

This qualification is subject to the conditions stated in DoD 4120.24-M and SD-6. Because we are held responsible for the accuracy and currency of this QPL, please let us know if your company discontinues production of these products.

If you have any questions concerning this letter, please contact Ms. Sonya Taylor at 614-692-2193 or email Sonya.Taylor@dla.mil.

Sincerely,

/SIGNED/

JOSEPH GEMPERLINE
Chief
Sourcing and Qualifications Division