

**DLA Land and Maritime - VQ
Supplemental Information Sheet for Electronic QPL-83725**

Date: 8/13/2019

Specification Details:

Specification: MIL-DTL-83725
 Title: Relays, Vacuum
 Federal Supply Class (FSC): 5945
 Conventional: Yes
 Specification contains quality assurance program: No
 MIL-STD-790 Established Reliability & High Reliability: No
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
 Weibull Graded: No
 Specification contains space level reliability requirements: No
 Specification allows test optimization: No

Contact Information:

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH
 Primary Qualifying Activity Contact: 614-692-0594, e-mail: vqh.kr@dla.mil
 Secondary Qualifying Activity Contact: 614-692-0586, e-mail: vqh.bt@dla.mil

Notes:

Contact the manufacturer or refer to the manufacturers website for a list of Authorized Distributors.

Part Configuration:

M83725/5-001

| Military Designator | General Specification | Specification Sheet Number | Dash Number |
|---------------------|-----------------------|----------------------------|-------------|
| M | 83725 | /5 | -001 |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|---|
| M83725/1-001 | MH-8A | | |
| M83725/1-002 | MH-8 | 83725-96-0185 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/1-003 | MH-8C | 83725-96-0185 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/1-004 | MH-8AF | 83725-96-0185 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/1-005 | MH-8F | 83725-96-0185 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/1-006 | MH-8CF | 83725-96-0185 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/2-001 | MH-17A | 83725-96-0186 | Tyco Electronics/CII Relays (India) |
| M83725/2-002 | MH-17 | 83725-96-0186 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/2-003 | MH-17C | 83725-96-0186 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/2-004 | MH-17A/115VDC | 83725-96-0186 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|---|
| M83725/2-005 | MH-17/115VDC | 83725-96-0186 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/2-006 | MH-17C/115VDC | 83725-96-0186 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/4-001 | MHC-3 | 83725-96-0187 | Tyco Electronics/CII Relays (India) |
| M83725/5-001 | MHC-1 | 83725-96-0188 | Tyco Electronics/CII Relays (India) |
| M83725/10-001 | MK43B834-001 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-002 | MK43B832-002 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-003 | MK43B332-003 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-004 | MK43B332-004 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-005 | MK43B734-005 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-006 | MK43B732-006 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-007 | MK43B234-007 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/10-008 | MK43B232-008 | 83725-96-0189 | Tyco Electronics/CII Relays (India) |
| M83725/16-001 | MK43C734-001 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-002 | MK43C834-002 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-003 | MK43C732-003 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-004 | MK43C832-004 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-005 | MK43C234-005 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-006 | MK43C334-006 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-007 | MK43C232-007 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/16-008 | MK43C332-008 | 83725-96-0190 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-001 | MK43A834-001 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|---|
| M83725/17-002 | MK43A832-002 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-003 | MK43A334-003 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-004 | MK43A332-004 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-005 | MK43A734-005 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-006 | MK43A732-006 | 83725-96-0191 | Tyco Electronics/CII Relays (India) |
| M83725/17-007 | MK43A234-007 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/17-008 | MK43A232-008 | 83725-96-0191 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/18-003 | MK47B334-003 | 83725-96-0192 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-001 | MK41A234-001 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-002 | MK41A334-002 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-003 | MK41A534-003 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-004 | MK41A232-004 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-005 | MK41A332-005 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-006 | MK41A532-006 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-007 | MK41A734-007 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-008 | MK41A834-008 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-009 | MK41A934-009 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-010 | MK41A732-010 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|---|
| M83725/21-011 | MK41A832-011 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/21-012 | MK41A932-012 | 83725-96-0193 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-001 | MK41B234-001 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-002 | MK41B334-002 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-003 | MK41B534-003 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-004 | MK41B232-004 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-005 | MK41B332-005 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-006 | MK41B532-006 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-007 | MK41B734-007 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-008 | MK41B834-008 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-009 | MK41B934-009 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-010 | MK41B732-010 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-011 | MK41B832-011 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/22-012 | MK41B932-012 | 83725-96-0194 | Tyco Electronics/CII Relays (India) Tyco, TE Conectivity High Performance Group - Relays |
| M83725/23-001 | MK41C234-001 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-002 | MK41C334-002 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-003 | MK41C534-003 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-004 | MK41C232-004 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-005 | MK41C332-005 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-006 | MK41C532-006 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M83725/23-007 | MK41C734-007 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-008 | MK41C834-008 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-009 | MK41C934-009 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-010 | MK41C732-010 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-011 | MK41C832-011 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/23-012 | MK41C932-012 | 83725-96-0195 | Tyco Electronics/CII Relays (India) |
| M83725/24-001 | MK41P334-001 | 83725-96-0196 | Tyco Electronics/CII Relays (India) |
| M83725/24-002 | MK41P332-002 | 83725-96-0196 | Tyco Electronics/CII Relays (India) |
| M83725/24-003 | MK40P334-003 | 83725-96-0196 | Tyco Electronics/CII Relays (India) |
| M83725/24-004 | MK40P332-004 | 83725-96-0196 | Tyco Electronics/CII Relays (India) |

Manufacturer and Supplier Location Information

Manufacturer: Tyco, TE Conectivity High Performance Group - Relays (CAGE Code: 58614)

Location: Ashville Operations, 1396 Charlotte Highway, Fairview, NC 28730, US

Assembly Plants:

1. Tyco Electronics/CII Relays (India), 16 Garment Complex, CSEZ, Kakkand, Cochin, 682037, India)

Plants:

1. Plant: Same Address as Manufacturer