

**DLA Land and Maritime - VQ
Supplemental Information Sheet for Electronic QPL-24308**

Date: 9/3/2019

Specification Details:

Specification: MIL-DTL-24308
 Title: Connectors, Electrical, Rectangular, Nonenvironmental, Miniature, Polarized Shell, Rack & Panel
 Federal Supply Class (FSC): 5935
 Conventional: No
 Specification contains quality assurance program: No
 MIL-STD-790 Established Reliability & High Reliability: Yes
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
 Weibull Graded: No
 Specification contains space level reliability requirements: No
 Specification allows test optimization: No

Contact Information:

Office of Primary Involvement: Passive Devices Branch, DLA Land and Maritime - VQP
 Primary Qualifying Activity Contact: 614-692-8367, e-mail: vqp.es@dla.mil
 Secondary Qualifying Activity Contact: 614-692-9519, e-mail: vqp.am@dla.mil

Notes:

N/A

Part Configuration:

M24308/1-1F

| Military Designation | Specification Sheet Number | Dash Number | Finish |
|----------------------|----------------------------|-------------|--------|
| M | /1 | -1 | F |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/1-1F | GPM-C01S-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-1Z | GPM-Z01S-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-2F | GPM-C01S-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-2Z | GPM-Z01S-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-3F | GPM-C01S-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-3Z | GPM-Z01S-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-4F | GPM-C01S-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-4Z | GPM-Z01S-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-5F | GPM-C01S-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-5Z | GPM-Z01S-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-12F | GPM-C01F-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-12Z | GPM-Z01F-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-13F | GPM-C01F-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-13Z | GPM-Z01F-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-14F | GPM-C01F-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-14Z | GPM-Z01F-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-15F | GPM-C01F-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-15Z | GPM-Z01F-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-16F | GPM-C01F-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-16Z | GPM-Z01F-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-23F | GPM-C01D-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-23Z | GPM-Z01D-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-24F | GPM-C01D-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-24Z | GPM-Z01D-00015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-25F | GPM-C01D-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-25Z | GPM-Z01D-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-26F | GPM-C01D-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-26Z | GPM-Z01D-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-27F | GPM-C01D-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/1-27Z | GPM-Z01D-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/1-1F | M2000/1-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-1K | M2000/1-1K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-1Z | M2000/1-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-2F | M2000/1-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-2K | M2000/1-2K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-2Z | M2000/1-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-3F | M2000/1-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-3K | M2000/1-3K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-3Z | M2000/1-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-4F | M2000/1-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-4K | M2000/1-4K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-4Z | M2000/1-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-5F | M2000/1-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-5K | M2000/1-5K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-5Z | M2000/1-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-12F | M2000/1-12F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-12K | M2000/1-12K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-12Z | M2000/1-12Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-13F | M2000/1-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-13K | M2000/1-13K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-13Z | M2000/1-13Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-14F | M2000/1-14F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-14K | M2000/1-14K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-14Z | M2000/1-14Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-15F | M2000/1-15F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-15K | M2000/1-15K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-15Z | M2000/1-15Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-16F | M2000/1-16F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-16K | M2000/1-16K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-16Z | M2000/1-16Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-23F | M2000/1-23F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-23K | M2000/1-23K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-23Z | M2000/1-23Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-24F | M2000/1-24F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-24K | M2000/1-24K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-24Z | M2000/1-24Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-25F | M2000/1-25F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-25K | M2000/1-25K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-25Z | M2000/1-25Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-26F | M2000/1-26F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-26K | M2000/1-26K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-26Z | M2000/1-26Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-27F | M2000/1-27F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-27K | M2000/1-27K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-27Z | M2000/1-27Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-34 | M2000/1-34 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-35 | M2000/1-35 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-36 | M2000/1-36 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-37 | M2000/1-37 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-38 | M2000/1-38 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-45 | M2000/1-45 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-46 | M2000/1-46 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-47 | M2000/1-47 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-48 | M2000/1-48 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-49 | M2000/1-49 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-56 | M2000/1-56 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-57 | M2000/1-57 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/1-58 | M2000/1-58 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-59 | M2000/1-59 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-60 | M2000/1-60 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/1-1F | 230-09-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-1Z | 230-09-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-2F | 230-15-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-2Z | 230-15-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-3F | 230-25-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-3Z | 230-25-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-4F | 230-37-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-4Z | 230-37-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-5F | 230-50-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-5Z | 230-50-09-129 | 261, JUN 69 | Cinch Connectors, Inc. |
| M24308/1-12F | 230-09-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-12Z | 230-09-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-13F | 230-15-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-13Z | 230-15-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-14F | 230-25-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-14Z | 230-25-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-15F | 230-37-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-15Z | 230-37-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-16F | 230-50-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-16Z | 230-50-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-23F | 230-09-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-23Z | 230-09-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-24F | 230-15-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-24Z | 230-15-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-25F | 230-25-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-25Z | 230-25-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-26F | 230-37-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-26Z | 230-37-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-27F | 230-50-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-27Z | 230-50-09-390 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/1-1F | DEG9S2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-2F | DAG15S2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-3F | DBG25S2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-4F | DCG37S2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-5F | DDG50S2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-12F | DEG9S2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-13F | DAG15S2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-14F | DBG25S2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-15F | DCG37S2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-16F | DDG50S2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-23F | DEG9S2D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-24F | DAG15S2D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-25F | DBG25S2D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-26F | DCG37S2D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-27F | DDG50S2D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/1-1F | M24308/1-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-1Z | M24308/1-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-2F | M24308/1-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-2Z | M24308/1-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-3F | M24308/1-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-3Z | M24308/1-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-4F | M24308/1-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-4Z | M24308/1-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-5F | M24308/1-5F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/1-5Z | M24308/1-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-12F | M24308/1-12F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-12Z | M24308/1-12Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-13F | M24308/1-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-13Z | M24308/1-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-14F | M24308/1-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-14Z | M24308/1-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-15F | M24308/1-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-15Z | M24308/1-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-16F | M24308/1-16F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-16Z | M24308/1-16Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-23F | M24308/1-23F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-23Z | M24308/1-23Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-24F | M24308/1-24F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-24Z | M24308/1-24Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-25F | M24308/1-25F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-25Z | M24308/1-25Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-26F | M24308/1-26F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-26Z | M24308/1-26Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-27F | M24308/1-27F | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-27Z | M24308/1-27Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/1-1F | HDC9S2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-1Z | HDC9S20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-2F | HDC15S2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-2Z | HDC15S20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-3F | HDC25S2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-3Z | HDC25S20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-4F | HDC37S2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-4Z | HDC37S20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-5F | HDC50S2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-5Z | HDC50S20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-23F | HDC9S2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-23Z | HDC9S2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-24F | HDC15S2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-24Z | HDC15S2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-25F | HDC25S2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-25Z | HDC25S2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-26F | HDC37S2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-26Z | HDC37S2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-27F | HDC50S2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-27Z | HDC50S2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-34 | HDC9S20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-35 | HDC15S20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-36 | HDC25S20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-37 | HDC37S20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-38 | HDC50S20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-56 | HDC9S2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-57 | HDC15S2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-58 | HDC25S2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-59 | HDC37S2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-60 | HDC50S2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/1-1F | DEM09S-032N | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-1Z | DEM09S-032 | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-2F | DAM15S-032N | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-2Z | DAM15S-032 | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-3F | DBM25S-032N | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-3Z | DBM25S-032 | 24308-169-77; 24308-326-86 | Souriau |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/1-4F | DCM37S-032N | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-4Z | DCM37S-032 | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-5F | DDM50S-032N | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-5Z | DDM50S-032 | 24308-169-77; 24308-326-86 | Souriau |
| M24308/1-12F | DEMF09S-032N | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-12Z | DEMF09S-032 | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-13F | DAMF15S-032N | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-13Z | DAMF15S-032 | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-14F | DBMF25S-032N | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-14Z | DBMF25S-032 | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-15F | DCMF37S-032N | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-15Z | DCMF37S-032 | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-16F | DDMF50S-032N | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-16Z | DDMF50S-032 | 24308-309-79; 24308-326-86 | Souriau |
| M24308/1-23F | DEMF09S-032N | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-23Z | DEMF09S-032 | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-24F | DAMF15S-032N | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-24Z | DAMF15S-032 | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-25F | DBMF25S-032N | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-25Z | DBMF25S-032 | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-26F | DCMF37S-032N | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-26Z | DCMF37S-032 | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-27F | DDMF50S-032N | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/1-27Z | DDMF50S-032 | 24308-1042-82; 24308-326-86 | Souriau |
| M24308/2-1F | GPM-C05S-00009S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-1Z | GPM-Z05S-00009S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-2F | GPM-C05S-00015S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-2Z | GPM-Z05S-00015S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-3F | GPM-C05S-00025S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-3Z | GPM-Z05S-00025S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-4F | GPM-C05S-00037S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-4Z | GPM-Z05S-00037S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-5F | GPM-C05S-00050S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-5Z | GPM-Z05S-00050S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-6F | GPM-C05S-00009S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-6Z | GPM-Z05S-00009S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-7F | GPM-C05S-00015S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-7Z | GPMZC05S-00015S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-8F | GPM-C05S-00025S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-8Z | GPM-Z05S-00025S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-9F | GPM-C05S-00037S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-9Z | GPM-Z05S-00037S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-10F | GPM-C05S-00050S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-10Z | GPM-Z05S-00050S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-11F | GLM-C04S-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-11Z | GLM-Z04S-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-12F | GLM-C04S-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-12Z | GLM-Z04S-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-13F | GLM-C04S-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-13Z | GLM-Z04S-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-14F | GLM-C04S-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-14Z | GLM-Z04S-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-15F | GLM-C04S-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-15Z | GLM-Z04S-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-17F | GLM-C04S-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-17Z | GLM-Z04S-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-18F | GLM-C04S-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-18Z | GLM-Z04S-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-19F | GLM-C04S-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-19Z | GLM-Z04S-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-20F | GLM-C04S-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-20Z | GLM-Z04S-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-21F | GLM-C04S-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-21Z | GLM-Z04S-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-23F | GPM-C05F-00009S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-23 | GPM-Z05F-00009S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-24F | GPM-C05F-00015S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-24 | GPM-Z05F-00015S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-25F | GPM-C05F-00025S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-25 | GPM-Z05F-00025S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-26F | GPM-C05F-00037S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-26 | GPM-Z05F-00037S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-27F | GPM-C05F-00050S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-27 | GPM-Z05F-00050S-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-28F | GLM-C04F-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-28Z | GLM-Z04F-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-29F | GLM-C04F-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-29Z | GLM-Z04F-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-30F | GLM-C04F-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-30Z | GLM-Z04F-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-31F | GLM-C04F-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-31Z | GLM-Z04F-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-32F | GLM-C04F-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-32Z | GLM-Z04F-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-34F | GPM-C05F-00009S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-34 | GPM-Z05F-00009S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-35F | GPM-C05F-00015S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-35 | GPM-Z05F-00015S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-36F | GPM-C05F-00025S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-36 | GPM-Z05F-00025S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-37F | GPM-C05F-00037S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-37 | GPM-Z05F-00037S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-38F | GPM-C05F-00050S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-38 | GPM-Z05F-00050S-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-39F | GLM-C04F-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-39Z | GLM-Z04F-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-40F | GLM-C04F-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-40Z | GLM-Z04F-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-41F | GLM-C04F-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-41Z | GLM-Z04F-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-42F | GLM-C04F-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-42Z | GLM-Z04F-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-43F | GLM-C04F-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-43Z | GLM-Z04F-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-281F | GPM-C05S-00009S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-281 | GPM-Z05S-00009S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-282F | GPM-C05S-00015S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-282 | GPM-Z05S-00015S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-283F | GPM-C05S-00025S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-283 | GPM-Z05S-00025S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-284F | GPM-C05S-00037S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-284 | GPM-Z05S-00037S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-285F | GPM-C05S-00050S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-285 | GPM-Z05S-00050S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-286F | GLM-C04S-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-286Z | GLM-Z04S-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-287F | GLM-C04S-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-287Z | GLM-Z04S-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-288F | GLM-C04S-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-288Z | GLM-Z04S-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-289F | GLM-C04S-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-289Z | GLM-Z04S-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-290F | GLM-C04S-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-290Z | GLM-Z04S-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-292F | GPM-C05F-00009S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-292 | GPM-Z05F-00009S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-293F | GPM-C05F-00015S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-293 | GPM-Z05F-00015S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-294F | GPM-C05F-00025S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-294 | GPM-Z05F-00025S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-295F | GPM-C05F-00037S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-295 | GPM-Z05F-00037S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-296F | GPM-C05F-00050S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-296 | GPM-Z05F-00050S-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/2-297F | GLM-C04F-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-297Z | GLM-Z04F-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-298F | GLM-C04F-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-298Z | GLM-Z04F-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-299F | GLM-C04F-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-299Z | GLM-Z04F-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-300F | GLM-C04F-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-300Z | GLM-Z04F-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-301F | GLM-C04F-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-301Z | GLM-Z04F-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-335F | GPM-C05R-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-335 | GPM-Z05R-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-336F | GPM-C05R-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-336 | GPM-Z05R-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-341F | GPM-C05R-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-341 | GPM-Z05R-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-342F | GPM-C05D-00009S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-342 | GPM-Z05D-00009S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-343F | GPM-C05D-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-343 | GPM-Z05D-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-344F | GPM-C05D-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-344 | GPM-Z05D-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-345F | GPM-C05D-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-345 | GPM-Z05D-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-346F | GPM-C05D-00050S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-346 | GPM-Z05D-00050S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-347F | GLM-C04D-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-347Z | GLM-Z04D-00015S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-348F | GLM-C04D-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-348Z | GLM-Z04D-00026S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-349F | GLM-C04D-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-349Z | GLM-Z04D-00044S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-350F | GLM-C04D-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-350Z | GLM-Z04D-00062S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-351F | GLM-C04D-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-351Z | GLM-Z04D-00078S-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-353F | GPM-C05D-00009S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-353 | GPM-Z05D-00009S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-354F | GPM-C05D-00015S-03 | 24308-84-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-354 | GPM-Z05D-00015S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-355F | GPM-C05D-00025S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-355 | GPM-Z05D-00025S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-356F | GPM-C05D-00037S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-356 | GPM-Z05D-00037S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-357F | GPM-C05D-00050S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-357 | GPM-Z05D-00050S-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-358F | GLM-C04D-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-358Z | GLM-Z04D-00015S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-359F | GLM-C04D-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-359Z | GLM-Z04D-00026S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-360F | GLM-C04D-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-360Z | GLM-Z04D-00044S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-361F | GLM-C04D-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-361Z | GLM-Z04D-00062S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-362F | GLM-C04D-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-362Z | GLM-Z04D-00078S-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-482F | GPM-C05D-00009S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-482 | GPM-Z05D-00009S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-483F | GPM-C05D-00015S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-483 | GPM-Z05D-00015S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-484F | GPM-C05D-00025S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-484 | GPM-Z05D-00025S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-485F | GPM-C05D-00037S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-485 | GPM-Z05D-00037S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-486F | GPM-C05D-00050S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-486 | GPM-Z05D-00050S-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-487F | GLM-C04D-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-487Z | GLM-Z04D-00015S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-488F | GLM-C04D-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-488Z | GLM-Z04D-00026S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-489F | GLM-C04D-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-489Z | GLM-Z04D-00044S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-490F | GLM-C04D-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-490Z | GLM-Z04D-00062S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-491F | GLM-C04D-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-491Z | GLM-Z04D-00078S-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/2-509F | GPM-C05D-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-509 | GPM-Z05D-00025S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-510F | GPM-C05D-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-510 | GPM-Z05D-00037S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-515F | GPM-C05D-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-515 | GPM-Z05D-00015S-02 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/2-1F | M2000/2-1F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-1K | M2000/2-1K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-1Z | M2000/2-1Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-2F | M2000/2-2F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-2K | M2000/2-2K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-2Z | M2000/2-2Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-3F | M2000/2-3F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-3K | M2000/2-3K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-3Z | M2000/2-3Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-4F | M2000/2-4F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-4K | M2000/2-4K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-4Z | M2000/2-4Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-5F | M2000/2-5F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-5K | M2000/2-5K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-5Z | M2000/2-5Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-6F | M2000/2-6F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-6K | M2000/2-6K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-6Z | M2000/2-6Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-7F | M2000/2-7F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-7K | M2000/2-7K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-7Z | M2000/2-7Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-8F | M2000/2-8F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-8K | M2000/2-8K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-8Z | M2000/2-8Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-9F | M2000/2-9F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-9K | M2000/2-9K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-9Z | M2000/2-9Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-10F | M2000/2-10F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-10K | M2000/2-10K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-10Z | M2000/2-10Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-11F | M2000/2-11F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-11K | M2000/2-11K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-11Z | M2000/2-11Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-12F | M2000/2-12F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-12K | M2000/2-12K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-12Z | M2000/2-12Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-13F | M2000/2-13F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-13K | M2000/2-13K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-13Z | M2000/2-13Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-14F | M2000/2-14F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-14K | M2000/2-14K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-14Z | M2000/2-14Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-15F | M2000/2-15F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-15K | M2000/2-15K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-15Z | M2000/2-15Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-16F | M2000/2-16F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-16K | M2000/2-16K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-16Z | M2000/2-16Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-17F | M2000/2-17F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-17K | M2000/2-17K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-17Z | M2000/2-17Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-18F | M2000/2-18F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-18K | M2000/2-18K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-18Z | M2000/2-18Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-19F | M2000/2-19F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-19K | M2000/2-19K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-19Z | M2000/2-19Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-20F | M2000/2-20F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-20K | M2000/2-20K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-20Z | M2000/2-20Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-21F | M2000/2-21F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-21K | M2000/2-21K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-21Z | M2000/2-21Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-22F | M2000/2-22F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-22K | M2000/2-22K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-22Z | M2000/2-22Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-23F | M2000/2-23F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-23K | M2000/2-23K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-23Z | M2000/2-23Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-24F | M2000/2-24F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-24K | M2000/2-24K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-24Z | M2000/2-24Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-25F | M2000/2-25F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-25K | M2000/2-25K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-25Z | M2000/2-25Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-26F | M2000/2-26F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-26K | M2000/2-26K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-26Z | M2000/2-26Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-27F | M2000/2-27F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-27K | M2000/2-27K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-27Z | M2000/2-27Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-28F | M2000/2-28F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-28K | M2000/2-28K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-28Z | M2000/2-28Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-29F | M2000/2-29F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-29K | M2000/2-29K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-29Z | M2000/2-29Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-30F | M2000/2-30F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-30K | M2000/2-30K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-30Z | M2000/2-30Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-31F | M2000/2-31F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-31K | M2000/2-31K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-31Z | M2000/2-31Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-32F | M2000/2-32F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-32K | M2000/2-32K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-32Z | M2000/2-32Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-33F | M2000/2-33F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-33K | M2000/2-33K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-33Z | M2000/2-33Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-34F | M2000/2-34F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-34K | M2000/2-34K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-34Z | M2000/2-34Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-35F | M2000/2-35F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-35K | M2000/2-35K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-35Z | M2000/2-35Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-36F | M2000/2-36F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-36K | M2000/2-36K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-36Z | M2000/2-36Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-37F | M2000/2-37F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-37K | M2000/2-37K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-37Z | M2000/2-37Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-38F | M2000/2-38F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-38K | M2000/2-38K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-38Z | M2000/2-38Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-39F | M2000/2-39F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-39K | M2000/2-39K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-39Z | M2000/2-39Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-40F | M2000/2-40F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-40K | M2000/2-40K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-40Z | M2000/2-40Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-41F | M2000/2-41F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-41K | M2000/2-41K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-41Z | M2000/2-41Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-42F | M2000/2-42F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-42K | M2000/2-42K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-42Z | M2000/2-42Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-43F | M2000/2-43F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-43K | M2000/2-43K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-43Z | M2000/2-43Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-44F | M2000/2-44F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-44K | M2000/2-44K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-44Z | M2000/2-44Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-281F | M2000/2-281F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-281K | M2000/2-281K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-281Z | M2000/2-281Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-282F | M2000/2-282F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-282K | M2000/2-282K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-282Z | M2000/2-282Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-283F | M2000/2-283F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-283K | M2000/2-283K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-283Z | M2000/2-283Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-284F | M2000/2-284F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-284K | M2000/2-284K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-284Z | M2000/2-284Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-285F | M2000/2-285F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-285K | M2000/2-285K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-285Z | M2000/2-285Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-286F | M2000/2-286F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-286K | M2000/2-286K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-286Z | M2000/2-286Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-287F | M2000/2-287F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-287K | M2000/2-287K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-287Z | M2000/2-287Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-288F | M2000/2-288F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-288K | M2000/2-288K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-288Z | M2000/2-288Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-289F | M2000/2-289F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-289K | M2000/2-289K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-289Z | M2000/2-289Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-290F | M2000/2-290F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-290K | M2000/2-290K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-290Z | M2000/2-290Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/2-291F | M2000/2-291F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-291K | M2000/2-291K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-291Z | M2000/2-291Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-292F | M2000/2-292F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-292K | M2000/2-292K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-292Z | M2000/2-292Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-293F | M2000/2-293F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-293K | M2000/2-293K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-293Z | M2000/2-293Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-294F | M2000/2-294F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-294K | M2000/2-294K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-294Z | M2000/2-294Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-295F | M2000/2-295F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-295K | M2000/2-295K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-295Z | M2000/2-295Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-296F | M2000/2-296F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-296K | M2000/2-296K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-296Z | M2000/2-296Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-297F | M2000/2-297F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-297K | M2000/2-297K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-297Z | M2000/2-297Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-298F | M2000/2-298F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-298K | M2000/2-298K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-298Z | M2000/2-298Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-299F | M2000/2-299F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-299K | M2000/2-299K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-299Z | M2000/2-299Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-300F | M2000/2-300F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-300K | M2000/2-300K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-300Z | M2000/2-300Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-301F | M2000/2-301F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-301K | M2000/2-301K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-301Z | M2000/2-301Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-302F | M2000/2-302F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-302K | M2000/2-302K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-302Z | M2000/2-302Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-335F | M2000/2-335F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-335K | M2000/2-335K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-335Z | M2000/2-335Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-336F | M2000/2-336F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-336K | M2000/2-336K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-336Z | M2000/2-336Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-341F | M2000/2-341F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-341K | M2000/2-341K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-341Z | M2000/2-341Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-342F | M2000/2-342F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-342K | M2000/2-342K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-342Z | M2000/2-342Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-343F | M2000/2-343F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-343K | M2000/2-343K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-343Z | M2000/2-343Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-344F | M2000/2-344F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-344K | M2000/2-344K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-344Z | M2000/2-344Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-345F | M2000/2-345F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-345K | M2000/2-345K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-345Z | M2000/2-345Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-346F | M2000/2-346F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-346K | M2000/2-346K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-346Z | M2000/2-346Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-347F | M2000/2-347F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-347K | M2000/2-347K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-347Z | M2000/2-347Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-348F | M2000/2-348F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-348K | M2000/2-348K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-348Z | M2000/2-348Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-349F | M2000/2-349F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-349K | M2000/2-349K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-349Z | M2000/2-349Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-350F | M2000/2-350F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-350K | M2000/2-350K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-350Z | M2000/2-350Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-351F | M2000/2-351F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-351K | M2000/2-351K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-351Z | M2000/2-351Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-352F | M2000/2-352F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-352K | M2000/2-352K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-352Z | M2000/2-352Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-353F | M2000/2-353F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-353K | M2000/2-353K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-353Z | M2000/2-353Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-354F | M2000/2-354F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-354K | M2000/2-354K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-354Z | M2000/2-354Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-355F | M2000/2-355F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-492Z | M2000/2-492Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-509F | M2000/2-509F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-509K | M2000/2-509K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-509Z | M2000/2-509Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-510F | M2000/2-510F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-510K | M2000/2-510K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-510Z | M2000/2-510Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-515F | M2000/2-515F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-515K | M2000/2-515K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-515Z | M2000/2-515Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-516 | M2000/2-516 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-517 | M2000/2-517 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-518 | M2000/2-518 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-519 | M2000/2-519 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-520 | M2000/2-520 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-521 | M2000/2-521 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-522 | M2000/2-522 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-523 | M2000/2-523 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-524 | M2000/2-524 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-525 | M2000/2-525 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-526 | M2000/2-526 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-527 | M2000/2-527 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-528 | M2000/2-528 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-529 | M2000/2-529 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-530 | M2000/2-530 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-531 | M2000/2-531 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-532 | M2000/2-532 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-533 | M2000/2-533 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-534 | M2000/2-534 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-535 | M2000/2-535 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-536 | M2000/2-536 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-537 | M2000/2-537 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-538 | M2000/2-538 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-539 | M2000/2-539 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-540 | M2000/2-540 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-541 | M2000/2-541 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-542 | M2000/2-542 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-543 | M2000/2-543 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-544 | M2000/2-544 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-545 | M2000/2-545 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-546 | M2000/2-546 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-547 | M2000/2-547 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-548 | M2000/2-548 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-549 | M2000/2-549 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-550 | M2000/2-550 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-551 | M2000/2-551 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-552 | M2000/2-552 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-553 | M2000/2-553 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-554 | M2000/2-554 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-555 | M2000/2-555 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-556 | M2000/2-556 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-557 | M2000/2-557 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-558 | M2000/2-558 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-559 | M2000/2-559 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-560 | M2000/2-560 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-561 | M2000/2-561 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-562 | M2000/2-562 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-563 | M2000/2-563 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-564 | M2000/2-564 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-565 | M2000/2-565 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-566 | M2000/2-566 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-567 | M2000/2-567 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-568 | M2000/2-568 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-569 | M2000/2-569 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/2-570 | M2000/2-570 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-571 | M2000/2-571 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-572 | M2000/2-572 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-573 | M2000/2-573 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-574 | M2000/2-574 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-575 | M2000/2-575 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-576 | M2000/2-576 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-577 | M2000/2-577 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-578 | M2000/2-578 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-579 | M2000/2-579 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-580 | M2000/2-580 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-581 | M2000/2-581 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-582 | M2000/2-582 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-583 | M2000/2-583 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-584 | M2000/2-584 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-585 | M2000/2-585 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-586 | M2000/2-586 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-587 | M2000/2-587 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-588 | M2000/2-588 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-589 | M2000/2-589 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-590 | M2000/2-590 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-591 | M2000/2-591 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-592 | M2000/2-592 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-593 | M2000/2-593 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-594 | M2000/2-594 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-595 | M2000/2-595 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-596 | M2000/2-596 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-597 | M2000/2-597 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-598 | M2000/2-598 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-599 | M2000/2-599 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-600 | M2000/2-600 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-601 | M2000/2-601 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-602 | M2000/2-602 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-603 | M2000/2-603 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-604 | M2000/2-604 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-605 | M2000/2-605 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-606 | M2000/2-606 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-607 | M2000/2-607 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-608 | M2000/2-608 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-609 | M2000/2-609 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-610 | M2000/2-610 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-611 | M2000/2-611 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-612 | M2000/2-612 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-613 | M2000/2-613 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-614 | M2000/2-614 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-615 | M2000/2-615 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-616 | M2000/2-616 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-617 | M2000/2-617 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-621 | M2000/2-621 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-622 | M2000/2-622 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-627 | M2000/2-627 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/2-1F | 230-01-09-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-1Z | 230-01-09-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-2F | 230-01-15-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-2Z | 230-01-15-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-3F | 230-01-25-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-3Z | 230-01-25-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-4F | 230-01-37-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-4Z | 230-01-37-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-5F | 230-01-50-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-5Z | 230-01-50-102 | 254, 18 NOV 68; 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/2-6F | 230-01-09-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-6Z | 230-01-09-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-7F | 230-01-15-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-7Z | 230-01-15-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-8F | 230-01-25-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-8Z | 230-01-25-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-9F | 230-01-37-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-9Z | 230-01-37-106 | 224308-454-74 | Cinch Connectors, Inc. |
| M24308/2-10F | 230-01-50-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-10Z | 230-01-50-106 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-23F | 230-01-09-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-23Z | 230-01-09-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-24F | 230-01-15-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-24Z | 230-01-15-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-25F | 230-01-25-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-25Z | 230-01-25-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-26F | 230-01-37-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-26Z | 230-01-37-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-27F | 230-01-50-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-27Z | 230-01-50-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-34F | 230-01-09-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-34Z | 230-01-09-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-35F | 230-01-15-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-35Z | 230-01-15-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-36F | 230-01-25-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-36Z | 230-01-25-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-37F | 230-01-37-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-37Z | 230-01-37-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-38F | 230-01-50-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-38Z | 230-01-50-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-281F | 230-01-09-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-281Z | 230-01-09-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-282F | 230-01-15-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-282Z | 230-01-15-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-283F | 230-01-25-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-283Z | 230-01-25-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-284F | 230-01-37-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-284Z | 230-01-37-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-285F | 230-01-50-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-285Z | 230-01-50-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-292F | 230-01-09-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-292Z | 230-01-09-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-293F | 230-01-15-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-293Z | 230-01-15-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-294F | 230-01-25-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-294Z | 230-01-25-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-295F | 230-01-37-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-295Z | 230-01-37-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-296F | 230-01-50-308 | 24308-454-74 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-296Z | 230-01-50-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-335F | 230-01-25-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-335Z | 230-01-25-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-336F | 230-01-37-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-336Z | 230-01-37-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-342F | 230-01-09-335 | 34308-454-74 | Cinch Connectors, Inc. |
| M24308/2-342Z | 230-01-09-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-343F | 230-01-15-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-343Z | 230-01-15-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-344F | 230-01-25-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-344Z | 230-01-25-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-345F | 230-01-37-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-345Z | 230-01-37-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-346F | 230-01-50-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-346Z | 230-01-50-335 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-353F | 230-01-09-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-353Z | 230-01-09-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-354F | 230-01-15-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-354Z | 230-01-15-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-355F | 230-01-25-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-355Z | 230-01-25-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-356F | 230-01-37-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-356Z | 230-01-37-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-357F | 230-01-50-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-357Z | 230-01-50-343 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-482F | 230-01-09-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-482Z | 230-01-09-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-483F | 230-01-09-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-483Z | 230-01-09-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-484F | 230-01-25-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-484Z | 230-01-25-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-485F | 230-01-37-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-485Z | 230-01-37-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-486F | 230-01-50-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-486Z | 230-01-50-336 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/2-1F | DEG9S1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-2F | DAG15S1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-3F | DBG25S1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-4F | DCG37S1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-5F | DDG50S1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-6F | DEG9S1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-7F | DAG15S1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-8F | DBG25S1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-9F | DCG37S1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-10F | DDG50S1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-23F | DEG9S1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-24F | DAG15S1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-25F | DBG25S1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-26F | DCG37S1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-27F | DDG50S1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-34F | DEG9S1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-35F | DAG15S1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-36F | DBG5S1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-37F | DCG37S1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-38F | DDG50S1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-281F | DEG9S1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-282F | DAG15S1N0-P6 | 24308-169-92 | Cristek Interconnects, Inc. |
| M24308/2-283F | DBG25S1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-284F | DCG37S1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-285F | DDG50S1N0 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-292F | DEG9S1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-293F | DAG15S1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-294F | DBG25S1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-295F | DCG37S1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-296F | DDG50S1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-335F | DBG25S1RF-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-336F | DCG37S1RF-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-341F | DAG15S1RF-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-342F | DEG9S1D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-343F | DAG15S1D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-344F | DBG25S1D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-345F | DCG37S1D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-346F | DDG50S1D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-353F | DEG9S1D-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-354F | DAG15S1D-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-355F | DBG25S1D-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-356F | DCG37S1D-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-357F | DDG50S1D-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-482F | DEG9S1DN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-483F | DAG15S1DN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-484F | DBG25S1DN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-485F | DCG37S1DN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-486F | DDG50S1DN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/2-1F | M24308/2-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-1Z | M24308/2-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-2F | M24308/2-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-2Z | M24308/2-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-3F | M24308/2-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-3Z | M24308/2-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-4F | M24308/2-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-4Z | M24308/2-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-5F | M24308/2-5F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-5Z | M24308/2-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-6F | M24308/2-6F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-6Z | M24308/2-6Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-7F | M24308/2-7F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-7Z | M24308/2-7Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-8F | M24308/2-8F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-8Z | M24308/2-8Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-9F | M24308/2-9F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-9Z | M24308/2-9Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-10F | M24308/2-10F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-10Z | M24308/2-10Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-11F | M24308/2-11F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-11Z | M24308/2-11Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-12F | M24308/2-12F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-12Z | M24308/2-12Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-13F | M24308/2-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-13Z | M24308/2-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-14F | M24308/2-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-14Z | M24308/2-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-15F | M24308/2-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-15Z | M24308/2-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-17F | M24308/2-17F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-17Z | M24308/2-17Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-18F | M24308/2-18F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-18Z | M24308/2-18Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-19F | M24308/2-19F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-19Z | M24308/2-19Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-20F | M24308/2-20F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-20Z | M24308/2-20Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-21F | M24308/2-21F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-21Z | M24308/2-21Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-23F | M24308/2-23F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-23Z | M24308/2-23Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-24F | M24308/2-24F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-24Z | M24308/2-24Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-25F | M24308/2-25F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-25Z | M24308/2-25Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-26F | M24308/2-26F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-26Z | M24308/2-26Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-27F | M24308/2-27F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-27Z | M24308/2-27Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-28F | M24308/2-28F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-28Z | M24308/2-28Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-29F | M24308/2-29F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-29Z | M24308/2-29Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-30F | M24308/2-30F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-30Z | M24308/2-30Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-31F | M24308/2-31F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-31Z | M24308/2-31Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-32F | M24308/2-32F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-32Z | M24308/2-32Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-34F | M24308/2-34F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-34Z | M24308/2-34Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-35F | M24308/2-35F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-35Z | M24308/2-35Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-36F | M24308/2-36F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-36Z | M24308/2-36Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-37F | M24308/2-37F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-37Z | M24308/2-37Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-38F | M24308/2-38F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-38Z | M24308/2-38Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-39F | M24308/2-39F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-39Z | M24308/2-39Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-40F | M24308/2-40F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-40Z | M24308/2-40Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-41F | M24308/2-41F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-41Z | M24308/2-41Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-42F | M24308/2-42F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-42Z | M24308/2-42Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-43F | M24308/2-43F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-43Z | M24308/2-43Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-281F | M24308/2-281F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-281Z | M24308/2-281Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-282F | M24308/2-282F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-282Z | M24308/2-282Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-283F | M24308/2-283F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-283Z | M24308/2-283Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-284F | M24308/2-284F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-284Z | M24308/2-284Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-285F | M24308/2-285F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-285Z | M24308/2-285Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-286F | M24308/2-286F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-286Z | M24308/2-286Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-287F | M24308/2-287F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-287Z | M24308/2-287Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-288F | M24308/2-288F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-288Z | M24308/2-288Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-289F | M24308/2-289F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-289Z | M24308/2-289Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-290F | M24308/2-290F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-290Z | M24308/2-290Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-292F | M24308/2-292F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-292Z | M24308/2-292Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-293F | M24308/2-293F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-293Z | M24308/2-293Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-294F | M24308/2-294F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-294Z | M24308/2-294Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-295F | M24308/2-295F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-295Z | M24308/2-295Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-296F | M24308/2-296F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-296Z | M24308/2-296Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-297F | M24308/2-297F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-297Z | M24308/2-297Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-298F | M24308/2-298F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-298Z | M24308/2-298Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-299F | M24308/2-299F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-299Z | M24308/2-299Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-300F | M24308/2-300F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-300Z | M24308/2-300Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-301F | M24308/2-301F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-301Z | M24308/2-301Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-335F | M24308/2-335F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-335Z | M24308/2-335Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-336F | M24308/2-336F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-336Z | M24308/2-336Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-342F | M24308/2-342F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-342Z | M24308/2-342Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-343F | M24308/2-343F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-343Z | M24308/2-343Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-344F | M24308/2-344F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-344Z | M24308/2-344Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-345F | M24308/2-345F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-345Z | M24308/2-345Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-346F | M24308/2-346F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-346Z | M24308/2-346Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-347F | M24308/2-347F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-347Z | M24308/2-347Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-348F | M24308/2-348F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-348Z | M24308/2-348Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-349F | M24308/2-349F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-349Z | M24308/2-349Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-350F | M24308/2-350F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-350Z | M24308/2-350Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-351F | M24308/2-351F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-351Z | M24308/2-351Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-353F | M24308/2-353F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-353Z | M24308/2-353Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-354F | M24308/2-354F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-354Z | M24308/2-354Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-355F | M24308/2-355F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-355Z | M24308/2-355Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-356F | M24308/2-356F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-356Z | M24308/2-356Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-357F | M24308/2-357F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-357Z | M24308/2-357Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-358F | M24308/2-358F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-358Z | M24308/2-358Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-359F | M24308/2-359F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-359Z | M24308/2-359Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-360F | M24308/2-360F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-360Z | M24308/2-360Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-361F | M24308/2-361F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-361Z | M24308/2-361Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-362F | M24308/2-362F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-362Z | M24308/2-362Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-482F | M24308/2-482F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-482Z | M24308/2-482Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-483F | M24308/2-483F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-483Z | M24308/2-483Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-484F | M24308/2-484F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-484Z | M24308/2-484Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-485F | M24308/2-485F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-485Z | M24308/2-485Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-486F | M24308/2-486F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-486Z | M24308/2-486Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-487F | M24308/2-487F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-487Z | M24308/2-487Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-488F | M24308/2-488F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-488Z | M24308/2-488Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-489F | M24308/2-489F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-489Z | M24308/2-489Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-490F | M24308/2-490F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-490Z | M24308/2-490Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-491F | M24308/2-491F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-491Z | M24308/2-491Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-509F | M24308/2-509F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-509Z | M24308/2-509Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-510F | M24308/2-510F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-510Z | M24308/2-510Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-515F | M24308/2-515F | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-515Z | M24308/2-515Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/2-1F | RD9S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-1Z | RD9S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-2F | RD15S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-2Z | RD15S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-3F | RD25S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-3Z | RD25S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-4F | RD37F1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-4Z | RD37F10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-5F | RD50S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-5Z | RD50S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-6F | RD9S1000C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-6Z | RD9S10000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-7F | RD15S1000C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-7Z | RD15S10000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-8F | RD25S1000C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-8Z | RD25S10000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-9F | RD37S1000C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-9Z | RD37S10000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-10F | RD50S1000C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-10Z | RD50S10000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-11F | DD15S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-11Z | DD15S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-12F | DD26S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-12Z | DD26S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-13F | DD44S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-13Z | DD44S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-14F | DD62S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-14Z | DD62S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-15F | DD78S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-15Z | DD78S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-16F | DD104S1000C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-16Z | DD104S10000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-17F | DD15S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-17Z | DD15S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-18F | DD26S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-18Z | DD26S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-19F | DD44S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-19Z | DD44S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-20F | DD62S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-20Z | DD62S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-21F | DD78S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-21Z | DD78S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-22F | DD104S1000C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-22Z | DD104S10000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-281F | RD9S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-281Z | RD9S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-282F | RD15S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-282Z | RD15S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-283F | RD25S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-283Z | RD25S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-284F | RD37S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-284Z | RD37S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-285F | RD50S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-285Z | RD50S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-286F | DD15S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-286Z | DD15S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-287F | DD26S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-287Z | DD26S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-288F | DD44S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-288Z | DD44S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-289F | DD62S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-289Z | DD62S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-290F | DD78S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-290Z | DD78S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-291F | DD104S0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-291Z | DD104S00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-342F | RD9S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-342Z | RD9S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-343F | RD15S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-343Z | RD15S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-344F | RD25S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-344Z | RD25S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-345F | RD37S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-345Z | RD37S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-346F | RD50S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-346Z | RD50S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-347F | DD15S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-347Z | DD15S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-348F | DD26S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-348Z | DD26S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-349F | DD44S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-349Z | DD44S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-350F | DD62S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-350Z | DD62S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-351F | DD78S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-351Z | DD78S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-352F | DD104S1F00C-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-352Z | DD104S1F000-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-353F | RD9S1F00C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-353Z | RD9S1F000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-354F | RD15S1F00C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-354Z | RD15S1F000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-355F | RD25S1F00C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-355Z | RD25S1F000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-356F | RD37S1F00C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-356Z | RD37S1F000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-357F | RD50S1F00C-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-357Z | RD50S1F000-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-358F | DD15S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-358Z | DD15S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-359F | DD26S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-359Z | DD26S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-360F | DD44S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-360Z | DD44S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-361F | DD62S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-361Z | DD62S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-362F | DD78S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-362Z | DD78S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-363F | DD104S1F00C-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-363Z | DD104S1F000-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-482F | RD9S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-482Z | RD9S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-483F | RD15S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-483Z | RD15S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-484F | RD25S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-484Z | RD25S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-485F | RD37S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-485Z | RD37S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-486F | RD50S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-486Z | RD50S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-487F | DD15S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-487Z | DD15S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-488F | DD26S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-488Z | DD26S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-489F | DD44S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-489Z | DD44S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-490F | DD62S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-490Z | DD62S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-491F | DD78S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-491Z | DD78S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-492F | DD104S0S00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-492Z | DD104S0S000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-516 | RD9S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-517 | RD15S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-518 | RD25S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-519 | RD37S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-520 | RD50S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-521 | RD9S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-522 | RD15S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-523 | RD25S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-524 | RD37S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-525 | RD50S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-526 | DD15S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-527 | DD26S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-528 | DD44S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-529 | DD62S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-530 | DD78S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-531 | DD104S10000-MIL-799.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-532 | DD15S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-533 | DD26S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-534 | DD44S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-535 | DD62S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-536 | DD78S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-537 | DD104S10000-MIL-799.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-560 | RD9S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-561 | RD15S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-562 | RD25S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-563 | RD37S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-564 | RD50S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-565 | DD15S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-566 | DD26S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-567 | DD44S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-568 | DD62S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-569 | DD78S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-570 | DD104S00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-585 | RD9S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-586 | RD15S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-587 | RD25S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-588 | RD37S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-589 | RD50S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-590 | DD15S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-591 | DD26S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-592 | DD44S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-593 | DD62S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-594 | DD78S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-595 | DD104S1F000-MIL-799.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-596 | RD9S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-597 | RD15S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-598 | RD25S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-599 | RD37S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-600 | RD50S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-601 | DD15S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-602 | DD26S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-603 | DD44S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-604 | DD62S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-605 | DD78S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-606 | DD104S1F000-MIL-799.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-607 | RD9S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-608 | RD15S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-609 | RD25S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-610 | RD37S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-611 | RD50S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-612 | DD15S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-613 | DD26S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-614 | DD44S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-615 | DD62S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-616 | DD78S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-617 | DD104S0S000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/2-1F | SEMA09S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-2F | SAMA15S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-3F | SBMA25S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-4F | SCMA37S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-5F | SDMA50S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-6F | SEMAT09S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-7F | SAMAT15S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-8F | SBMAT25S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-9F | SCMAT37S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-10F | SDMAT50S | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-23F | SEMAF09S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-24F | SAMAF15S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-25F | SBMAF25S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-26F | SCMAF37S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-27F | SDMAF50S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-34F | SEMAFT09S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-35F | SAMAFT15S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-36F | SBMAFT25S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-37F | SCMAFT37S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-38F | SDMAFT50S | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-281F | SEMA09SL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-282F | SAMA15SL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-283F | SBMA25SL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-284F | SCMA37SL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/2-285F | SDMA50SL | 24308-2933-10 | Souriau |
| M24308/2-292F | SEMAF09S-L | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-293F | SAMAF15S-L | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-294F | SBMAF25S-L | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-295F | SCMAF37S-L | 24308-174-88; 24308-308-79 | Souriau |
| M24308/2-296F | SDMAF50S-L | 24308-174-88; 24308-309-79 | Souriau |
| M24308/2-342F | SEMAF09S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-343F | SAMAF15S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-344F | SBMAF25S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-345F | SCMAF37S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-346F | SDMAF50S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-353F | SEMAFT09S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-354F | SAMAFT15S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-354Z | SAMAFT15S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-355F | SBMAFT25S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-356F | SCMAFT37S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-357F | SDMAFT50S | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-482F | SEMAF09SL | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-483F | SAMAF15SL | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-484F | SBMAF25SL | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-485F | SCMAF37SL | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-486F | SDMAF50SL | 24308-1042-82; 24308-174-88 | Souriau |
| M24308/2-1F | 205555-2 | 24308-703-71 | Tyco Electronics |
| M24308/2-1Z | 1757820-6 | 24308-1320-05 | Tyco Electronics |
| M24308/2-2F | 205557-2 | 24308-703-71 | Tyco Electronics |
| M24308/2-2Z | 1757820-7 | 24308-1320-05 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-3F | 205559-2 | 24308-703-71 | Tyco Electronics |
| M24308/2-3Z | 1757820-8 | 24308-1320-05 | Tyco Electronics |
| M24308/2-4F | 205561-2 | 24308-703-71 | Tyco Electronics |
| M24308/2-4Z | 1757820-9 | 24308-1320-05 | Tyco Electronics |
| M24308/2-5F | 205563-2 | 24308-703-71 | Tyco Electronics |
| M24308/2-5Z | 1-1757820-0 | 24308-1320-05 | Tyco Electronics |
| M24308/2-6F | 205555-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-7F | 205557-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-8F | 205559-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-9F | 205561-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-10F | 205563-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-11F | 204512-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-11Z | 1757824-7 | 24308-1320-05 | Tyco Electronics |
| M24308/2-12F | 204514-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-12Z | 1757824-8 | 24308-1320-05 | Tyco Electronics |
| M24308/2-13F | 204516-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-13Z | 1757824-9 | 24308-1320-05 | Tyco Electronics |
| M24308/2-14F | 204518-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-14Z | 1-1757824-0 | 24308-1320-05 | Tyco Electronics |
| M24308/2-15F | 204520-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-15Z | 1-1757824-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-16F | 204522-2 | 24308-1254-71 | Tyco Electronics |
| M24308/2-16Z | 1-1757824-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-17F | 204512-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-18F | 204514-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-19F | 204516-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-20F | 204518-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-21F | 204520-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-22F | 204522-3 | 24308-215-77 | Tyco Electronics |
| M24308/2-23F | 205483-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-23Z | 1757822-6 | 24308-1320-05 | Tyco Electronics |
| M24308/2-24F | 205433-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-24Z | 1757822-7 | 24308-1320-05 | Tyco Electronics |
| M24308/2-25F | 205484-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-25Z | 1757822-8 | 24308-1320-05 | Tyco Electronics |
| M24308/2-26F | 205485-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-26Z | 1757822-9 | 24308-1320-05 | Tyco Electronics |
| M24308/2-27F | 205432-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-27Z | 1-1757822-0 | 24308-1320-05 | Tyco Electronics |
| M24308/2-28F | 204536-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-28Z | 1757826-7 | 24308-1320-05 | Tyco Electronics |
| M24308/2-29F | 204538-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-29Z | 1757826-8 | 24308-1320-05 | Tyco Electronics |
| M24308/2-30F | 204540-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-30Z | 1757826-9 | 24308-1320-05 | Tyco Electronics |
| M24308/2-31F | 204542-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-31Z | 1-1757826-0 | 24308-1320-05 | Tyco Electronics |
| M24308/2-32F | 204544-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-32Z | 1-1757826-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-33F | 204546-2 | 24308-437-73 | Tyco Electronics |
| M24308/2-33Z | 1-1757826-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-34F | 593015-1 | 24308-1232-71 | Tyco Electronics |
| M24308/2-35F | 593015-2 | 24308-1232-71 | Tyco Electronics |
| M24308/2-36F | 593015-3 | 24308-1232-71 | Tyco Electronics |
| M24308/2-37F | 593015-4 | 24308-1232-71 | Tyco Electronics |
| M24308/2-38F | 593015-5 | 24308-1232-71 | Tyco Electronics |
| M24308/2-39F | 593016-1 | 24308-641-73 | Tyco Electronics |
| M24308/2-42Z | 204542-2 | 1140, 23 MAY 69 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-44Z | 204546-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/2-281F | 205161-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-281Z | 1757820-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-291Z | 1757824-6 | 24308-1320-05 | Tyco Electronics |
| M24308/2-282F | 205163-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-282Z | 1757820-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-292Z | 1757822-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-283F | 205165-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-283Z | 1757820-3 | 24308-1320-05 | Tyco Electronics |
| M24308/2-293Z | 1757822-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-284F | 205167-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-284Z | 1757820-4 | 24308-1320-05 | Tyco Electronics |
| M24308/2-294Z | 1757822-3 | 24308-1320-05 | Tyco Electronics |
| M24308/2-285F | 205169-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-285Z | 1757820-5 | 24308-1320-05 | Tyco Electronics |
| M24308/2-295Z | 1757822-4 | 24308-1320-05 | Tyco Electronics |
| M24308/2-286F | 204500-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-286Z | 1757824-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-296Z | 1757822-5 | 24308-1320-05 | Tyco Electronics |
| M24308/2-287F | 204502-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-287Z | 1757824-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-297Z | 1757826-1 | 24308-1320-05 | Tyco Electronics |
| M24308/2-288F | 204504-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-288Z | 1757824-3 | 24308-1320-05 | Tyco Electronics |
| M24308/2-298Z | 1757826-2 | 24308-1320-05 | Tyco Electronics |
| M24308/2-289F | 204506-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-289Z | 1757824-4 | 24308-1320-05 | Tyco Electronics |
| M24308/2-299Z | 1757826-3 | 24308-1320-05 | Tyco Electronics |
| M24308/2-290F | 204508-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-290Z | 1757824-5 | 24308-1320-05 | Tyco Electronics |
| M24308/2-291F | 204510-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-292F | 205416-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-293F | 205417-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-294F | 205418-1 | 24308-1232-71 | Tyco Electronics |
| M24308/2-295F | 205419-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-296F | 205420-1 | 24308-215-77 | Tyco Electronics |
| M24308/2-297F | 204524-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-298F | 204526-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-299F | 204528-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-300F | 204530-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-300Z | 1757826-4 | 24308-1320-05 | Tyco Electronics |
| M24308/2-301F | 204532-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-301Z | 1757826-5 | 24308-1320-05 | Tyco Electronics |
| M24308/2-302F | 204534-1 | 24308-217-77 | Tyco Electronics |
| M24308/2-302Z | 1757826-6 | 24308-1320-05 | Tyco Electronics |
| M24308/2-335F | 593020-3 | 1140, DTD 24 MAY 69 | Tyco Electronics |
| M24308/2-336F | 593020-4 | 1140, DTD 24 MAY 69 | Tyco Electronics |
| M24308/2-341F | 593020-2 | 1140, DTD 24 MAY 69 | Tyco Electronics |
| M24308/2-342F | 211525-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-343F | 211526-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-344F | 211527-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-345F | 211528-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-346F | 211529-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-347F | 211536-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-348F | 211537-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-349F | 211538-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-350F | 211539-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-351F | 211540-2 | 24308-1224-84 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/2-352F | 211541-2 | 24308-1224-84 | Tyco Electronics |
| M24308/2-353F | 593023-1 | 24308-36-82 | Tyco Electronics |
| M24308/2-354F | 593023-2 | 24308-36-82 | Tyco Electronics |
| M24308/2-355F | 593023-3 | 24308-36-82 | Tyco Electronics |
| M24308/2-356F | 593023-4 | 24308-36-82 | Tyco Electronics |
| M24308/2-357F | 593023-5 | 24308-36-82 | Tyco Electronics |
| M24308/2-358F | 593024-1 | 24308-36-82 | Tyco Electronics |
| M24308/2-482F | 211525-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-483F | 211526-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-484F | 211527-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-485F | 211528-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-486F | 211529-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-487F | 211536-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-488F | 211537-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-489F | 211538-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-490F | 211539-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-491F | 211540-1 | 24308-1224-84 | Tyco Electronics |
| M24308/2-492F | 211541-1 | 24308-1224-84 | Tyco Electronics |
| M24308/3-1F | GPM-C01S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-1Z | GPM-Z01S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-2F | GPM-C01S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-2Z | GPM-Z01S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-3F | GPM-C01S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-3Z | GPM-Z01S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-4F | GPM-C01S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-4Z | GPM-Z01S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-5F | GPM-C01S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-5Z | GPM-Z01S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-12F | GPM-C01F-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-12Z | GPM-Z01F-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-13F | GPM-C01F-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-13Z | GPM-Z01F-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-14F | GPM-C01F-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-14Z | GPM-Z01F-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-15F | GPM-C01F-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-15Z | GPM-Z01F-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-16F | GPM-C01F-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-16Z | GPM-Z01F-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-17F | GPM-C01D-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-17Z | GPM-Z01D-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-18F | GPM-C01D-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-18Z | GPM-Z01D-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-19F | GPM-C01D-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-19Z | GPM-Z01D-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-20F | GPM-C01D-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-20Z | GPM-Z01D-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-21F | GPM-C01D-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-21Z | GPM-Z01D-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/3-1F | M2000/3-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-1K | M2000/3-1K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-1Z | M2000/3-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-2F | M2000/3-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-12F | M2000/3-12F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-2K | M2000/3-2K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-2Z | M2000/3-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-3F | M2000/3-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-3K | M2000/3-3K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/3-3Z | M2000/3-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-4F | M2000/3-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-4K | M2000/3-4K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-4Z | M2000/3-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-5F | M2000/3-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-5K | M2000/3-5K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-5Z | M2000/3-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-12K | M2000/3-12K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-12Z | M2000/3-12Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-13F | M2000/3-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-13K | M2000/3-13K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-13Z | M2000/3-13Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-14F | M2000/3-14F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-14K | M2000/3-14K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-14Z | M2000/3-14Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-15F | M2000/3-15F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-15K | M2000/3-15K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-15Z | M2000/3-15Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-16F | M2000/3-16F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-16K | M2000/3-16K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-16Z | M2000/3-16Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-17F | M2000/3-17F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-17K | M2000/3-17K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-17Z | M2000/3-17Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-18F | M2000/3-18F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-18K | M2000/3-18K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-18Z | M2000/3-18Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-19F | M2000/3-19F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-19K | M2000/3-19K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-19Z | M2000/3-19Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-20F | M2000/3-20F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-20K | M2000/3-20K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-20Z | M2000/3-20Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-21F | M2000/3-21F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-21K | M2000/3-21K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-21Z | M2000/3-21Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-23 | M2000/3-23 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-24 | M2000/3-24 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-25 | M2000/3-25 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-26 | M2000/3-26 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-27 | M2000/3-27 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-34 | M2000/3-34 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-35 | M2000/3-35 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-36 | M2000/3-36 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-37 | M2000/3-37 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-38 | M2000/3-38 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-39 | M2000/3-39 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-40 | M2000/3-40 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-41 | M2000/3-41 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-42 | M2000/3-42 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-43 | M2000/3-43 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/3-1F | 231-09-09-129 | 24308-804-84 | Cinch Connectors, Inc. |
| M24308/3-2F | 231-15-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-2Z | 231-15-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-3F | 231-25-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-3Z | 231-25-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-4F | 231-37-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-4Z | 231-37-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/3-5F | 231-50-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-5Z | 231-50-09-129 | 261, 30 JUN 69 | Cinch Connectors, Inc. |
| M24308/3-12F | 231-09-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-12Z | 231-09-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-13F | 231-15-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-13Z | 231-15-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-14F | 231-25-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-14Z | 231-25-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-15F | 231-37-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-15Z | 231-37-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-16F | 231-50-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-16Z | 231-50-09-322 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-17F | 231-09-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-17Z | 231-09-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-18F | 231-15-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-18Z | 231-15-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-19F | 231-25-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-19Z | 231-25-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-20F | 231-37-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-20Z | 231-37-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-21F | 231-50-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-21Z | 231-50-09-350 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/3-1F | DEG9P2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-2F | DAG15P2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-3F | DBG25P2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-4F | DCG37P2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-5F | DDG50P2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-12F | DEG9P2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-13F | DAG15P2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-14F | DBG25PF-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-15F | DCG37P2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-16F | DDG50P2F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/3-1F | M24308/3-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-1Z | M24308/3-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-2F | M24308/3-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-2Z | M24308/3-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-3F | M24308/3-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-3Z | M24308/3-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-4F | M24308/3-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-4Z | M24308/3-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-5F | M24308/3-5F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-5Z | M24308/3-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-12F | M24308/3-12F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-12Z | M24308/3-12Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-13F | M24308/3-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-13Z | M24308/3-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-14F | M24308/3-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-14Z | M24308/3-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-15F | M24308/3-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-15Z | M24308/3-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-16F | M24308/3-16F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-16Z | M24308/3-16Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-17F | M24308/3-17F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-17Z | M24308/3-17Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-18F | M24308/3-18F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-18Z | M24308/3-18Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-19F | M24308/3-19F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/3-19Z | M24308/3-19Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-20F | M24308/3-20F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-20Z | M24308/3-20Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-21F | M24308/3-21F | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-21Z | M24308/3-21Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/3-1F | HDC9M2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-1Z | HDC9M20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-2F | HDC15M2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-2Z | HDC15M20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-3F | HDC25M2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-3Z | HDC25M20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-4F | HDC37M2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-4Z | HDC37M20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-5F | HDC50M2000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-5Z | HDC50M20000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-12F | HDC9M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-12Z | HDC9M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-13F | HDC15M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-13Z | HDC15M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-14F | HDC25M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-14Z | HDC25M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-15F | HDC37M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-15Z | HDC37M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-16F | HDC50M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-16Z | HDC50M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-17F | HDC9M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-17Z | HDC9M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-18F | HDC15M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-18Z | HDC15M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-19F | HDC25M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-19Z | HDC25M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-20F | HDC37M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-20Z | HDC37M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-21F | HDC50M2F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-21Z | HDC50M2F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-23 | HDC9M20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-24 | HDC15M20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-25 | HDC25M20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-26 | HDC37M20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-27 | HDC50M20000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-39 | HDC9M2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-40 | HDC15M2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-41 | HDC25M2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-42 | HDC37M2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/3-43 | HDC50M2F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-1F | GPM-C05S-00009P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-1Z | GPM-Z05S-00009P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-2F | GPM-C05S-00015P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-2Z | GPM-Z05S-00015P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-3F | GPM-C05S-00025P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-3Z | GPM-Z05S-00025P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-4F | GPM-C05S-00037P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-4Z | GPM-Z05S-00037P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-5F | GPM-C05S-00050P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-5Z | GPM-Z05S-00050P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-6F | GPM-C05S-00009P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-6Z | GPM-Z05S-00009P-03 | 24308-284-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-7F | GPM-C05S-00015P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-7Z | GPM-Z05S-00015P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-8F | GPM-C05S-00025P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-8Z | GPM-Z05S-00025P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-9F | GPM-C05S-00037P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-9Z | GPM-Z05S-00037P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-10F | GPM-C05S-00050P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-10Z | GPM-Z05S-00050P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-11F | GLM-C04S-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-11Z | GLM-Z04S-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-12F | GLM-C04S-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-12Z | GLM-Z04S-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-13F | GLM-C04S-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-13Z | GLM-Z04S-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-14F | GLM-C04S-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-14Z | GLM-Z04S-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-15F | GLM-C04S-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-15Z | GLM-Z04S-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-17F | GLM-C04S-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-17Z | GLM-Z04S-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-18F | GLM-C04S-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-18Z | GLM-Z04S-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-19F | GLM-C04S-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-19Z | GLM-Z04S-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-20F | GLM-C04S-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-20Z | GLM-Z04S-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-259F | GPM-C05S-00009P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-259F | GPM-C05S-00009P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-259Z | GPM-Z05S-00009P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-259Z | GPM-Z05S-00009P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-260F | GPM-C05S-00015P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-260F | GPM-C05S-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-260Z | GPM-Z05S-00015P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-260Z | GPM-Z05S-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-261F | GPM-C05S-00025P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-261F | GPM-C05S-00025P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-261Z | GPM-Z05S-00025P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-261Z | GPM-Z05S-00025P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-262F | GPM-C05S-00037P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-262F | GPM-C05S-00037P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-262Z | GPM-Z05S-00037P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-262Z | GPM-Z05S-00037P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-263F | GPM-C05S-00050P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-263F | GPM-C05S-00050P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-263Z | GPM-Z05S-00050P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-263Z | GPM-Z05S-00050P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-264F | GLM-C04S-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-264Z | GLM-Z04S-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-265F | GLM-C04S-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-265Z | GLM-Z04S-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-266F | GLM-C04S-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-266Z | GLM-Z04S-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-267F | GLM-C04S-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-267Z | GLM-Z04S-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-268F | GLM-C04S-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-268Z | GLM-Z04S-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-302F | GPM-C05F-00009P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-302Z | GPM-Z05F-00009P-02 | 24308-284-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-303F | GPM-C05F-00015P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-303Z | GPM-Z05F-00015P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-304F | GPM-C05F-00025P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-304Z | GPM-Z05F-00025P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-305F | GPM-C05F-00037P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-305Z | GPM-Z05F-00037P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-306F | GPM-C05F-00050P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-306Z | GPM-Z05F-00050P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-307F | GLM-C04F-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-307Z | GLM-Z04F-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-308F | GLM-C04F-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-308Z | GLM-Z04F-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-309F | GLM-C04F-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-309Z | GLM-Z04F-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-310F | GLM-C04F-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-310Z | GLM-Z04F-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-311F | GLM-C04F-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-311Z | GLM-Z04F-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-313F | GPM-C05F-00009P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-313Z | GPM-Z05F-00009P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-314F | GPM-C05F-00015P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-314Z | GPM-Z05F-00015P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-315F | GPM-C05F-00025P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-315Z | GPM-Z05F-00025P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-316F | GPM-C05F-00037P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-316Z | GPM-Z05F-00037P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-317F | GPM-C05F-00050P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-317Z | GPM-Z05F-00050P-03 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-318F | GLM-C04F-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-318Z | GLM-Z04F-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-319F | GLM-C04F-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-319Z | GLM-Z04F-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-320F | GLM-C04F-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-320Z | GLM-Z04F-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-321F | GLM-C04F-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-321Z | GLM-Z04F-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-322F | GLM-C04F-00078P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-322Z | GLM-Z04F-00078P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-324F | GPM-C05F-00009P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-324Z | GPM-Z05F-00009P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-325F | GPM-C05F-00015P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-325Z | GPM-Z05F-00015P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-326F | GPM-C05F-00025P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-326Z | GPM-Z05F-00025P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-327F | GPM-C05F-00037P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-327Z | GPM-Z05F-00037P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-328F | GPM-C05F-00050P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-328Z | GPM-Z05F-00050P-01 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-329F | GLM-C04F-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-329Z | GLM-Z04F-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-330F | GLM-C04F-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-330Z | GLM-Z04F-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-331F | GLM-C04F-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-331Z | GLM-Z04F-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-332F | GLM-C04F-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-332Z | GLM-Z04F-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-333F | GLM-C04F-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-333Z | GLM-Z04F-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-435F | GPM-C05D-00009P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-436F | GPM-C05D-00015P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-437F | GPM-C05D-00025P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-438F | GPM-C05D-00037P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-439F | GPM-C05D-00050P-02 | 24308-284-89 | ADI Electronics Incorporated |
| M24308/4-440F | GLM-C04D-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-440Z | GLM-Z04D-00015P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-441F | GLM-C04D-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-441Z | GLM-Z04D-00026P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-442F | GLM-C04D-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-442Z | GLM-Z04D-00044P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-443F | GLM-C04D-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-443Z | GLM-Z04D-00062P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-444F | GLM-C04D-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-444Z | GLM-Z04D-00078P-02 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-446F | GPM-C05D-00009P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-446Z | GPM-Z05D-00009P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-447F | GPM-C05D-00015P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-447Z | GPM-Z05D-00015P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-448F | GPM-C05D-00025P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-448Z | GPM-Z05D-00025P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-449F | GPM-C05D-00037P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-449Z | GPM-Z05D-00037P-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-450F | GPM-C05D-00050p-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-450Z | GPM-Z05D-00050p-03 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-451F | GLM-C04D-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-451Z | GLM-Z04D-00015P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-452F | GLM-C04D-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-452Z | GLM-Z04D-00026P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-453F | GLM-C04D-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-453Z | GLM-Z04D-00044P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-454F | GLM-C04D-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-454Z | GLM-Z04D-00062P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-455F | GLM-C04D-00078P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-455Z | GLM-Z04D-00078P-03 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-457F | GPM-C05D-00009P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-457Z | GPM-Z05D-00009P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-458F | GPM-C05D-00015P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-458Z | GPM-Z05D-00015P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-459F | GPM-C05D-00025P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-459Z | GPM-Z05D-00025P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-460F | GPM-C05D-00037P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-460Z | GPM-Z05D-00037P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-461F | GPM-C05D-00050P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-461Z | GPM-Z05D-00050P-01 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/4-462F | GLM-C04D-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-462Z | GLM-Z04D-00015P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-463F | GLM-C04D-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-463Z | GLM-Z04D-00026P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-464F | GLM-C04D-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-464Z | GLM-Z04D-00044P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-465F | GLM-C04D-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-465Z | GLM-Z04D-00062P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-466F | GLM-C04D-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-466Z | GLM-Z04D-00078P-01 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/4-1F | M2000/4-1F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-1K | M2000/4-1K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-1Z | M2000/4-1Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-2F | M2000/4-2F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-2K | M2000/4-2K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-2Z | M2000/4-2Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-3F | M2000/4-3F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-3K | M2000/4-3K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-3Z | M2000/4-3Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-4F | M2000/4-4F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-4K | M2000/4-4K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-4Z | M2000/4-4Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-5F | M2000/4-5F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-5K | M2000/4-5K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-5Z | M2000/4-5Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-6F | M2000/4-6F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-6K | M2000/4-6K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-6Z | M2000/4-6Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-7F | M2000/4-7F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-7K | M2000/4-7K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-7Z | M2000/4-7Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-8F | M2000/4-8F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-8K | M2000/4-8K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-8Z | M2000/4-8Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-9F | M2000/4-9F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-9K | M2000/4-9K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-9Z | M2000/4-9Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-10F | M2000/4-10F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-10K | M2000/4-10K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-10Z | M2000/4-10Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-11F | M2000/4-11F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-11K | M2000/4-11K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-11Z | M2000/4-11Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-12F | M2000/4-12F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-12K | M2000/4-12K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-12Z | M2000/4-12Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-13F | M2000/4-13F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-13K | M2000/4-13K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-13Z | M2000/4-13Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-14F | M2000/4-14F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-14K | M2000/4-14K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-14Z | M2000/4-14Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-15F | M2000/4-15F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-15K | M2000/4-15K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-15Z | M2000/4-15Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-16F | M2000/4-16F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-16K | M2000/4-16K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-16Z | M2000/4-16Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-17F | M2000/4-17F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-17K | M2000/4-17K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-17Z | M2000/4-17Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-18F | M2000/4-18F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-18K | M2000/4-18K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-18Z | M2000/4-18Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-19F | M2000/4-19F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-19K | M2000/4-19K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-19Z | M2000/4-19Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-20F | M2000/4-20F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-20K | M2000/4-20K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-20Z | M2000/4-20Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-21F | M2000/4-21F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-21K | M2000/4-21K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-21Z | M2000/4-21Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-22F | M2000/4-22F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-22K | M2000/4-22K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-22Z | M2000/4-22Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-259F | M2000/4-259F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-259K | M2000/4-259K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-259Z | M2000/4-259Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-260F | M2000/4-260F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-260K | M2000/4-260K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-260Z | M2000/4-260Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-261F | M2000/4-261F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-261K | M2000/4-261K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-261Z | M2000/4-261Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-262F | M2000/4-262F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-262K | M2000/4-262K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-262Z | M2000/4-262Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-263F | M2000/4-263F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-263K | M2000/4-263K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-263Z | M2000/4-263Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-264F | M2000/4-264F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-264K | M2000/4-264K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-264Z | M2000/4-264Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-265F | M2000/4-265F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-265K | M2000/4-265K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-265Z | M2000/4-265Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-266F | M2000/4-266F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-266K | M2000/4-266K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-266Z | M2000/4-266Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-267F | M2000/4-267F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-267K | M2000/4-267K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-267Z | M2000/4-267Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-268F | M2000/4-268F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-268K | M2000/4-268K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-268Z | M2000/4-268Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/4-269F | M2000/4-269F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-269K | M2000/4-269K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-269Z | M2000/4-269Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-302F | M2000/4-302F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-302K | M2000/4-302K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-302Z | M2000/4-302Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-303F | M2000/4-303F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-303K | M2000/4-303K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-303Z | M2000/4-303Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-304F | M2000/4-304F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-304K | M2000/4-304K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-304Z | M2000/4-304Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-305F | M2000/4-305F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-305K | M2000/4-305K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-305Z | M2000/4-305Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-306F | M2000/4-306F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-306K | M2000/4-306K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-306Z | M2000/4-306Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-307F | M2000/4-307F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-307K | M2000/4-307K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-307Z | M2000/4-307Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-308F | M2000/4-308F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-308K | M2000/4-308K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-328F | M2000/4-328F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-328K | M2000/4-328K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-328Z | M2000/4-328Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-329F | M2000/4-329F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-329K | M2000/4-329K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-329Z | M2000/4-329Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-330F | M2000/4-330F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-330K | M2000/4-330K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-330Z | M2000/4-330Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-331F | M2000/4-331F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-331K | M2000/4-331K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-331Z | M2000/4-331Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-332F | M2000/4-332F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-332K | M2000/4-332K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-332Z | M2000/4-332Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-333F | M2000/4-333F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-333K | M2000/4-333K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-333Z | M2000/4-333Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-334F | M2000/4-334F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-334K | M2000/4-334K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-334Z | M2000/4-334Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-335 | M2000/4-335 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-336 | M2000/4-336 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-337 | M2000/4-337 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-338 | M2000/4-338 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-339 | M2000/4-339 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-340 | M2000/4-340 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-341 | M2000/4-341 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-342 | M2000/4-342 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-343 | M2000/4-343 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-344 | M2000/4-344 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-345 | M2000/4-345 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-346 | M2000/4-346 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-347 | M2000/4-347 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-348 | M2000/4-348 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-349 | M2000/4-349 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-350 | M2000/4-350 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-351 | M2000/4-351 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-352 | M2000/4-352 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-353 | M2000/4-353 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-354 | M2000/4-354 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-355 | M2000/4-355 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-356 | M2000/4-356 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-357 | M2000/4-357 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-358 | M2000/4-358 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-359 | M2000/4-359 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-360 | M2000/4-360 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-361 | M2000/4-361 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-362 | M2000/4-362 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-363 | M2000/4-363 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-364 | M2000/4-364 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-365 | M2000/4-365 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-366 | M2000/4-366 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/4-367 | M2000/4-367 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-368 | M2000/4-368 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-369 | M2000/4-369 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-370 | M2000/4-370 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-371 | M2000/4-371 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-430 | M2000/4-430 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-431 | M2000/4-431 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-432 | M2000/4-432 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-433 | M2000/4-433 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-435F | M2000/4-435F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-435K | M2000/4-435K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-435Z | M2000/4-435Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-436F | M2000/4-436F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-436K | M2000/4-436K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-436Z | M2000/4-436Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-437F | M2000/4-437F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-437K | M2000/4-437K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-437Z | M2000/4-437Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-438F | M2000/4-438F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-438K | M2000/4-438K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-438Z | M2000/4-438Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-439F | M2000/4-439F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-439K | M2000/4-439K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-439Z | M2000/4-439Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-440F | M2000/4-440F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-440K | M2000/4-440K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-440Z | M2000/4-440Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-441F | M2000/4-441F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-441K | M2000/4-441K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-441Z | M2000/4-441Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-442F | M2000/4-442F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-442K | M2000/4-442K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-442Z | M2000/4-442Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-443F | M2000/4-443F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-443K | M2000/4-443K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-443Z | M2000/4-443Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-444F | M2000/4-444F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-444K | M2000/4-444K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-444Z | M2000/4-444Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-445F | M2000/4-445F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-445K | M2000/4-445K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-445Z | M2000/4-445Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-446F | M2000/4-446F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-446K | M2000/4-446K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-446Z | M2000/4-446Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-447F | M2000/4-447F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-447K | M2000/4-447K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-447Z | M2000/4-447Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-448F | M2000/4-448F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-448K | M2000/4-448K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-448Z | M2000/4-448Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-449F | M2000/4-449F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-449K | M2000/4-449K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-449Z | M2000/4-449Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-450F | M2000/4-450F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-450K | M2000/4-450K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-450Z | M2000/4-450Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-451F | M2000/4-451F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-451K | M2000/4-451K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-451Z | M2000/4-451Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-452F | M2000/4-452F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-452K | M2000/4-452K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-452Z | M2000/4-452Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-453F | M2000/4-453F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-453K | M2000/4-453K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-453Z | M2000/4-453Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-454F | M2000/4-454F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-454K | M2000/4-454K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-454Z | M2000/4-454Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-455F | M2000/4-455F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-455K | M2000/4-455K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-455Z | M2000/4-455Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-456F | M2000/4-456F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-456K | M2000/4-456K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-456Z | M2000/4-456Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-457F | M2000/4-457F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-457K | M2000/4-457K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-457Z | M2000/4-457Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-458F | M2000/4-458F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-458K | M2000/4-458K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-458Z | M2000/4-458Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-459F | M2000/4-459F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-459K | M2000/4-459K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-459Z | M2000/4-459Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-460F | M2000/4-460F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-460K | M2000/4-460K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-460Z | M2000/4-460Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-461F | M2000/4-461F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-461K | M2000/4-461K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-461Z | M2000/4-461Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-462F | M2000/4-462F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-462K | M2000/4-462K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-462Z | M2000/4-462Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-463F | M2000/4-463F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-463K | M2000/4-463K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-463Z | M2000/4-463Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-464F | M2000/4-464F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-464K | M2000/4-464K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-464Z | M2000/4-464Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-465F | M2000/4-465F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-465K | M2000/4-465K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-465Z | M2000/4-465Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-466F | M2000/4-466F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-466K | M2000/4-466K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-466Z | M2000/4-466Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-467F | M2000/4-467F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-467K | M2000/4-467K | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-467Z | M2000/4-467Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/4-305F | 231-01-37-307 | 24308-454-74 | Cinch Connectors (Vinita, OK) |
| M24308/4-1F | 231-01-09-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-1Z | 231-01-09-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-2F | 231-01-15-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-2Z | 231-01-15-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-3F | 231-01-25-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-3Z | 231-01-25-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-4F | 231-01-37-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-4Z | 231-01-37-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-5F | 231-01-50-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-5Z | 231-01-50-102 | 255, 20 MAR 69 | Cinch Connectors, Inc. |
| M24308/4-259F | 231-01-09-109 | 24308-454-74 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-259Z | 231-01-09-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-260F | 231-01-15-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-260Z | 231-01-15-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-261F | 231-01-25-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-261Z | 231-01-25-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-262F | 231-01-37-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-262Z | 231-01-37-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-263F | 231-01-50-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-263Z | 231-01-50-109 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-302F | 231-01-09-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-302Z | 231-01-09-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-303F | 231-01-15-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-303Z | 231-01-15-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-304F | 231-01-25-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-304Z | 231-01-25-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-305Z | 231-01-37-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-306F | 231-01-50-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-306Z | 231-01-50-307 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-313F | 231-01-09-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-313Z | 231-01-09-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-314F | 231-01-15-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-314Z | 231-01-15-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-315F | 231-01-25-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-315Z | 231-01-25-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-316F | 231-01-37-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-316Z | 231-01-37-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-317F | 231-01-50-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-317Z | 231-01-50-309 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-324F | 231-01-09-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-324Z | 231-01-09-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-325F | 231-01-15-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-325Z | 231-01-15-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-326F | 231-01-25-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-326Z | 231-01-25-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-327F | 231-01-37-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-327Z | 231-01-37-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-328F | 231-01-50-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-328Z | 231-01-50-308 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-435F | 231-01-09-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-435Z | 231-01-09-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-436F | 231-01-15-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-436Z | 231-01-15-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-437F | 231-01-25-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-437Z | 231-01-25-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-438F | 231-01-37-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-438Z | 231-01-37-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-439F | 231-01-50-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-439Z | 231-01-50-342 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-446F | 231-01-09-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-446Z | 231-01-09-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-447F | 231-01-15-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-447Z | 231-01-15-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-448F | 231-01-25-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-448Z | 231-01-25-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-449F | 231-01-37-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-449Z | 231-01-37-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-450F | 231-01-50-344 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-450Z | 231-01-50-344 | 24308-454-74 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-457F | 231-01-09-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-457Z | 231-01-09-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-458F | 231-01-15-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-458Z | 231-01-15-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-459F | 231-01-25-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-459Z | 231-01-25-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-460F | 231-01-37-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-460Z | 231-01-37-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-461F | 231-01-50-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-461Z | 231-01-50-345 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/4-1F | DEG9P1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-2F | DAG15P1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-3F | DBG25P1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-4F | DCG37P1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-5F | DDG50P1-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-6F | DEG9P1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-7F | DAG15P1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-8F | DBG25P1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-9F | DCG37P1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-10F | DDG50P1-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-259F | DEG9P1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-260F | DAG15P1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-261F | DBG25P1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-262F | DCG37P1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-263F | DDG50P1N0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-302F | DEG9P1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-303F | DAG15P1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-304F | DBG25P1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-305F | DCG37P1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-306F | DDG50P1F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-313F | DEG9P1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-314F | DAG15P1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-315F | DBG25P1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-316F | DCG37P1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-317F | DDG50P1F-T2-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-324F | DEG9P1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-325F | DAG15P1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-326F | DBG25P1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-327F | DCG37P1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-328F | DDG50P1FN0-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/4-1F | M24308/4-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-1Z | M24308/4-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-2F | M24308/4-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-2Z | M24308/4-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-3F | M24308/4-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-3Z | M24308/4-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-4F | M24308/4-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-4Z | M24308/4-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-5F | M24308/4-5F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-5Z | M24308/4-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-6F | M24308/4-6F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-6Z | M24308/4-6Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-7F | M24308/4-7F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-7Z | M24308/4-7Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-8F | M24308/4-8F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-8Z | M24308/4-8Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-9F | M24308/4-9F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-9Z | M24308/4-9Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-10F | M24308/4-10F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-10Z | M24308/4-10Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-11F | M24308/4-11F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-11Z | M24308/4-11Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-12F | M24308/4-12F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-12Z | M24308/4-12Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-13F | M24308/4-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-13Z | M24308/4-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-14F | M24308/4-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-14Z | M24308/4-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-15F | M24308/4-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-15Z | M24308/4-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-17F | M24308/4-17F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-17Z | M24308/4-17Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-18F | M24308/4-18F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-18Z | M24308/4-18Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-19F | M24308/4-19F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-19Z | M24308/4-19Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-20F | M24308/4-20F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-20Z | M24308/4-20Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-21F | M24308/4-21F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-21Z | M24308/4-21Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-259F | M24308/4-259F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-259Z | M24308/4-259Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-260F | M24308/4-260F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-260Z | M24308/4-260Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-261F | M24308/4-261F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-261Z | M24308/4-261Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-262F | M24308/4-262F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-262Z | M24308/4-262Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-263F | M24308/4-263F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-263Z | M24308/4-263Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-264F | M24308/4-264F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-264Z | M24308/4-264Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-265F | M24308/4-265F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-265Z | M24308/4-265Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-266F | M24308/4-266F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-266Z | M24308/4-266Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-267F | M24308/4-267F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-267Z | M24308/4-267Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-268F | M24308/4-268F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-268Z | M24308/4-268Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-302F | M24308/4-302F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-302Z | M24308/4-302Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-303F | M24308/4-303F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-303Z | M24308/4-303Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-304F | M24308/4-304F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-304Z | M24308/4-304Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-305F | M24308/4-305F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-305Z | M24308/4-305Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-306F | M24308/4-306F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-306Z | M24308/4-306Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-307F | M24308/4-307F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-307Z | M24308/4-307Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-308F | M24308/4-308F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-308Z | M24308/4-308Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-309F | M24308/4-309F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-309Z | M24308/4-309Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-310F | M24308/4-310F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-310Z | M24308/4-310Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-311F | M24308/4-311F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-311Z | M24308/4-311Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-313F | M24308/4-313F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-313Z | M24308/4-313Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-314F | M24308/4-314F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-314Z | M24308/4-314Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-315F | M24308/4-315F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-315Z | M24308/4-315Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-316F | M24308/4-316F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-316Z | M24308/4-316Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-317F | M24308/4-317F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-317Z | M24308/4-317Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-318F | M24308/4-318F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-318F | M24308/4-318F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-319F | M24308/4-319F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-319F | M24308/4-319F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-320F | M24308/4-320F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-320F | M24308/4-320F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-321F | M24308/4-321F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-321F | M24308/4-321F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-322F | M24308/4-322F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-322F | M24308/4-322F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-324F | M24308/4-324F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-324Z | M24308/4-324Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-325F | M24308/4-325F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-325Z | M24308/4-325Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-326F | M24308/4-326F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-326Z | M24308/4-326Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-327F | M24308/4-327F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-327Z | M24308/4-327Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-328F | M24308/4-328F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-328Z | M24308/4-328Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-329F | M24308/4-329F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-329Z | M24308/4-329Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-330F | M24308/4-330F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-330Z | M24308/4-330Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-331F | M24308/4-331F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-331Z | M24308/4-331Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-332F | M24308/4-332F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-332Z | M24308/4-332Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-333F | M24308/4-333F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-333Z | M24308/4-333Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-435F | M24308/4-435F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-435Z | M24308/4-435Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-436F | M24308/4-436F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-436Z | M24308/4-436Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-437F | M24308/4-437F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-437Z | M24308/4-437Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-438F | M24308/4-438F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-438Z | M24308/4-438Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-439F | M24308/4-439F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-439Z | M24308/4-439Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-440F | M24308/4-440F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-440Z | M24308/4-440Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-441F | M24308/4-441F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-441Z | M24308/4-441Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-442F | M24308/4-442F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-442Z | M24308/4-442Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-443F | M24308/4-443F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-443Z | M24308/4-443Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-444F | M24308/4-444F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-444Z | M24308/4-444Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-446F | M24308/4-446F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-446Z | M24308/4-446Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-447F | M24308/4-447F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-447Z | M24308/4-447Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-448F | M24308/4-448F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-448Z | M24308/4-448Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-449F | M24308/4-449F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-449Z | M24308/4-449Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-450F | M24308/4-450F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-450Z | M24308/4-450Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-451F | M24308/4-451F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-451Z | M24308/4-451Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-452F | M24308/4-452F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-452Z | M24308/4-452Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-453F | M24308/4-453F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-453Z | M24308/4-453Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-454F | M24308/4-454F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-454Z | M24308/4-454Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-455F | M24308/4-455F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-455Z | M24308/4-455Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-457F | M24308/4-457F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-457Z | M24308/4-457Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-458F | M24308/4-458F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-458Z | M24308/4-458Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-459F | M24308/4-459F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-459Z | M24308/4-459Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-460F | M24308/4-460F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-460Z | M24308/4-460Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-461F | M24308/4-461F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-461Z | M24308/4-461Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-462F | M24308/4-462F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-462Z | M24308/4-462Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-463F | M24308/4-463F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-463Z | M24308/4-463Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-464F | M24308/4-464F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-464Z | M24308/4-464Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-465F | M24308/4-465F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-465Z | M24308/4-465Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-466F | M24308/4-466F | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-466Z | M24308/4-466Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/4-1F | RD9M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-1Z | RD9M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-2F | RD15M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-2Z | RD15M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-3F | RD25M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-3Z | RD25M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-4F | RD37M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-4Z | RD37M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-5F | RD50M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-5Z | RD50M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-6F | RD9M1000C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-6Z | RD9M10000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-7F | RD15M1000C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-7Z | RD15M10000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-8F | RD25M1000C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-8Z | RD25M10000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-9F | RD37M1000C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-9Z | RD37M10000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-10F | RD50M1000C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-10Z | RD50M10000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-11F | DD15M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-11Z | DD15M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-12F | DD26M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-12Z | DD26M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-13F | DD44M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-13Z | DD44M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-14F | DD62M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-14Z | DD62M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-15F | DD78M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-15Z | DD78M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-16F | DD104M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-16Z | DD104M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-17F | DD15M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-17Z | DD15M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-18F | DD26M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-18Z | DD26M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-19F | DD44M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-19Z | DD44M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-20F | DD62M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-20Z | DD62M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-21F | DD78M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-21Z | DD78M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-22F | DD104M1000C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-22Z | DD104M10000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-259F | RD9M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-259Z | RD9M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-260F | RD15M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-260Z | RD15M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-261F | RD25M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-261Z | RD25M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-262F | RD37M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-262Z | RD37M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-263F | RD50M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-263Z | RD50M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-264F | DD15M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-264Z | DD15M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-265F | DD26M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-265Z | DD26M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-266F | DD44M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-266Z | DD44M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-267F | DD62M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-267Z | DD62M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-268F | DD78M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-268Z | DD78M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-269F | DD104M0000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-269Z | DD104M00000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-302F | RD9M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-302Z | RD9M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-303F | RD15M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-303Z | RD15M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-304F | RD25M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-304Z | RD25M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-305F | RD37M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-305Z | RD37M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-306F | RD50M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-306Z | RD50M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-313F | RD9M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-313Z | RD9M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-314F | RD15M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-314Z | RD15M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-315F | RD25M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-315Z | RD25M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-316F | RD37M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-316Z | RD37M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-317F | RD50M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-317Z | RD50M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-324F | RD9M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-324Z | RD9M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-325F | RD15M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-325Z | RD15M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-326F | RD25M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-326Z | RD25M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-327F | RD37M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-327Z | RD37M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-328F | RD50M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-328Z | RD50M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-335 | RD9M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-336 | RD15M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-337 | RD25M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-338 | RD37M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-339 | RD50M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-340 | RD9M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-341 | RD15M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-342 | RD25M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-343 | RD37M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-344 | RD50M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-345 | DD15M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-346 | DD26M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-347 | DD44M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-348 | DD62M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-349 | DD78M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-350 | DD104M10000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-351 | DD15M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-352 | DD26M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-353 | DD44M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-354 | DD62M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-355 | DD78M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-356 | DD104M10000-MIL-799.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-357 | RD9M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-358 | RD15M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-359 | RD25M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-360 | RD37M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-361 | RD50M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-362 | DD15M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-363 | DD26M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-364 | DD44M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-365 | DD62M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-366 | DD78M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-367 | DD104M00000-MIL-799.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-401 | RD9M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-402 | RD15M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-403 | RD25M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-404 | RD37M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-405 | RD50M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-406 | DD15M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-407 | DD26M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-408 | DD44M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-409 | DD62M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-410 | DD78M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-411 | DD104M1F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-412 | RD9M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-413 | RD15M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-414 | RD25M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-415 | RD37M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-416 | RD50M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-417 | DD15M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-418 | DD26M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-419 | DD44M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-420 | DD62M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-421 | DD78M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-422 | DD104M1F000-MIL-799.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-423 | RD9M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-424 | RD15M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-425 | RD25M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-426 | RD37M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-427 | RD50M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-428 | DD15M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-429 | DD26M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-430 | DD44M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-431 | DD62M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-432 | DD78M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-433 | DD104M0F000-MIL-799.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-435F | RD9M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-435Z | RD9M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-436F | RD15M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-436Z | RD15M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-437F | RD25M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-437Z | RD25M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-438F | RD37M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-438Z | RD37M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-439F | RD50M1F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-439Z | RD50M1F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-440F | DD15M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-440Z | DD15M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-441F | DD26M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-441Z | DD26M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-442F | DD44M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-442Z | DD44M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-443F | DD62M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-443Z | DD62M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-444F | DD78M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-444Z | DD78M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-445F | DD104M1000C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-445Z | DD104M10000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-446F | RD9M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-446Z | RD9M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-447F | RD15M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-447Z | RD15M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-448F | RD25M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-448Z | RD25M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-449F | RD37M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-449Z | RD37M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-450F | RD50M1F00C-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-450Z | RD50M1F000-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-451F | DD15M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-451Z | DD15M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-452F | DD26M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-452Z | DD26M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-453F | DD44M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-453Z | DD44M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-454F | DD62M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-454Z | DD62M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-455F | DD78M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-455Z | DD78M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-456F | DD104M1F00C-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-456Z | DD104M1F000-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-457F | RD9M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-457Z | RD9M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-458F | RD15M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-458Z | RD15M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-459F | RD25M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-459Z | RD25M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-460F | RD37M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-460Z | RD37M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-461F | RD50M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-461Z | RD50M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-462F | DD15M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-462Z | DD15M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-463F | DD26M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-463Z | DD26M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-464F | DD44M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-464Z | DD44M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-465F | DD62M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-465Z | DD62M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-466F | DD78M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-466Z | DD78M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-467F | DD104M0F00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-467Z | DD104M0F000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/4-1F | SEMA09P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-2F | SAMA15P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-3F | SBMA25P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-4F | SCMA37P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-5F | SDMA50P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-6F | SEMAT09P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-7F | SAMAT15P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-8F | SBMAT25P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-9F | SCMAT37P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-10F | SDMAT50P | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-259F | SEMA-09PL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-260F | SAMA-15PL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-261F | SBMA-25PL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-262F | SCMA-37PL | 24308-169-77; 24308-174-88 | Souriau |
| M24308/4-263F | SDMA-50PL | 24308-169-77; 24308-174-88 | Souriau |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---|--|
| M24308/4-302F | SEMAF09P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-303F | SAMAF15P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-304F | SBMAF25P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-305F | SCMAF37P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-306F | SDMAF50P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-313F | SEMAFT09P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-314F | SAMAFT15P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-315F | SBMAFT25P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-316F | SCMAFT37P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-317F | SDMAFT50P | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-324F | SEMAF09PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-324F | SEMAF09PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-325F | SAMAF15PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-326F | SBMAF25PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-327F | SCMAF37PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-328F | SDMAF50PL | 24308-174-88; 24308-309-79 | Souriau |
| M24308/4-1F | 205556-2 | 24308-703-71; 24308-704-71; 24308-705-71; 24308-706-71; 24308-707-71 | Tyco Electronics |
| M24308/4-1Z | 1757819-6 | 24308-1320-05 | Tyco Electronics |
| M24308/4-2F | 205558-2 | 24308-703-71; 24308-704-71; 24308-705-71; 24308-706-71; 24308-707-71 | Tyco Electronics |
| M24308/4-2Z | 1757819-7 | 24308-1320-05 | Tyco Electronics |
| M24308/4-3F | 205560-2 | 24308-703-71; 24308-704-71; 24308-705-71; 24308-706-71; 24308-707-71 | Tyco Electronics |
| M24308/4-3Z | 1757819-8 | 24308-1320-05 | Tyco Electronics |
| M24308/4-4F | 205562-2 | 24308-703-71; 24308-704-71; 24308-705-71; 24308-706-71; 24308-707-71 | Tyco Electronics |
| M24308/4-4Z | 1757819-9 | 24308-1320-05 | Tyco Electronics |
| M24308/4-5F | 205564-2 | 24308-703-71; 24308-704-71; 24308-705-71; 24308-706-71; 24308-707-71 | Tyco Electronics |
| M24308/4-5Z | 1-1757819-0 | 24308-1320-05 | Tyco Electronics |
| M24308/4-6F | 205556-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-7F | 205558-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-8F | 205560-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-9F | 205562-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-10F | 205564-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-11F | 204513-2 | 24308-1254-71 | Tyco Electronics |
| M24308/4-11Z | 1757823-7 | 24308-1320-05 | Tyco Electronics |
| M24308/4-12F | 204515-2 | 24308-1255-71 | Tyco Electronics |
| M24308/4-12Z | 1757823-8 | 24308-1320-05 | Tyco Electronics |
| M24308/4-13F | 204517-2 | 24308-1256-71 | Tyco Electronics |
| M24308/4-13Z | 1757823-9 | 24308-1320-05 | Tyco Electronics |
| M24308/4-14F | 204519-2 | 24308-1257-71 | Tyco Electronics |
| M24308/4-14Z | 1-1757823-0 | 24308-1320-05 | Tyco Electronics |
| M24308/4-15F | 204521-2 | 24308-1258-71 | Tyco Electronics |
| M24308/4-15Z | 1-1757823-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-16F | 204523-2 | 24308-1278-70 | Tyco Electronics |
| M24308/4-16Z | 1-1757823-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-17F | 204513-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-18F | 204515-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-19F | 204517-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-20F | 204519-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-21F | 204521-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-22F | 204523-3 | 24308-215-77 | Tyco Electronics |
| M24308/4-259F | 205162-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-259Z | 1757819-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-260F | 205164-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-260Z | 1757819-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-261F | 205166-1 | 24308-216-77 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-261Z | 1757819-3 | 24308-1320-05 | Tyco Electronics |
| M24308/4-262F | 205168-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-262Z | 1757819-4 | 24308-1320-05 | Tyco Electronics |
| M24308/4-263F | 205170-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-263Z | 1757819-5 | 24308-1320-05 | Tyco Electronics |
| M24308/4-264F | 204501-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-264Z | 1757823-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-265F | 204503-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-265Z | 1757823-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-266F | 204505-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-266Z | 1757823-3 | 24308-1320-05 | Tyco Electronics |
| M24308/4-267F | 204507-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-267Z | 1757823-4 | 24308-1320-05 | Tyco Electronics |
| M24308/4-268F | 204509-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-268Z | 1757823-5 | 24308-1320-05 | Tyco Electronics |
| M24308/4-269F | 204511-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-269Z | 1757823-6 | 24308-1320-05 | Tyco Electronics |
| M24308/4-302F | 205486-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-302Z | 1757821-6 | 24308-1320-05 | Tyco Electronics |
| M24308/4-303F | 205409-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-303Z | 1757821-7 | 24308-1320-05 | Tyco Electronics |
| M24308/4-304F | 205487-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-304Z | 1757821-8 | 24308-1320-05 | Tyco Electronics |
| M24308/4-305F | 205488-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-305Z | 1757821-9 | 24308-1320-05 | Tyco Electronics |
| M24308/4-306F | 205431-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-306Z | 1-1757821-0 | 24308-1320-05 | Tyco Electronics |
| M24308/4-307F | 204537-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-307Z | 1757825-7 | 24308-1320-05 | Tyco Electronics |
| M24308/4-308F | 204539-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-308Z | 1757825-8 | 24308-1320-05 | Tyco Electronics |
| M24308/4-309F | 204541-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-309Z | 1757825-9 | 24308-1320-05 | Tyco Electronics |
| M24308/4-310F | 204543-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-310Z | 1-1757825-0 | 24308-1320-05 | Tyco Electronics |
| M24308/4-311F | 204545-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-311Z | 1-1757825-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-312F | 204547-2 | 24308-602-76 | Tyco Electronics |
| M24308/4-312Z | 1-1757825-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-313F | 593032-1 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-314F | 593032-2 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-315F | 593032-3 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-316F | 593032-4 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-317F | 593032-5 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-318F | 593033-1 | 1140, MAY 69 | Tyco Electronics |
| M24308/4-324F | 205412-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-324Z | 1757821-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-325F | 205408-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-325Z | 1757821-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-326F | 205413-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-326Z | 1757821-3 | 24308-1320-05 | Tyco Electronics |
| M24308/4-327F | 205414-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-327Z | 1757821-4 | 24308-1320-05 | Tyco Electronics |
| M24308/4-328F | 205415-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-328Z | 1757821-5 | 24308-1320-05 | Tyco Electronics |
| M24308/4-329F | 204525-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-329Z | 1757825-1 | 24308-1320-05 | Tyco Electronics |
| M24308/4-330F | 204527-1 | 24308-216-77 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/4-330Z | 1757825-2 | 24308-1320-05 | Tyco Electronics |
| M24308/4-331F | 204529-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-331Z | 1757825-3 | 24308-1320-05 | Tyco Electronics |
| M24308/4-332F | 204531-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-332Z | 1757825-4 | 24308-1320-05 | Tyco Electronics |
| M24308/4-333F | 204533-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-333Z | 1757825-5 | 24308-1320-05 | Tyco Electronics |
| M24308/4-334F | 204535-1 | 24308-216-77 | Tyco Electronics |
| M24308/4-334Z | 1757825-6 | 24308-1320-05 | Tyco Electronics |
| M24308/5-1F | M2000/5-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-1Z | M2000/5-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-2F | M2000/5-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-2Z | M2000/5-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-3F | M2000/5-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-3Z | M2000/5-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-4F | M2000/5-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-4Z | M2000/5-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-5F | M2000/5-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-5Z | M2000/5-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-12F | M2000/5-12F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-12Z | M2000/5-12Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-13F | M2000/5-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-13Z | M2000/5-13Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-14F | M2000/5-14F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-14Z | M2000/5-14Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-15F | M2000/5-15F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-15Z | M2000/5-15Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-16F | M2000/5-16F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-16Z | M2000/5-16Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-23F | M2000/5-23F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-23Z | M2000/5-23Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-24F | M2000/5-24F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-24Z | M2000/5-24Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-25F | M2000/5-25F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-25Z | M2000/5-25Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-26F | M2000/5-26F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-26Z | M2000/5-26Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-27F | M2000/5-27F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-27Z | M2000/5-27Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-34 | M2000/5-34 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-35 | M2000/5-35 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-36 | M2000/5-36 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-37 | M2000/5-37 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-38 | M2000/5-38 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-45 | M2000/5-45 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-46 | M2000/5-46 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-47 | M2000/5-47 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-48 | M2000/5-48 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-49 | M2000/5-49 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-56 | M2000/5-56 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-57 | M2000/5-57 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-58 | M2000/5-58 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-59 | M2000/5-59 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-60 | M2000/5-60 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/5-34 | 115372-2001 | 24308-3535-12 | C&K Components SAS |
| M24308/5-35 | 115372-2003 | 24308-3535-12 | C&K Components SAS |
| M24308/5-36 | 115372-2005 | 24308-3535-12 | C&K Components SAS |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/5-37 | 115372-2007 | 24308-3535-12 | C&K Components SAS |
| M24308/5-38 | 115372-2009 | 24308-3535-12 | C&K Components SAS |
| M24308/5-56 | 115372-2051 | 24308-3535-12 | C&K Components SAS |
| M24308/5-57 | 115372-2053 | 24308-3535-12 | C&K Components SAS |
| M24308/5-58 | 115372-2055 | 24308-3535-12 | C&K Components SAS |
| M24308/5-59 | 115372-2057 | 24308-3535-12 | C&K Components SAS |
| M24308/5-60 | 115372-2059 | 24308-3535-12 | C&K Components SAS |
| M24308/5-1F | DEG9S2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/5-2F | DAG15S2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/5-3F | DBG25S2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/5-4F | DCG37S2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/5-5F | DDG50S2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/5-1F | HDC9S2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-1P | HDC9S2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-1Z | HDC9S20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-2F | HDC15S2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-2P | HDC15S2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-2Z | HDC15S20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-3F | HDC25S2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-3P | HDC25S2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-3Z | HDC25S20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-4F | HDC37S2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-4P | HDC37S2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-4Z | HDC37S20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-5F | HDC50S2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-5P | HDC50S2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-5Z | HDC50S20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-23F | HDC9S2S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-23P | HDC9S2S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-23Z | HDC9S2S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-24F | HDC15S2S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-24P | HDC15S2S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-24Z | HDC15S2S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-25F | HDC25S2S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-25P | HDC25S2S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-25Z | HDC25S2S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-26F | HDC37S2S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-26P | HDC37S2S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-26Z | HDC37S2S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-27F | HDC50S2S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-27P | HDC50S2S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-27Z | HDC50S2S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-34 | HDC9S20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-35 | HDC15S20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-36 | HDC25S20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-37 | HDC37S20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-38 | HDC50S20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-56 | HDC9S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-57 | HDC15S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-58 | HDC25S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-59 | HDC37S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-60 | HDC50S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-60 | HDC50S2S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/5-34 | DEM9P011NM | 24308-072-99 | Souriau |
| M24308/5-35 | DAM15S011NM | 24308-072-99 | Souriau |
| M24308/5-36 | DBM25S011NM | 24308-072-99 | Souriau |
| M24308/5-37 | DCM37S011NM | 24308-072-99 | Souriau |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/5-38 | DDM50S011NM | 24308-072-99 | Souriau |
| M24308/6-1F | M2000/6-1F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-1Z | M2000/6-1Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-2F | M2000/6-2F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-2Z | M2000/6-2Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-3F | M2000/6-3F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-3Z | M2000/6-3Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-4F | M2000/6-4F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-4Z | M2000/6-4Z | | Amphenol Interconnect India PVT LTD |
| M24308/6-5F | M2000/6-5F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-5Z | M2000/6-5Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-6F | M2000/6-6F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-6Z | M2000/6-6Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-7F | M2000/6-7F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-7Z | M2000/6-7Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-8F | M2000/6-8F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-8Z | M2000/6-8Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-9F | M2000/6-9F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-9Z | M2000/6-9Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-10F | M2000/6-10F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-10Z | M2000/6-10Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-11F | M2000/6-11F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-11Z | M2000/6-11Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-12F | M2000/6-12F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-12Z | M2000/6-12Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-13F | M2000/6-13F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-13Z | M2000/6-13Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-14F | M2000/6-14F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-14Z | M2000/6-14Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-15F | M2000/6-15F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-15Z | M2000/6-15Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-16F | M2000/6-16F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-16Z | M2000/6-16Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-17F | M2000/6-17F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-17Z | M2000/6-17Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-18F | M2000/6-18F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-18Z | M2000/6-18Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-19F | M2000/6-19F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-19Z | M2000/6-19Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-20F | M2000/6-20F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-20Z | M2000/6-20Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-21F | M2000/6-21F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-21Z | M2000/6-21Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-22F | M2000/6-22F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-22Z | M2000/6-22Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-259F | M2000/6-259F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-259Z | M2000/6-259Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-260F | M2000/6-260F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-260Z | M2000/6-260Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-261F | M2000/6-261F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-261Z | M2000/6-261Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-262F | M2000/6-262F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-262Z | M2000/6-262Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-263F | M2000/6-263F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-263Z | M2000/6-263Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-264F | M2000/6-264F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-264Z | M2000/6-264Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-265F | M2000/6-265F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-265Z | M2000/6-265Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-266F | M2000/6-266F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-266Z | M2000/6-266Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-267F | M2000/6-267F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-267Z | M2000/6-267Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-268F | M2000/6-268F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-268Z | M2000/6-268Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-269F | M2000/6-269F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-269Z | M2000/6-269Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-270F | M2000/6-270F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-270Z | M2000/6-270Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-271F | M2000/6-271F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-271Z | M2000/6-271Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-272F | M2000/6-272F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-272Z | M2000/6-272Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-273F | M2000/6-273F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-273Z | M2000/6-273Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-274F | M2000/6-274F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-274Z | M2000/6-274Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-275F | M2000/6-275F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-275Z | M2000/6-275Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-276F | M2000/6-276F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-276Z | M2000/6-276Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-277F | M2000/6-277F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-277Z | M2000/6-277Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-278F | M2000/6-278F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-278Z | M2000/6-278Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-279F | M2000/6-279F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-279Z | M2000/6-279Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-280F | M2000/6-280F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-280Z | M2000/6-280Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-281F | M2000/6-281F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-281Z | M2000/6-281Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-282F | M2000/6-282F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-282Z | M2000/6-282Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-283F | M2000/6-283F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-283Z | M2000/6-283Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-284F | M2000/6-284F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-284Z | M2000/6-284Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-285F | M2000/6-285F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-285Z | M2000/6-285Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-286F | M2000/6-286F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-286Z | M2000/6-286Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-287F | M2000/6-287F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-287Z | M2000/6-287Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-288F | M2000/6-288F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-288Z | M2000/6-288Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-289F | M2000/6-289F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-289Z | M2000/6-289Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-290F | M2000/6-290F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-290Z | M2000/6-290Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/6-291F | M2000/6-291F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-291Z | M2000/6-291Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-453F | M2000/6-453F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-453Z | M2000/6-453Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-454F | M2000/6-454F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-454Z | M2000/6-454Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-455F | M2000/6-455F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-455Z | M2000/6-455Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-456F | M2000/6-456F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-456Z | M2000/6-456Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-457F | M2000/6-457F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-457Z | M2000/6-457Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-458F | M2000/6-458F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-458Z | M2000/6-458Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-459F | M2000/6-459F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-459Z | M2000/6-459Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-460F | M2000/6-460F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-460Z | M2000/6-460Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-461F | M2000/6-461F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-461Z | M2000/6-461Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-462F | M2000/6-462F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-462Z | M2000/6-462Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-463F | M2000/6-463F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-463Z | M2000/6-463Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-464F | M2000/6-464F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-464Z | M2000/6-464Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-465F | M2000/6-465F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-465Z | M2000/6-465Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-466F | M2000/6-466F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-466Z | M2000/6-466Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-467F | M2000/6-467F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-467Z | M2000/6-467Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-468F | M2000/6-468F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-468Z | M2000/6-468Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-469F | M2000/6-469F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-469Z | M2000/6-469Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-470F | M2000/6-470F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-470Z | M2000/6-470Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-471F | M2000/6-471F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-471Z | M2000/6-471Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-472F | M2000/6-472F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-472Z | M2000/6-472Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-473F | M2000/6-473F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-473Z | M2000/6-473Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-474F | M2000/6-474F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-474Z | M2000/6-474Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-491F | M2000/6-491F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-491Z | M2000/6-491Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-492F | M2000/6-492F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-492Z | M2000/6-492Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-493F | M2000/6-493F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-493Z | M2000/6-493Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-494F | M2000/6-494F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-494Z | M2000/6-494Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-495F | M2000/6-495F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-495Z | M2000/6-495Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-496F | M2000/6-496F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-496Z | M2000/6-496Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-497F | M2000/6-497F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-497Z | M2000/6-497Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-498F | M2000/6-498F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-498Z | M2000/6-498Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-499F | M2000/6-499F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-499Z | M2000/6-499Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-500F | M2000/6-500F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-500Z | M2000/6-500Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-501F | M2000/6-501F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-501Z | M2000/6-501Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-502 | M2000/6-502 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-503 | M2000/6-503 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-504 | M2000/6-504 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-505 | M2000/6-505 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-506 | M2000/6-506 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-507 | M2000/6-507 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-508 | M2000/6-508 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-509 | M2000/6-509 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-510 | M2000/6-510 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-511 | M2000/6-511 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-512 | M2000/6-512 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-513 | M2000/6-513 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-514 | M2000/6-514 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-515 | M2000/6-515 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-516 | M2000/6-516 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-517 | M2000/6-517 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-518 | M2000/6-518 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-519 | M2000/6-519 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-520 | M2000/6-520 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-521 | M2000/6-521 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-522 | M2000/6-522 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-523 | M2000/6-523 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-524 | M2000/6-524 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-525 | M2000/6-525 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-526 | M2000/6-526 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-527 | M2000/6-527 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-528 | M2000/6-528 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-529 | M2000/6-529 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-530 | M2000/6-530 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-531 | M2000/6-531 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-532 | M2000/6-532 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-533 | M2000/6-533 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-534 | M2000/6-534 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-535 | M2000/6-535 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-536 | M2000/6-536 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-537 | M2000/6-537 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-538 | M2000/6-538 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-539 | M2000/6-539 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-540 | M2000/6-540 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-541 | M2000/6-541 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-542 | M2000/6-542 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-543 | M2000/6-543 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-544 | M2000/6-544 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-545 | M2000/6-545 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-546 | M2000/6-546 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-547 | M2000/6-547 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-548 | M2000/6-548 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-549 | M2000/6-549 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/6-550 | M2000/6-550 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-551 | M2000/6-551 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-552 | M2000/6-552 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-553 | M2000/6-553 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-554 | M2000/6-554 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-555 | M2000/6-555 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-556 | M2000/6-556 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-557 | M2000/6-557 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-558 | M2000/6-558 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-559 | M2000/6-559 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-560 | M2000/6-560 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-561 | M2000/6-561 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-562 | M2000/6-562 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-563 | M2000/6-563 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-564 | M2000/6-564 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-565 | M2000/6-565 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-566 | M2000/6-566 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-567 | M2000/6-567 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-568 | M2000/6-568 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-569 | M2000/6-569 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-570 | M2000/6-570 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-571 | M2000/6-571 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-572 | M2000/6-572 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-573 | M2000/6-573 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-574 | M2000/6-574 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-575 | M2000/6-575 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-576 | M2000/6-576 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-577 | M2000/6-577 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-578 | M2000/6-578 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-579 | M2000/6-579 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-580 | M2000/6-580 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-581 | M2000/6-581 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-582 | M2000/6-582 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-583 | M2000/6-583 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/6-502 | 115370-1701 | 24308-3535-12 | C&K Components SAS |
| M24308/6-503 | 115370-1703 | 24308-3535-12 | C&K Components SAS |
| M24308/6-504 | 115370-1705 | 24308-3535-12 | C&K Components SAS |
| M24308/6-505 | 115370-1707 | 24308-3535-12 | C&K Components SAS |
| M24308/6-506 | 115370-1709 | 24308-3535-12 | C&K Components SAS |
| M24308/6-512 | C115368-1601 | 24308-3535-12 | C&K Components SAS |
| M24308/6-513 | C115368-1603 | 24308-3535-12 | C&K Components SAS |
| M24308/6-514 | C115368-1605 | 24308-3535-12 | C&K Components SAS |
| M24308/6-515 | C115368-1607 | 24308-3535-12 | C&K Components SAS |
| M24308/6-516 | C115368-1609 | 24308-3535-12 | C&K Components SAS |
| M24308/6-540 | 115370-1711 | 24308-3535-12 | C&K Components SAS |
| M24308/6-541 | 115370-1713 | 24308-3535-12 | C&K Components SAS |
| M24308/6-542 | 115370-1715 | 24308-3535-12 | C&K Components SAS |
| M24308/6-543 | 115370-1717 | 24308-3535-12 | C&K Components SAS |
| M24308/6-544 | 115370-1719 | 24308-3535-12 | C&K Components SAS |
| M24308/6-545 | C115368-1611 | 24308-3535-12 | C&K Components SAS |
| M24308/6-546 | C115368-1613 | 24308-3535-12 | C&K Components SAS |
| M24308/6-547 | C115368-1615 | 24308-3535-12 | C&K Components SAS |
| M24308/6-548 | C115368-1617 | 24308-3535-12 | C&K Components SAS |
| M24308/6-549 | C115368-1619 | 24308-3535-12 | C&K Components SAS |
| M24308/6-551 | 115370-1721 | 24308-3535-12 | C&K Components SAS |
| M24308/6-552 | 115370-1723 | 24308-3535-12 | C&K Components SAS |
| M24308/6-553 | 115370-1725 | 24308-3535-12 | C&K Components SAS |
| M24308/6-554 | 115370-1727 | 24308-3535-12 | C&K Components SAS |
| M24308/6-555 | 115370-1729 | 24308-3535-12 | C&K Components SAS |
| M24308/6-556 | C115368-1621 | 24308-3535-12 | C&K Components SAS |
| M24308/6-557 | C115368-1623 | 24308-3535-12 | C&K Components SAS |
| M24308/6-558 | C115368-1625 | 24308-3535-12 | C&K Components SAS |
| M24308/6-559 | C115368-1627 | 24308-3535-12 | C&K Components SAS |
| M24308/6-560 | C115368-1629 | 24308-3535-12 | C&K Components SAS |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-573 | 115370-1731 | 24308-3535-12 | C&K Components SAS |
| M24308/6-574 | 115370-1733 | 24308-3535-12 | C&K Components SAS |
| M24308/6-575 | 115370-1735 | 24308-3535-12 | C&K Components SAS |
| M24308/6-576 | 115370-1737 | 24308-3535-12 | C&K Components SAS |
| M24308/6-577 | 115370-1739 | 24308-3535-12 | C&K Components SAS |
| M24308/6-578 | C115368-1631 | 24308-3535-12 | C&K Components SAS |
| M24308/6-579 | C115368-1633 | 24308-3535-12 | C&K Components SAS |
| M24308/6-580 | C115368-1635 | 24308-3535-12 | C&K Components SAS |
| M24308/6-581 | C115368-1637 | 24308-3535-12 | C&K Components SAS |
| M24308/6-582 | C115368-1639 | 24308-3535-12 | C&K Components SAS |
| M24308/6-1F | DEG9S1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-2F | DAG15S1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-3F | DBG25S1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-4F | DCG37S1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-5F | DCG37S1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-281F | DEG9S1BN0 | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-282F | DAG15S1BN0 | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-283F | DBG25S1BN0 | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-284F | DCG37S1BN0 | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-285F | DDG50S1BN0 | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/6-1F | RD9S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-1P | RD9S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-1Z | RD9S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-2F | RD15S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-2P | RD15S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-2Z | RD15S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-3F | RD25S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-3P | RD25S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-3Z | RD25S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-4F | RD37S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-4P | RD37S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-4Z | RD37S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-5F | RD50S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-5P | RD50S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-5Z | RD50S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-6F | RD9S1000C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-6P | RD9S1000S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-6Z | RD9S10000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-7F | RD15S1000C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-7P | RD15S1000S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-7Z | RD15S10000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-8F | RD25S1000C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-8P | RD25S1000S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-8Z | RD25S10000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-9F | RD37S1000C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-9P | RD37S1000S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-9Z | RD37S10000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-10F | RD50S1000C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-10P | RD50S1000S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-10Z | RD50S10000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-11F | DD15S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-11P | DD15S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-11Z | DD15S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-12F | DD26S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-12P | DD26S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-12Z | DD26S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-13F | DD44S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-13P | DD44S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-13Z | DD44S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-14F | DD62S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-14P | DD62S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-14Z | DD62S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-15F | DD78S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-15P | DD78S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-15Z | DD78S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-16F | DD104S1000C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-16P | DD104S1000S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-16Z | DD104S10000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-17F | DD15S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-17P | DD15S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-17Z | DD15S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-18F | DD26S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-18P | DD26S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-18Z | DD26S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-19F | DD44S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-19P | DD44S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-19Z | DD44S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-20F | DD62S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-20P | DD62S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-20Z | DD62S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-21F | DD78S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-21P | DD78S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-21Z | DD78S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-22F | DD104S1000C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-22P | DD104S1000S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-22Z | DD104S10000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-281F | RD9S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-281P | RD9S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-281Z | RD9S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-282F | RD15S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-282P | RD15S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-282Z | RD15S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-283F | RD25S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-283P | RD25S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-283Z | RD25S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-284F | RD37S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-284P | RD37S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-284Z | RD37S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-285F | RD50S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-285P | RD50S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-285Z | RD50S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-286F | DD15S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-286P | DD15S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-286Z | DD15S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-287F | DD26S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-287P | DD26S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-287Z | DD26S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-288F | DD44S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-288P | DD44S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-288Z | DD44S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-289F | DD62S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-289P | DD62S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-289Z | DD62S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-290F | DD78S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-290P | DD78S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-290Z | DD78S00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-291F | DD104S0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-291P | DD104S0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-291Z | DD104S00000-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-453F | RD9S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-453P | RD9S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-453Z | RD9S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-454F | RD15S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-454P | RD15S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-454Z | RD15S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-455F | RD25S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-455P | RD25S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-455Z | RD25S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-456F | RD37S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-456P | RD37S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-456Z | RD37S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-457F | RD50S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-457P | RD50S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-457Z | RD50S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-458F | DD15S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-458P | DD15S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-458Z | DD15S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-459F | DD26S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-459P | DD26S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-459Z | DD26S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-460F | DD44S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-460P | DD44S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-460Z | DD44S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-461F | DD62S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-461P | DD62S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-461Z | DD62S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-462F | DD78S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-462P | DD78S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-462Z | DD78S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-463F | DD104S1F00C-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-463P | DD104S1F00S-MIL+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-463Z | DD104S1F000-MIL-403.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-464F | RD9S1F00C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-464P | RD9S1F00S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-464Z | RD9S1F000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-465F | RD15S1F00C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-465P | RD15S1F00S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-465Z | RD15S1F000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-466F | RD25S1F00C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-466P | RD25S1F00S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-466Z | RD25S1F000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-467F | RD37S1F00C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-467P | RD37S1F00S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-467Z | RD37S1F000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-468F | RD50S1F00C-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-468P | RD50S1F00S-MIL-400.0+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-468Z | RD50S1F000-MIL-403.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-469F | DD15S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-469P | DD15S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-469Z | DD15S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-470F | DD26S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-470P | DD26S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-470Z | DD26S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-471F | DD44S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-471P | DD44S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-471Z | DD44S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-472F | DD62S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-472P | DD62S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-472Z | DD62S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-473F | DD78S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-473P | DD78S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-473Z | DD78S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-474F | DD104S1F00C-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-474P | DD104S1F00S-MIL-400.1+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-474Z | DD104S1F000-MIL-403.2+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-491F | RD9S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-491P | RD9S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-491Z | RD9S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-492F | RD15S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-492P | RD15S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-492Z | RD15S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-493F | RD25S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-493P | RD25S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-493Z | RD25S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-494F | RD37S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-494P | RD37S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-494Z | RD37S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-495F | RD50S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-495P | RD50S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-495Z | RD50S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-496F | DD15S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-496P | DD15S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-496Z | DD15S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-497F | DD26S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-497P | DD26S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-497Z | DD26S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-498F | DD44S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-498P | DD44S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-498Z | DD44S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-499F | DD62S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-499P | DD62S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-499Z | DD62S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-500F | DD78S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-500P | DD78S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-500Z | DD78S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-501F | DD104S0S00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-501P | DD104S0S00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-501Z | DD104S0S000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-502 | RD9S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-503 | RD15S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-504 | RD25S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-505 | RD37S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-506 | RD50S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-507 | RD9S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-508 | RD15S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-509 | RD25S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-510 | RD37S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-511 | RD50S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-512 | DD15S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-513 | DD26S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-514 | DD44S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-515 | DD62S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-516 | DD78S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-517 | DD104S10000-MIL-403.3+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-518 | DD15S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-519 | DD26S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-520 | DD44S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-521 | DD62S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-522 | DD78S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-523 | DD104S10000-MIL-403.5+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-540 | RD9S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-541 | RD15S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-542 | RD25S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-543 | RD37S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-544 | RD50S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-545 | DD15S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-546 | DD26S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-547 | DD44S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-548 | DD62S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-549 | DD78S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-550 | DD104S00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-551 | RD9S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-552 | RD15S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-553 | RD25S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-554 | RD37S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-555 | RD50S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-556 | DD15S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-557 | DD26S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-558 | DD44S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-559 | DD62S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-560 | DD78S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-561 | DD104S1F000-MIL-403.4+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-562 | RD9S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-563 | RD15S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-564 | RD25S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-565 | RD37S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-566 | RD50S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-567 | DD15S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-568 | DD26S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-569 | DD44S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-570 | DD62S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-571 | DD78S1F000-MIL-403.6+ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-572 | DD104S1F000-MIL-403.6++ | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-573 | RD9S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-574 | RD15S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-575 | RD25S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-576 | RD37S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-577 | RD50S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-578 | DD15S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-579 | DD26S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-580 | DD44S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-581 | DD62S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-582 | DD78S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-583 | DD104S0S000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/6-1F | 8630-09S011NMA | 24308-169-77 | Souriau |
| M24308/6-1Z | 8630-09S011NMA | 24308-169-77 | Souriau |
| M24308/6-2F | 8630-15S011NMA | 24308-169-77 | Souriau |
| M24308/6-2Z | 8630-15S011NMA | 24308-169-77 | Souriau |
| M24308/6-3F | 8630-25S011NMA | 24308-169-77 | Souriau |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-3Z | 8630-25S011NMA | 24308-169-77 | Souriau |
| M24308/6-4F | 8630-37S011NMA | 24308-169-77 | Souriau |
| M24308/6-4Z | 8630-37S011NMA | 24308-169-77 | Souriau |
| M24308/6-5F | 8630-50S011NMA | 24308-169-77 | Souriau |
| M24308/6-5Z | 8630-50S011NMA | 24308-169-77 | Souriau |
| M24308/6-6F | 8630-09ST011NMA | 24308-169-77 | Souriau |
| M24308/6-6Z | 8630-09ST011NMA | 24308-169-77 | Souriau |
| M24308/6-7F | 8630-15ST011NMA | 24308-169-77 | Souriau |
| M24308/6-7Z | 8630-15ST011NMA | 24308-169-77 | Souriau |
| M24308/6-8F | 8630-25ST011NMA | 24308-169-77 | Souriau |
| M24308/6-8Z | 8630-25ST011NMA | 24308-169-77 | Souriau |
| M24308/6-9F | 8630-25ST011NMA | 24308-169-77 | Souriau |
| M24308/6-9Z | 8630-37ST011NMA | 24308-169-77 | Souriau |
| M24308/6-10F | 8630-50ST011NMA | 24308-169-77 | Souriau |
| M24308/6-10Z | 8630-50ST011NMA | 24308-169-77 | Souriau |
| M24308/6-259F | 8631-09S011NMA | 24308-309-79 | Souriau |
| M24308/6-259Z | 8631-09S011NMA | 24308-309-79 | Souriau |
| M24308/6-260Z | 8631-15S011NMA | 24308-309-79 | Souriau |
| M24308/6-261F | 8631-25S011NMA | 24308-309-79 | Souriau |
| M24308/6-261Z | 8631-25S011NMA | 24308-309-79 | Souriau |
| M24308/6-262F | 8631-37S011NMA | 24308-309-79 | Souriau |
| M24308/6-262Z | 8631-37S011NMA | 24308-309-79 | Souriau |
| M24308/6-263F | 8631-50S011NMA | 24308-309-79 | Souriau |
| M24308/6-263Z | 8631-50S011NMA | 24308-309-79 | Souriau |
| M24308/6-324 | 8631-09S011NMAL | 24308-309-79 | Souriau |
| M24308/6-324F | 8631-09S011NMAL | 24308-309-79 | Souriau |
| M24308/6-325 | 8631-15S011NMAL | 24308-309-79 | Souriau |
| M24308/6-325F | 8631-15S011NMAL | 24308-309-79 | Souriau |
| M24308/6-326 | 8631-25S011NMAL | 24308-169-77 | Souriau |
| M24308/6-326F | 8631-25S011NMAL | 24308-309-79 | Souriau |
| M24308/6-327 | 8631-37S011NMAL | 24308-309-79 | Souriau |
| M24308/6-327F | 8631-37S011NMAL | 24308-309-79 | Souriau |
| M24308/6-328 | 8631-50S011NMAL | 24308-309-79 | Souriau |
| M24308/6-328F | 8631-50S011NMAL | 24308-309-79 | Souriau |
| M24308/6-453F | 8631-09S911NMA | 24308-1042-82 | Souriau |
| M24308/6-453Z | 8631-09S911NMA | 24308-1042-82 | Souriau |
| M24308/6-454F | 8631-15S011NMA | 24308-1042-82 | Souriau |
| M24308/6-454Z | 8631-15S011NMA | 24308-1042-82 | Souriau |
| M24308/6-455F | 8631-25S011NMA | 24308-1042-82 | Souriau |
| M24308/6-455Z | 8631-25S011NMA | 24308-1042-82 | Souriau |
| M24308/6-456F | 8631-37S011NMA | 24308-1042-82 | Souriau |
| M24308/6-456Z | 8631-37S011NMA | 24308-1042-82 | Souriau |
| M24308/6-457F | 8631-50S011NMA | 24308-1042-82 | Souriau |
| M24308/6-457Z | 8631-50S011NMA | 24308-1042-82 | Souriau |
| M24308/6-464F | 8631-09ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-464Z | 8631-09ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-465F | 8631-15ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-465Z | 8631-15ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-466F | 8631-25ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-466Z | 8631-25ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-467F | 8631-37ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-467Z | 8631-37ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-468F | 8631-50ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-468Z | 8631-50ST011NMA | 24308-1042-82 | Souriau |
| M24308/6-491F | 8631-09S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-491Z | 8631-09S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-492F | 8631-09S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-492Z | 863115S011NMAL | 24308-1042-82 | Souriau |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-493F | 8631-25S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-493Z | 8631-25S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-494F | 8631-37S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-494Z | 8631-37S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-495F | 8631-50S011NMAL | 24308-1042-82 | Souriau |
| M24308/6-502 | 8630-09S011NM | 24308-072-99 | Souriau |
| M24308/6-503 | 8630-15S011NM | 24308-072-99 | Souriau |
| M24308/6-504 | 8630-25S011NM | 24308-072-99 | Souriau |
| M24308/6-505 | 8630-37S011NM | 24308-072-99 | Souriau |
| M24308/6-506 | 8630-50S011NM | 24308-072-99 | Souriau |
| M24308/6-507 | 8630-09ST011NMA | 24308-072-99 | Souriau |
| M24308/6-508 | 8630-15ST011NMA | 24308-072-99 | Souriau |
| M24308/6-509 | 8630-25ST011NMA | 24308-072-99 | Souriau |
| M24308/6-510 | 8630-37ST011NMA | 24308-072-99 | Souriau |
| M24308/6-511 | 8630-50ST011NMA | 24308-072-99 | Souriau |
| M24308/6-540 | 8630-09STNM | 24308-072-99 | Souriau |
| M24308/6-541 | 8630-15STNM | 24308-072-99 | Souriau |
| M24308/6-542 | 8630-25STNM | 24308-072-99 | Souriau |
| M24308/6-543 | 8630-37STNM | 24308-072-99 | Souriau |
| M24308/6-544 | 8630-50STNM | 24308-072-99 | Souriau |
| M24308/6-1F | 593039-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-2F | 593039-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-3F | 593039-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-4F | 593039-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-5F | 593039-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-6F | 593040-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-7F | 593040-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-8F | 593040-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-9F | 593040-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-10F | 593040-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-259F | 593043-1 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-260F | 593043-2 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-261F | 593043-3 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-262F | 593043-4 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-263F | 593043-5 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-270F | 593045-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-271F | 593045-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-272F | 593045-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-273F | 593045-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-274F | 593045-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/6-281F | 593047-1 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-282F | 593047-2 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-283F | 593047-3 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-284F | 593047-4 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-285F | 593047-5 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-286F | 593048-1 | 24308-642-73 | Tyco Electronics |
| M24308/6-287F | 593048-2 | 24308-642-73 | Tyco Electronics |
| M24308/6-288F | 593048-3 | 24308-642-73 | Tyco Electronics |
| M24308/6-289F | 593048-4 | 24308-642-73 | Tyco Electronics |
| M24308/6-290F | 593048-5 | 24308-642-73 | Tyco Electronics |
| M24308/6-324F | 593049-1 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-325F | 593049-2 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-326F | 593049-3 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-327F | 593049-4 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-328F | 593049-5 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-329F | 593050-1 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-330F | 593050-2 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-331F | 593050-3 | 1140, 24 MAY 69 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/6-332F | 593050-4 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-333F | 593050-5 | 1140, 24 MAY 69 | Tyco Electronics |
| M24308/6-453F | 593051-1 | 24308-36-82 | Tyco Electronics |
| M24308/6-454F | 593051-2 | 24308-36-82 | Tyco Electronics |
| M24308/6-455F | 593051-3 | 24308-36-82 | Tyco Electronics |
| M24308/6-456F | 593051-4 | 24308-36-82 | Tyco Electronics |
| M24308/6-457F | 593051-5 | 24308-36-82 | Tyco Electronics |
| M24308/6-464F | 593053-1 | 24308-36-82 | Tyco Electronics |
| M24308/6-465F | 593053-2 | 24308-36-82 | Tyco Electronics |
| M24308/6-466F | 593053-3 | 24308-36-82 | Tyco Electronics |
| M24308/6-467F | 593053-4 | 24308-36-82 | Tyco Electronics |
| M24308/6-468F | 593053-5 | 24308-36-82 | Tyco Electronics |
| M24308/6-491F | 593055-1 | 24308-36-82 | Tyco Electronics |
| M24308/6-492F | 593055-2 | 24308-36-82 | Tyco Electronics |
| M24308/6-493F | 593055-3 | 24308-36-82 | Tyco Electronics |
| M24308/6-494F | 593055-4 | 24308-36-82 | Tyco Electronics |
| M24308/6-495F | 593055-5 | 24308-36-82 | Tyco Electronics |
| M24308/6-496F | 593056-1 | 24308-36-82 | Tyco Electronics |
| M24308/6-497F | 593056-2 | 24308-36-82 | Tyco Electronics |
| M24308/6-498F | 593056-3 | 24308-36-82 | Tyco Electronics |
| M24308/6-499F | 593056-4 | 24308-36-82 | Tyco Electronics |
| M24308/6-500F | 593056-5 | 24308-36-82 | Tyco Electronics |
| M24308/7-1F | M2000/7-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-1Z | M2000/7-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-2F | M2000/7-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-2Z | M2000/7-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-3F | M2000/7-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-3Z | M2000/7-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-4F | M2000/7-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-4Z | M2000/7-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-5F | M2000/7-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-5Z | M2000/7-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-12F | M2000/7-12F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-12Z | M2000/7-12Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-13F | M2000/7-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-13Z | M2000/7-13Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-14F | M2000/7-14F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-14Z | M2000/7-14Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-15F | M2000/7-15F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-15Z | M2000/7-15Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-16F | M2000/7-16F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-16Z | M2000/7-16Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-17F | M2000/7-17F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-17Z | M2000/7-17Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-18F | M2000/7-18F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-18Z | M2000/7-18Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-19F | M2000/7-19F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-19Z | M2000/7-19Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-20F | M2000/7-20F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-20Z | M2000/7-20Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-21F | M2000/7-21F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-21Z | M2000/7-21Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-23 | M2000/7-23 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-24 | M2000/7-24 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-25 | M2000/7-25 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-26 | M2000/7-26 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-27 | M2000/7-27 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/7-34 | M2000/7-34 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-35 | M2000/7-35 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-36 | M2000/7-36 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-37 | M2000/7-37 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-38 | M2000/7-38 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-39 | M2000/7-39 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-40 | M2000/7-40 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-41 | M2000/7-41 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-42 | M2000/7-42 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-43 | M2000/7-43 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/7-23 | 115372-2000 | | C&K Components SAS |
| M24308/7-24 | 115372-2002 | 24308-3535-12 | C&K Components SAS |
| M24308/7-25 | 115372-2004 | 24308-3535-12 | C&K Components SAS |
| M24308/7-26 | 115372-2006 | 24308-3535-12 | C&K Components SAS |
| M24308/7-27 | 115372-2008 | 24308-3535-12 | C&K Components SAS |
| M24308/7-39 | 115372-2050 | 24308-3535-12 | C&K Components SAS |
| M24308/7-40 | 115372-2052 | 24308-3535-12 | C&K Components SAS |
| M24308/7-41 | 115372-2054 | 24308-3535-12 | C&K Components SAS |
| M24308/7-42 | 115372-2056 | 24308-3535-12 | C&K Components SAS |
| M24308/7-43 | 115372-2058 | 24308-3535-12 | C&K Components SAS |
| M24308/7-1F | DEG9P2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/7-2F | DAG15P2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/7-3F | DBG25P2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/7-4F | DCG37P2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/7-5F | DDG50P2B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/7-1F | HDC9M2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-1P | HDC9M2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-1Z | HDC9M20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-2F | HDC15M2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-2P | HDC15M2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-2Z | HDC15M20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-3F | HDC25M2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-3P | HDC25M2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-3Z | HDC25M20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-4F | HDC37M2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-4P | HDC37M2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-4Z | HDC37M20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-5F | HDC50M2000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-5P | HDC50M2000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-5Z | HDC50M20000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-12F | HDC9M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-12P | HDC9M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-12Z | HDC9M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-13F | HDC15M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-13P | HDC15M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-13Z | HDC15M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-14F | HDC25M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-14P | HDC25M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-14Z | HDC25M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-15F | HDC37M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-15P | HDC37M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-15Z | HDC37M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-16F | HDC50M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-16P | HDC50M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-16Z | HDC50M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-17F | HDC9M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-17P | HDC9M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/7-17Z | HDC9M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-18F | HDC15M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-18P | HDC15M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-18Z | HDC15M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-19F | HDC25M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-19P | HDC25M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-19Z | HDC25M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-20F | HDC37M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-20P | HDC37M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-20Z | HDC37M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-21F | HDC50M2F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-21P | HDC50M2F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-21Z | HDC50M2F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-23 | HDC9M20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-24 | HDC15M20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-25 | HDC25M20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-26 | HDC37M20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-27 | HDC50M20000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-34 | HDC9M2F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-35 | HDC15M2F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-36 | HDC25M2F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-37 | HDC37M2F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-38 | HDC50M2F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/7-23 | DEM9P011NM | 24308-072-99 | Souriau |
| M24308/7-24 | DAM15P011NM | 24308-072-99 | Souriau |
| M24308/7-25 | DBM25P011NM | 24308-072-99 | Souriau |
| M24308/7-26 | DCM37P011NM | 24308-072-99 | Souriau |
| M24308/7-27 | DDM50P011NM | 24308-072-99 | Souriau |
| M24308/8-338 | 115370-1706 | 24308-3535-12 | |
| M24308/8-1F | M2000/8-1F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-1Z | M2000/8-1Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-2F | M2000/8-2F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-2Z | M2000/8-2Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-3F | M2000/8-3F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-3Z | M2000/8-3Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-4F | M2000/8-4F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-4Z | M2000/8-4Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-5F | M2000/8-5F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-5Z | M2000/8-5Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-6F | M2000/8-6F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-6Z | M2000/8-6Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-7F | M2000/8-7F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-7Z | M2000/8-7Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-8F | M2000/8-8F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-8Z | M2000/8-8Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-9F | M2000/8-9F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-9Z | M2000/8-9Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-10F | M2000/8-10F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-10Z | M2000/8-10Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-11F | M2000/8-11F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-11Z | M2000/8-11Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-12F | M2000/8-12F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-12Z | M2000/8-12Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-13F | M2000/8-13F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-13Z | M2000/8-13Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-14F | M2000/8-14F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-14Z | M2000/8-14Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-15F | M2000/8-15F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-15Z | M2000/8-15Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-16F | M2000/8-16F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-16Z | M2000/8-16Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-17F | M2000/8-17F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-17Z | M2000/8-17Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-18F | M2000/8-18F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-18Z | M2000/8-18Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-19F | M2000/8-19F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-19Z | M2000/8-19Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-20F | M2000/8-20F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-20Z | M2000/8-20Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-21F | M2000/8-21F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-21Z | M2000/8-21Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-22F | M2000/8-22F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-22Z | M2000/8-22Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-259F | M2000/8-259F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-259Z | M2000/8-259Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-260F | M2000/8-260F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-260Z | M2000/8-260Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-261F | M2000/8-261F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-261Z | M2000/8-261Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-262F | M2000/8-262F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-262Z | M2000/8-262Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-263F | M2000/8-263F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-263Z | M2000/8-263Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-264F | M2000/8-264F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-264Z | M2000/8-264Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-265F | M2000/8-265F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-265Z | M2000/8-265Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-266F | M2000/8-266F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-266Z | M2000/8-266Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-267F | M2000/8-267F | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-267Z | M2000/8-267Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-268F | M2000/8-268 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-268Z | M2000/8-268Z | 24308-3160-11 | Amphenol Interconnect India PVT LTD |
| M24308/8-269F | M2000/8-269F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-269Z | M2000/8-269Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-302F | M2000/8-302F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-302Z | M2000/8-302Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-303F | M2000/8-303F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-303Z | M2000/8-303Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-304F | M2000/8-304F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-304Z | M2000/8-304Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-305F | M2000/8-305F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-305Z | M2000/8-305Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-306F | M2000/8-306F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-306Z | M2000/8-306Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-307F | M2000/8-307F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-307Z | M2000/8-307Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-308F | M2000/8-308F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-308Z | M2000/8-308Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-309F | M2000/8-309F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-309Z | M2000/8-309Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-310F | M2000/8-310F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-310Z | M2000/8-310Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-311F | M2000/8-311F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-311Z | M2000/8-311Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-312F | M2000/8-312F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-312Z | M2000/8-312Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-313F | M2000/8-313F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-313Z | M2000/8-313Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-314F | M2000/8-314F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-314Z | M2000/8-314Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-315F | M2000/8-315F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-315Z | M2000/8-315Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-316F | M2000/8-316F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-316Z | M2000/8-316Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-317F | M2000/8-317F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-317Z | M2000/8-317Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-318F | M2000/8-318F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-318Z | M2000/8-318Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-319F | M2000/8-319F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-319Z | M2000/8-319Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-320F | M2000/8-320F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-320Z | M2000/8-320Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-321F | M2000/8-321F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-321Z | M2000/8-321Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-322F | M2000/8-322F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-322Z | M2000/8-322Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-323F | M2000/8-323F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-323Z | M2000/8-323Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-324F | M2000/8-324F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-324Z | M2000/8-324Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-325F | M2000/8-325F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-325Z | M2000/8-325Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-326F | M2000/8-326F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-326Z | M2000/8-326Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-327F | M2000/8-327F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-327Z | M2000/8-327Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-328F | M2000/8-328F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-328Z | M2000/8-328Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-329F | M2000/8-329F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-329Z | M2000/8-329Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-330F | M2000/8-330F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-330Z | M2000/8-330Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-331F | M2000/8-331F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-331Z | M2000/8-331Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-332F | M2000/8-332F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-332Z | M2000/8-332Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-333F | M2000/8-333F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-333Z | M2000/8-333Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-334F | M2000/8-334F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-334Z | M2000/8-334Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-335 | M2000/8-335 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-336 | M2000/8-336 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-337 | M2000/8-337 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-338 | M2000/8-338 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-339 | M2000/8-339 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-340 | M2000/8-340 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-341 | M2000/8-341 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-342 | M2000/8-342 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-343 | M2000/8-343 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-344 | M2000/8-344 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-345 | M2000/8-345 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-346 | M2000/8-346 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-347 | M2000/8-347 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-348 | M2000/8-348 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-349 | M2000/8-349 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-350 | M2000/8-350 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-351 | M2000/8-351 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-352 | M2000/8-352 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-353 | M2000/8-353 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-354 | M2000/8-354 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-355 | M2000/8-355 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-356 | M2000/8-356 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-357 | M2000/8-357 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-358 | M2000/8-358 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-359 | M2000/8-359 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-360 | M2000/8-360 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-361 | M2000/8-361 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-362 | M2000/8-362 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-363 | M2000/8-363 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-364 | M2000/8-364 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-365 | M2000/8-365 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-366 | M2000/8-366 | 24308-2934-10 | Amphenol Interconnect India PVT LTD |
| M24308/8-367 | M2000/8-367 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-368 | M2000/8-368 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-369 | M2000/8-369 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-370 | M2000/8-370 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-371 | M2000/8-371 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-372 | M2000/8-372 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-373 | M2000/8-373 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-374 | M2000/8-374 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-375 | M2000/8-375 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-376 | M2000/8-376 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-377 | M2000/8-377 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-378 | M2000/8-378 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-379 | M2000/8-379 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-380 | M2000/8-380 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-381 | M2000/8-381 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-382 | M2000/8-382 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-383 | M2000/8-383 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-384 | M2000/8-384 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-385 | M2000/8-385 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-386 | M2000/8-386 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-387 | M2000/8-387 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-388 | M2000/8-388 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-389 | M2000/8-389 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-390 | M2000/8-390 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-391 | M2000/8-391 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-392 | M2000/8-392 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-393 | M2000/8-393 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-394 | M2000/8-394 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-395 | M2000/8-395 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-396 | M2000/8-396 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-397 | M2000/8-397 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-398 | M2000/8-398 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-399 | M2000/8-399 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-400 | M2000/8-400 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-401 | M2000/8-401 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-402 | M2000/8-402 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-403 | M2000/8-403 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-404 | M2000/8-404 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-405 | M2000/8-405 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-406 | M2000/8-406 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-407 | M2000/8-407 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-408 | M2000/8-408 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-409 | M2000/8-409 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-410 | M2000/8-410 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-411 | M2000/8-411 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-412 | M2000/8-412 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-413 | M2000/8-413 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-414 | M2000/8-414 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-415 | M2000/8-415 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-416 | M2000/8-416 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-417 | M2000/8-417 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-418 | M2000/8-418 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-419 | M2000/8-419 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-420 | M2000/8-420 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-421 | M2000/8-421 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-422 | M2000/8-422 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-423 | M2000/8-423 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-424 | M2000/8-424 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-425 | M2000/8-425 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-426 | M2000/8-426 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-427 | M2000/8-427 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-428 | M2000/8-428 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-429 | M2000/8-429 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-430 | M2000/8-430 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-431 | M2000/8-431 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-432 | M2000/8-432 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-433 | M2000/8-433 | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-435F | M2000/8-435F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-435Z | M2000/8-435Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-436F | M2000/8-436F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-436Z | M2000/8-436Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-437F | M2000/8-437F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-437Z | M2000/8-437Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-438F | M2000/8-438F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-438Z | M2000/8-438Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-439F | M2000/8-439F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-439Z | M2000/8-439Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-440F | M2000/8-440F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-440Z | M2000/8-440Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-441F | M2000/8-441F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-441Z | M2000/8-441Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-442F | M2000/8-442F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-442Z | M2000/8-442Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-443F | M2000/8-443F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-443Z | M2000/8-443Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-444F | M2000/8-444F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-444Z | M2000/8-444Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-445F | M2000/8-445F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-445Z | M2000/8-445Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-446F | M2000/8-446F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-446Z | M2000/8-446Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-447F | M2000/8-447F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-447Z | M2000/8-447Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-448F | M2000/8-448F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-448Z | M2000/8-448Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-449F | M2000/8-449F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-449Z | M2000/8-449Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-450F | M2000/8-450F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-450Z | M2000/8-450Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-451F | M2000/8-451F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-451Z | M2000/8-451Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-452F | M2000/8-452F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-452Z | M2000/8-452Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-453F | M2000/8-453F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-453Z | M2000/8-453Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-454F | M2000/8-454F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-454Z | M2000/8-454Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-455F | M2000/8-455F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-455Z | M2000/8-455Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-456F | M2000/8-456F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-456Z | M2000/8-456Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-457F | M2000/8-457F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-457Z | M2000/8-457Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-458F | M2000/8-458F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-458Z | M2000/8-458Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-459F | M2000/8-459F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-459Z | M2000/8-459Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-460F | M2000/8-460F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-460Z | M2000/8-460Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-461F | M2000/8-461F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-461Z | M2000/8-461Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-462F | M2000/8-462F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-462Z | M2000/8-462Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-463F | M2000/8-463F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-463Z | M2000/8-463Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-464F | M2000/8-464F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-464Z | M2000/8-464Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-465F | M2000/8-465F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-465Z | M2000/8-465Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-466F | M2000/8-466F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-466Z | M2000/8-466Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-467F | M2000/8-467F | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-467Z | M2000/8-467Z | 24308-5114-18 | Amphenol Interconnect India PVT LTD |
| M24308/8-336 | 115370-1702 | 24308-3535-12 | C&K Components SAS |
| M24308/8-337 | 115370-1704 | 24308-3535-12 | C&K Components SAS |
| M24308/8-339 | 115370-1708 | 24308-3535-12 | C&K Components SAS |
| M24308/8-345 | C115368-1600 | 24308-3535-12 | C&K Components SAS |
| M24308/8-346 | C115368-1602 | 24308-3535-12 | C&K Components SAS |
| M24308/8-347 | C115368-1604 | 24308-3535-12 | C&K Components SAS |
| M24308/8-348 | C115368-1606 | 24308-3535-12 | C&K Components SAS |
| M24308/8-349 | C115368-1608 | 24308-3535-12 | C&K Components SAS |
| M24308/8-335 | 115370-1700 | 24308-3535-12 | C&K Components SAS |
| M24308/8-357 | 115370-1710 | 24308-3535-12 | C&K Components SAS |
| M24308/8-358 | 115370-1712 | 24308-3535-12 | C&K Components SAS |
| M24308/8-359 | 115370-1714 | 24308-3535-12 | C&K Components SAS |
| M24308/8-360 | 115370-1716 | 24308-3535-12 | C&K Components SAS |
| M24308/8-361 | 115370-1718 | 24308-3535-12 | C&K Components SAS |
| M24308/8-362 | C115368-1610 | 24308-3535-12 | C&K Components SAS |
| M24308/8-363 | C115368-1612 | 24308-3535-12 | C&K Components SAS |
| M24308/8-364 | C115368-1614 | 24308-3535-12 | C&K Components SAS |
| M24308/8-365 | C115368-1616 | 24308-3535-12 | C&K Components SAS |
| M24308/8-366 | C115368-1618 | 24308-3535-12 | C&K Components SAS |
| M24308/8-401 | 115370-1720 | 24308-3535-12 | C&K Components SAS |
| M24308/8-402 | 115370-1722 | 24308-3535-12 | C&K Components SAS |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-403 | 115370-1724 | 24308-3535-12 | C&K Components SAS |
| M24308/8-404 | 115370-1726 | 24308-3535-12 | C&K Components SAS |
| M24308/8-405 | 115370-1728 | 24308-3535-12 | C&K Components SAS |
| M24308/8-406 | C115368-1620 | 24308-3535-12 | C&K Components SAS |
| M24308/8-407 | C115368-1622 | 24308-3535-12 | C&K Components SAS |
| M24308/8-408 | C115368-1624 | 24308-3535-12 | C&K Components SAS |
| M24308/8-409 | C115368-1626 | 24308-3535-12 | C&K Components SAS |
| M24308/8-410 | C115368-1628 | 24308-3535-12 | C&K Components SAS |
| M24308/8-423 | 115370-1730 | 24308-3535-12 | C&K Components SAS |
| M24308/8-424 | 115370-1732 | 24308-3535-12 | C&K Components SAS |
| M24308/8-425 | 115370-1734 | 24308-3535-12 | C&K Components SAS |
| M24308/8-426 | 115370-1736 | 24308-3535-12 | C&K Components SAS |
| M24308/8-427 | 115370-1738 | 24308-3535-12 | C&K Components SAS |
| M24308/8-428 | C115368-1630 | 24308-3535-12 | C&K Components SAS |
| M24308/8-429 | C115368-1632 | 24308-3535-12 | C&K Components SAS |
| M24308/8-431 | C115368-1636 | 24308-3535-12 | C&K Components SAS |
| M24308/8-432 | C115368-1638 | 24308-3535-12 | C&K Components SAS |
| M24308/8-430 | C115368-1634 | 24308-3535-12 | C&K Components SAS |
| M24308/8-1F | DEG9P1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-2F | DAG15P1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-3F | DBG25P1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-4F | DCG37P1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-5F | DDG50P1B | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-259F | DEG9P1BNO | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-260F | DAG15P1BNO | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-261F | DBG25P1BNO | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-262F | DCG37P1BNO | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-263F | DDG50P1BNO | 24308-160-92; 24308-281-93 | Cristek Interconnects, Inc. |
| M24308/8-1F | RD9M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-1P | RD9M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-1Z | RD9M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-2F | RD15M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-2P | RD15M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-2Z | RD15M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-3F | RD25M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-3P | RD25M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-3Z | RD25M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-4F | RD37M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-4P | RD37M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-4Z | RD37M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-5F | RD50M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-5P | RD50M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-5Z | RD50M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-6F | RD9M1000C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-6P | RD9M1000S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-6Z | RD9M10000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-7F | RD15M1000C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-7P | RD15M1000S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-7Z | RD15M10000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-8F | RD25M1000C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-8P | RD25M1000S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-8Z | RD25M10000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-9F | RD37M1000C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-9P | RD37M1000S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-9Z | RD37M10000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-10F | RD50M1000C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-10P | RD50M1000S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-10Z | RD50M10000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-11F | DD15M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-11P | DD15M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-11Z | DD15M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-12F | DD26M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-12P | DD26M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-12Z | DD26M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-13F | DD44M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-13P | DD44M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-13Z | DD44M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-14F | DD62M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-14P | DD62M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-14Z | DD62M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-15F | DD78M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-15P | DD78M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-15Z | DD78M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-16F | DD104M1000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-16P | DD104M1000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-16Z | DD104M10000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-17F | DD15M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-17P | DD15M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-17Z | DD15M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-18F | DD26M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-18P | DD26M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-18Z | DD26M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-19F | DD44M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-19P | DD44M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-19Z | DD44M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-20F | DD62M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-20P | DD62M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-20Z | DD62M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-21F | DD78M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-21P | DD78M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-21Z | DD78M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-22F | DD104M1000C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-22P | DD104M1000S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-22Z | DD104M10000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-259F | RD9M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-259P | RD9M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-259Z | RD9M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-260F | RD15M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-260P | RD15M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-260Z | RD15M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-261F | RD25M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-261P | RD25M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-261Z | RD25M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-262F | RD37M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-262P | RD37M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-262Z | RD37M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-263F | RD50M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-263P | RD50M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-263Z | RD50M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-264F | DD15M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-264P | DD15M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-264Z | DD15M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-265F | DD26M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-265P | DD26M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-265Z | DD26M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-266F | DD44M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-266P | DD44M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-266Z | DD44M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-267F | DD62M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-267P | DD62M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-267Z | DD62M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-268F | DD78M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-268P | DD78M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-268Z | DD78M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-269F | DD104M0000C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-269P | DD104M0000S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-269Z | DD104M00000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-335 | RD9M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-336 | RD15M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-337 | RD25M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-338 | RD37M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-339 | RD50M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-340 | RD9M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-341 | RD15M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-342 | RD25M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-343 | RD37M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-344 | RD50M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-345 | DD15M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-346 | DD26M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-347 | DD44M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-348 | DD62M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-349 | DD78M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-350 | DD104M10000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-351 | DD15M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-352 | DD26M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-353 | DD44M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-354 | DD62M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-355 | DD78M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-356 | DD104M10000-MIL-403.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-357 | RD9M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-358 | RD15M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-359 | RD25M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-360 | RD37M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-361 | RD50M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-362 | DD15M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-363 | DD26M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-364 | DD44M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-365 | DD62M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-366 | DD78M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-367 | DD104M00000-MIL-403.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-401 | RD9M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-402 | RD15M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-403 | RD25M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-404 | RD37M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-405 | RD50M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-406 | DD15M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-407 | DD26M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-408 | DD44M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-409 | DD62M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-410 | DD78M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-411 | DD104M1F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-412 | RD9M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-413 | RD15M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-414 | RD25M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-415 | RD37M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-416 | RD50M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-417 | DD15M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-418 | DD26M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-419 | DD44M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-420 | DD62M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-421 | DD78M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-422 | DD104M1F000-MIL-403.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-423 | RD9M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-424 | RD15M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-425 | RD25M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-426 | RD37M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-427 | RD50M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-428 | DD15M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-429 | DD26M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-430 | DD44M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-431 | DD62M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-432 | DD78M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-433 | DD104M0F000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-435F | RD9M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-435P | RD9M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-435Z | RD9M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-436F | RD15M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-436P | RD15M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-436Z | RD15M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-437F | RD25M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-437P | RD25M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-437Z | RD25M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-438F | RD37M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-438P | RD37M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-438Z | RD37M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-439F | RD50M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-439P | RD50M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-439Z | RD50M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-440F | DD15M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-440P | DD15M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-440Z | DD15M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-441F | DD26M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-441P | DD26M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-441Z | DD26M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-442F | DD44M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-442P | DD44M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-442Z | DD44M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-443F | DD62M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-443P | DD62M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-443Z | DD62M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-444F | DD78M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-444P | DD78M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-444Z | DD78M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-445F | DD104M1F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-445P | DD104M1F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-445Z | DD104M1F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-446F | RD9M1F00C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-446P | RD9M1F00S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-446Z | RD9M1F000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-447F | RD15M1F00C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-447P | RD15M1F00S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-447Z | RD15M1F000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-448F | RD25M1F00C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-448P | RD25M1F00S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-448Z | RD25M1F000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-449F | RD37M1F00C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-449P | RD37M1F00S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-449Z | RD37M1F000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-450F | RD50M1F00C-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-450P | RD50M1F00S-MIL-400.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-450Z | RD50M1F000-MIL-403.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-451F | DD15M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-451P | DD15M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-451Z | DD15M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-452F | DD26M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-452P | DD26M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-452Z | DD26M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-453F | DD44M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-453P | DD44M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-453Z | DD44M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-454F | DD62M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-454P | DD62M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-454Z | DD62M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-455F | DD78M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-455P | DD78M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-455Z | DD78M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-456F | DD104M1F00C-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-456P | DD104M1F00S-MIL-400.1 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-456Z | DD104M1F000-MIL-403.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-457F | RD9M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-457P | RD9M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-457Z | RD9M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-458F | RD15M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-458P | RD15M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-458Z | RD15M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-459F | RD25M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-459P | RD25M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-459Z | RD25M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-460F | RD37M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-460P | RD37M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-460Z | RD37M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-461F | RD50M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-461P | RD50M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-461Z | RD50M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-462F | DD15M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-462P | DD15M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-462Z | DD15M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-463F | DD26M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-463P | DD26M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-463Z | DD26M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-464F | DD44M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-464P | DD44M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-464Z | DD44M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-465F | DD62M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-465P | DD62M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-465Z | DD62M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-466F | DD78M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-466P | DD78M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-466Z | DD78M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/8-467F | DD104M0F00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-467P | DD104M0F00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-467Z | DD104M0F000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/8-335 | 8630-09P011NM | 24308-072-99 | Souriau |
| M24308/8-336 | 8630-15P011NM | 24308-072-99 | Souriau |
| M24308/8-337 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-338 | 8630-37P011NM | 24308-072-99 | Souriau |
| M24308/8-339 | 8630-50P011NM | 24308-072-99 | Souriau |
| M24308/8-340 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-341 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-342 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-343 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-344 | 8630-25P011NM | 24308-072-99 | Souriau |
| M24308/8-1F | 593059-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-2F | 593059-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-3F | 593059-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-4F | 593059-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-5F | 593059-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-6F | 593060-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-7F | 593060-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-8F | 593060-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-9F | 593060-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-10F | 593060-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-302F | 593065-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-303F | 593065-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-304F | 593065-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-305F | 593065-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-306F | 593065-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-313F | 593067-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-314F | 593067-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-315F | 593067-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-316F | 593067-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-317F | 593067-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-324F | 593069-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-325F | 593069-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-326F | 593069-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-327F | 593069-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-328F | 593069-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-329F | 593070-1 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-330F | 593070-2 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-331F | 593070-3 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-332F | 593070-4 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/8-333F | 593070-5 | 1140, 23 MAY 69 | Tyco Electronics |
| M24308/9-1 | 280-006H1AP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-2 | 280-006H2AP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-3 | 280-006H3AP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-4 | 280-006H4AP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-5 | 280-006H5AP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-6 | 280-006H1AX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-7 | 280-006H2AX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-8 | 280-006H3AX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-9 | 280-006H4AX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-10 | 280-006H5AX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-11 | 280-006H1BP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-12 | 280-006H2BP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-13 | 280-006H3BP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-14 | 280-006H4BP | 24308-1356-05 | Glenair, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/9-15 | 280-006H5BP | 24308-1356-05 | Glenair, Inc. |
| M24308/9-16 | 280-006H1BX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-17 | 280-006H2BX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-18 | 280-006H3BX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-19 | 280-006H4BX | 24308-1356-05 | Glenair, Inc. |
| M24308/9-20 | 280-006H5BX | 24308-1356-05 | Glenair, Inc. |
| M24308/23-1F | GPM-C10S-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-1Z | GPM-Z10S-00009S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-2F | GPM-C10S-000015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-2Z | GPM-Z10S-000015S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-3F | GPM-C10S-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-3Z | GPM-Z10S-00025S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-4F | GPM-C10S-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-4Z | GPM-Z10S-00037S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-5F | GPM-C10S-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-5Z | GPM-Z10S-00050S-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-7F | GPM-C10S-00009S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-7Z | GPM-Z10S-00009S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-8F | GPM-C10S-00015S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-8Z | GPM-Z10S-00015S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-9F | GPM-C10S-00025S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-9Z | GPM-Z10S-00025S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-10F | GPM-C10S-00037S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-10Z | GPM-Z10S-00037S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-11F | GPM-C10S-00050S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-11Z | GPM-Z10S-00050S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-13F | GPM-C11S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-13Z | GPM-Z11S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-14F | GPM-C11S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-14Z | GPM-Z11S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-15F | GPM-C11S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-15Z | GPM-Z11S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-16F | GPM-C11S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-16Z | GPM-Z11S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-17F | GPM-C11S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-17Z | GPM-Z11S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-19F | GPM-C11S-00009S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-19Z | GPM-Z11S-00009S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-20F | GPM-C10S-00015S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-20Z | GPM-Z11S-00015S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-21F | GPM-C10S-00025S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-21Z | GPM-Z11S-00025S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-22F | GPM-C10S-00037S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-22Z | GPM-Z11S-00037S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-23F | GPM-C10S-00050S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-23Z | GPM-Z11S-00050S-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/23-1F | M2000/23-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-1K | M2000/23-1K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-1Z | M2000/23-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-2F | M2000/23-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-2K | M2000/23-2K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-2Z | M2000/23-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-3F | M2000/23-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-3K | M2000/23-3K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-3Z | M2000/23-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-4F | M2000/23-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-4K | M2000/23-4K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-4Z | M2000/23-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-5F | M2000/23-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-5K | M2000/23-5K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-5Z | M2000/23-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-7F | M2000/23-7F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-7K | M2000/23-7K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-7Z | M2000/23-7Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-8F | M2000/23-8F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-8K | M2000/23-8K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-8Z | M2000/23-8Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-9F | M2000/23-9F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-9K | M2000/23-9K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-9Z | M2000/23-9Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-10F | M2000/23-10F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-10K | M2000/23-10K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-10Z | M2000/23-10Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-11F | M2000/23-11F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-11K | M2000/23-11K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-11Z | M2000/23-11Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-13F | M2000/23-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-13K | M2000/23-13K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-13Z | M2000/23-13Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-14F | M2000/23-14F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-14K | M2000/23-14K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-14Z | M2000/23-14Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-15F | M2000/23-15F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-15K | M2000/23-15K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-15Z | M2000/23-15Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-16F | M2000/23-16F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-16K | M2000/23-16K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-16Z | M2000/23-16Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-17F | M2000/23-17F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-17K | M2000/23-17K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-17Z | M2000/23-17Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-19F | M2000/23-19F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-19K | M2000/23-19K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-19Z | M2000/23-19Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-20F | M2000/23-20F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-20K | M2000/23-20K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-20Z | M2000/23-20Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-21F | M2000/23-21F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-21K | M2000/23-21K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-21Z | M2000/23-21Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-22F | M2000/23-22F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-22K | M2000/23-22K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-22Z | M2000/23-22Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-23F | M2000/23-23F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-23K | M2000/23-23K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-23Z | M2000/23-23Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-25F | M2000/23-25F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-25K | M2000/23-25K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-25Z | M2000/23-25Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-26F | M2000/23-26F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-26K | M2000/23-26K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-26Z | M2000/23-26Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-27F | M2000/23-27F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-27K | M2000/23-27K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-27Z | M2000/23-27Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-28F | M2000/23-28F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-28K | M2000/23-28K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-28Z | M2000/23-28Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-29F | M2000/23-29F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-29K | M2000/23-29K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-29Z | M2000/23-29Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-31F | M2000/23-31F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-31K | M2000/23-31K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-31Z | M2000/23-31Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-32F | M2000/23-32F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-32K | M2000/23-32K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-32Z | M2000/23-32Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-33F | M2000/23-33F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-33K | M2000/23-33K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-33Z | M2000/23-33Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-34F | M2000/23-34F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-34K | M2000/23-34K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-34Z | M2000/23-34Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-35F | M2000/23-35F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-35K | M2000/23-35K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-35Z | M2000/23-35Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-37F | M2000/23-37F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-37K | M2000/23-37K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-37Z | M2000/23-37Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-38F | M2000/23-38F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-38K | M2000/23-38K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-38Z | M2000/23-38Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-39F | M2000/23-39F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-39K | M2000/23-39K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-39Z | M2000/23-39Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-40F | M2000/23-40F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-40K | M2000/23-40K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-40Z | M2000/23-40Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-41F | M2000/23-41F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-41K | M2000/23-41K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-41Z | M2000/23-41Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-43F | M2000/23-43F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-43K | M2000/23-43K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-43Z | M2000/23-43Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-44F | M2000/23-44F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-44K | M2000/23-44K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-44Z | M2000/23-44Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-45F | M2000/23-45F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-45K | M2000/23-45K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-45Z | M2000/23-45Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-46F | M2000/23-46F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-46K | M2000/23-46K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-46Z | M2000/23-46Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-47F | M2000/23-47F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-47K | M2000/23-47K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-47Z | M2000/23-47Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-49F | M2000/23-49F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-49K | M2000/23-49K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-49Z | M2000/23-49Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-50F | M2000/23-50F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-50K | M2000/23-50K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-50Z | M2000/23-50Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-51F | M2000/23-51F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-74Z | M2000/23-74Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-75F | M2000/23-75F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-75K | M2000/23-75K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-75Z | M2000/23-75Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-76F | M2000/23-76F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-76K | M2000/23-76K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-76Z | M2000/23-76Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-77F | M2000/23-77F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-77K | M2000/23-77K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-77Z | M2000/23-77Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-101 | M2000/23-101 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-102 | M2000/23-102 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-103 | M2000/23-103 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-104 | M2000/23-104 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-105 | M2000/23-105 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-107 | M2000/23-107 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-108 | M2000/23-108 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-109 | M2000/23-109 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-110 | M2000/23-110 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-111 | M2000/23-111 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-113 | M2000/23-113 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-114 | M2000/23-114 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-115 | M2000/23-115 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-116 | M2000/23-116 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-117 | M2000/23-117 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-119 | M2000/23-119 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-120 | M2000/23-120 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-121 | M2000/23-121 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-122 | M2000/23-122 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-123 | M2000/23-123 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-125 | M2000/23-125 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-126 | M2000/23-126 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-127 | M2000/23-127 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-128 | M2000/23-128 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-129 | M2000/23-129 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-131 | M2000/23-131 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-132 | M2000/23-132 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-133 | M2000/23-133 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-134 | M2000/23-134 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-135 | M2000/23-135 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-137 | M2000/23-137 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-138 | M2000/23-138 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-139 | M2000/23-139 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-140 | M2000/23-140 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-141 | M2000/23-141 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-143 | M2000/23-143 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-144 | M2000/23-144 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-145 | M2000/23-145 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-146 | M2000/23-146 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-147 | M2000/23-147 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-149 | M2000/23-149 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-150 | M2000/23-150 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-151 | M2000/23-151 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-152 | M2000/23-152 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-153 | M2000/23-153 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-155 | M2000/23-155 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-156 | M2000/23-156 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-157 | M2000/23-157 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-158 | M2000/23-158 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-159 | M2000/23-159 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-161 | M2000/23-161 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-162 | M2000/23-162 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-163 | M2000/23-163 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-164 | M2000/23-164 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-165 | M2000/23-165 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-167 | M2000/23-167 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-168 | M2000/23-168 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-169 | M2000/23-169 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-170 | M2000/23-170 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-171 | M2000/23-171 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-173 | M2000/23-173 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-174 | M2000/23-174 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-175 | M2000/23-175 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-176 | M2000/23-176 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-177 | M2000/23-177 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-201F | M2000/23-201F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-201Z | M2000/23-201Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-202F | M2000/23-202F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-202Z | M2000/23-202Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-203F | M2000/23-203F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-203Z | M2000/23-203Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-204F | M2000/23-204F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-204Z | M2000/23-204Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-205F | M2000/23-205F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-205Z | M2000/23-205Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-207F | M2000/23-207F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-207Z | M2000/23-207Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-208F | M2000/23-208F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-208Z | M2000/23-208Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-209F | M2000/23-209F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-209Z | M2000/23-209Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-210F | M2000/23-210F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-210Z | M2000/23-210Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-211F | M2000/23-211F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-211Z | M2000/23-211Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-213F | M2000/23-213F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-213Z | M2000/23-213Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-214F | M2000/23-214F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-214Z | M2000/23-214Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-215F | M2000/23-215F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-215Z | M2000/23-215Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-216F | M2000/23-216F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-216Z | M2000/23-216Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-217F | M2000/23-217F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-217Z | M2000/23-217Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-219F | M2000/23-219F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-219Z | M2000/23-219Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-220F | M2000/23-220F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-220Z | M2000/23-220Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-221F | M2000/23-221F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-221Z | M2000/23-221Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-222F | M2000/23-222F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-222Z | M2000/23-222Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-223F | M2000/23-223F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-223Z | M2000/23-223Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-225F | M2000/23-225F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-225Z | M2000/23-225Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-226F | M2000/23-226F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-226Z | M2000/23-226Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-227F | M2000/23-227F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-227Z | M2000/23-227Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-228F | M2000/23-228F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-228Z | M2000/23-228Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-229F | M2000/23-229F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-229Z | M2000/23-229Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-231F | M2000/23-231F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-231Z | M2000/23-231Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-232F | M2000/23-232F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-232Z | M2000/23-232Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-233F | M2000/23-233F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-233Z | M2000/23-233Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-234F | M2000/23-234F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-234Z | M2000/23-234Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-235F | M2000/23-235F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-235Z | M2000/23-235Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-237F | M2000/23-237F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-237Z | M2000/23-237Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-238F | M2000/23-238F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-238Z | M2000/23-238Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-239F | M2000/23-239F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-239Z | M2000/23-239Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-240F | M2000/23-240F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-240Z | M2000/23-240Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-241F | M2000/23-241F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-241Z | M2000/23-241Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-243F | M2000/23-243F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-243Z | M2000/23-243Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-244F | M2000/23-244F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-244Z | M2000/23-244Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-245F | M2000/23-245F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-245Z | M2000/23-245Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-246F | M2000/23-246F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-246Z | M2000/23-246Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-247F | M2000/23-247F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-247Z | M2000/23-247Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-249F | M2000/23-249F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-249Z | M2000/23-249Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-250F | M2000/23-250F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-250Z | M2000/23-250Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-251F | M2000/23-251F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-251Z | M2000/23-251Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-252F | M2000/23-252F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-252Z | M2000/23-252Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-253F | M2000/23-253F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-253Z | M2000/23-253Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-255F | M2000/23-255F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-255Z | M2000/23-255Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-256F | M2000/23-256F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-256Z | M2000/23-256Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-257F | M2000/23-257F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-257Z | M2000/23-257Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-258F | M2000/23-258F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-258Z | M2000/23-258Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-259F | M2000/23-259F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-259Z | M2000/23-259Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-261F | M2000/23-261F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-261Z | M2000/23-261Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-262F | M2000/23-262F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-262Z | M2000/23-262Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-263F | M2000/23-263F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-263Z | M2000/23-263Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-264F | M2000/23-264F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-264Z | M2000/23-264Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-265F | M2000/23-265F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-265Z | M2000/23-265Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-267F | M2000/23-267F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-267Z | M2000/23-267Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-268F | M2000/23-268F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-268Z | M2000/23-268Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-269F | M2000/23-269F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-269Z | M2000/23-269Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-270F | M2000/23-270F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-270Z | M2000/23-270Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-271F | M2000/23-271F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-271Z | M2000/23-271Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-273F | M2000/23-273F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-273Z | M2000/23-273Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-274F | M2000/23-274F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-274Z | M2000/23-274Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-275F | M2000/23-275F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-275Z | M2000/23-275Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-276F | M2000/23-276F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-276Z | M2000/23-276Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-277F | M2000/23-277F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-277Z | M2000/23-277Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-301 | M2000/23-301 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-302 | M2000/23-302 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-303 | M2000/23-303 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-304 | M2000/23-304 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-305 | M2000/23-305 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-307 | M2000/23-307 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-308 | M2000/23-308 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-309 | M2000/23-309 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-310 | M2000/23-310 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-311 | M2000/23-311 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-313 | M2000/23-313 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-314 | M2000/23-314 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-315 | M2000/23-315 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-316 | M2000/23-316 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-317 | M2000/23-317 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-319 | M2000/23-319 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-320 | M2000/23-320 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-321 | M2000/23-321 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-322 | M2000/23-322 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-323 | M2000/23-323 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-325 | M2000/23-325 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-326 | M2000/23-326 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-327 | M2000/23-327 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-328 | M2000/23-328 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-329 | M2000/23-329 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-331 | M2000/23-331 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-332 | M2000/23-332 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-333 | M2000/23-333 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-334 | M2000/23-334 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-335 | M2000/23-335 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-337 | M2000/23-337 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-338 | M2000/23-338 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-339 | M2000/23-339 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-340 | M2000/23-340 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-341 | M2000/23-341 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-343 | M2000/23-343 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-344 | M2000/23-344 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-345 | M2000/23-345 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-346 | M2000/23-346 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-347 | M2000/23-347 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-349 | M2000/23-349 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-350 | M2000/23-350 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-351 | M2000/23-351 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-352 | M2000/23-352 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-353 | M2000/23-353 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-355 | M2000/23-355 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-356 | M2000/23-356 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-357 | M2000/23-357 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-358 | M2000/23-358 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-359 | M2000/23-359 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-361 | M2000/23-361 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-362 | M2000/23-362 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-363 | M2000/23-363 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-364 | M2000/23-364 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-365 | M2000/23-365 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-367 | M2000/23-367 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-368 | M2000/23-368 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-369 | M2000/23-369 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-370 | M2000/23-370 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-371 | M2000/23-371 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-373 | M2000/23-373 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-374 | M2000/23-374 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-375 | M2000/23-375 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-376 | M2000/23-376 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-377 | M2000/23-377 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/23-131 | 115372-2111 | 24308-3535-12 | C&K Components SAS |
| M24308/23-133 | 115372-2115 | 24308-3535-12 | C&K Components SAS |
| M24308/23-134 | 115372-2117 | 24308-3535-12 | C&K Components SAS |
| M24308/23-135 | 115372-2119 | 24308-3535-12 | C&K Components SAS |
| M24308/23-149 | 115372-2141 | 24308-3535-12 | C&K Components SAS |
| M24308/23-150 | 115372-2143 | 24308-3535-12 | C&K Components SAS |
| M24308/23-151 | 115372-2145 | 24308-3535-12 | C&K Components SAS |
| M24308/23-152 | 115372-2147 | 24308-3535-12 | C&K Components SAS |
| M24308/23-153 | 115372-2149 | 24308-3535-12 | C&K Components SAS |
| M24308/23-1F | 230-09-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-1Z | 230-09-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-2F | 230-15-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-2Z | 230-15-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-3F | 230-25-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-3F | 230-25-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-3Z | 230-25-09-133 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-4F | 230-37-09-127 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-4Z | 230-37-09-127 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-5F | 230-50-09-137 | 24308-454-74 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-5Z | 230-50-09-137 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-7F | 230-09-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-7F | 230-09-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-7Z | 230-09-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-8F | 230-15-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-8Z | 230-15-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-9F | 230-25-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-9Z | 230-25-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-10F | 230-37-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-10Z | 230-37-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-11F | 230-50-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-11Z | 230-50-09-139 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-13F | 230-09-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-13Z | 230-09-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-14F | 230-15-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-14Z | 230-15-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-15F | 230-25-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-15Z | 230-25-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-16F | 230-37-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-16Z | 230-37-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-17F | 230-50-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-17Z | 230-50-01-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-19F | 230-09-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-19Z | 230-09-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-20F | 230-15-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-20Z | 230-15-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-21F | 230-25-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-21Z | 230-25-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-22F | 230-37-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-22Z | 230-37-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-23F | 230-50-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-23Z | 230-50-09-183 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/23-1F | DEG9S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-2F | DAG15S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-3F | DBG25S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-4F | DCG37S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-5F | DDG50S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-5F | DDG50S3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-7F | DEG9S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-8F | DAG15S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-8F | DAG15S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-9F | DBG25S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-9F | DBG25S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-10F | DCG37S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-11F | DDG50S3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-13F | DEG9S3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-14F | DAG15S3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-15F | DBG25S3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-16F | DCG37S3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-17F | DDG50S3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-19F | DEG9S3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-20F | DAG15S3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-21F | DBG25S3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-22F | DCG37S3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-23F | DDG50S3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-25F | DEG9S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-26F | DAG15S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-27F | DBG25S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-28F | DCG37S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-29F | DDG50S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-31F | DEG9S5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-32F | DAG15S5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-33F | DBG25S5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-34F | DCG37S5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-35F | DDG50S5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-37F | DEG9S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-38F | DAG15S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-39F | DBG25S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-40F | DCG37S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-41F | DDG50S5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-43F | DEG9S5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-44F | DAG15S5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-45F | DBG25S5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-46F | DCG37S5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-47F | DDG50S5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-49F | DEG9S5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-50F | DAG15S5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-51F | DBG25S5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-52F | DCG37S5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-53F | DDG50S5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-55F | DEG9S5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-56F | DAG15S5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-57F | DBG25S5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-58F | DCG37S5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-59F | DDG50S5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/23-1F | M24308/23-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-1Z | M24308/23-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-2F | M24308/23-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-2Z | M24308/23-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-3F | M24308/23-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-3Z | M24308/23-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-4F | M24308/23-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-4Z | M24308/23-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-5F | M24308/23-5F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-5Z | M24308/23-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-7F | M24308/23-7F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-7Z | M24308/23-7Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-8F | M24308/23-8F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-8Z | M24308/23-8Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-9F | M24308/23-9F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-9Z | M24308/23-9Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-10F | M24308/23-10F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-10Z | M24308/23-10Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-11F | M24308/23-11F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-11Z | M24308/23-11Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-13F | M24308/23-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-13Z | M24308/23-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-14F | M24308/23-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-14Z | M24308/23-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-15F | M24308/23-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-15Z | M24308/23-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-16F | M24308/23-16F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-16Z | M24308/23-16Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-17F | M24308/23-17F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-17Z | M24308/23-17Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-19F | M24308/23-19F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-19Z | M24308/23-19Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-20F | M24308/23-20F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-20Z | M24308/23-20Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-21F | M24308/23-21F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-21Z | M24308/23-21Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-22F | M24308/23-22F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-22Z | M24308/23-22Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-23F | M24308/23-23F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-23Z | M24308/23-23Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-25F | M24308/23-25F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-25Z | M24308/23-25Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-26F | M24308/23-26F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-26Z | M24308/23-26Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-27F | M24308/23-27F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-27Z | M24308/23-27Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-28F | M24308/23-28F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-28Z | M24308/23-28Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-29F | M24308/23-29F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-29Z | M24308/23-29Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-31F | M24308/23-31F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-31Z | M24308/23-31Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-32F | M24308/23-32F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-32Z | M24308/23-32Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-33F | M24308/23-33F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-33Z | M24308/23-33Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-34F | M24308/23-34F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-34Z | M24308/23-34Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-35F | M24308/23-35F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-35Z | M24308/23-35Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-37F | M24308/23-37F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-37Z | M24308/23-37Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-38F | M24308/23-38F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-38Z | M24308/23-38Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-39F | M24308/23-39F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-39Z | M24308/23-39Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-40F | M24308/23-40F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-40Z | M24308/23-40Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-41F | M24308/23-41F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-41Z | M24308/23-41Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-43F | M24308/23-43F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-43Z | M24308/23-43Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-44F | M24308/23-44F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-44Z | M24308/23-44Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-45F | M24308/23-45F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-45Z | M24308/23-45Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-46F | M24308/23-46F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-46Z | M24308/23-46Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-47F | M24308/23-47F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-47Z | M24308/23-47Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-49F | M24308/23-49F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-49Z | M24308/23-49Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-50F | M24308/23-50F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-50Z | M24308/23-50Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-51F | M24308/23-51F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-51Z | M24308/23-51Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-52F | M24308/23-52F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-52Z | M24308/23-52Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-53F | M24308/23-53F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-53Z | M24308/23-53Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-55F | M24308/23-55F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-55Z | M24308/23-55Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-56F | M24308/23-56F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-56Z | M24308/23-56Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-57F | M24308/23-57F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-57Z | M24308/23-57Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-58F | M24308/23-58F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-58Z | M24308/23-58Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-59F | M24308/23-59F | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-59Z | M24308/23-59Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/23-50F | HDC15S5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-50P | HDC15S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-50Z | HDC15S5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-1F | HDC9S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-1P | HDC9SP00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-1Z | HDC9S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-2F | HDC15S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-2P | HDC15S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-2Z | HDC15S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-3F | HDC25S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-3P | HDC25S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-3Z | HDC25S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-4F | HDC37S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-4P | HDC37S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-4Z | HDC37S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-5F | HDC50S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-5P | HDC50S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-5Z | HDC50S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-7F | HDC9S3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-7P | HDC9S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-7Z | HDC9S3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-8F | HDC15S3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-8P | HDC15S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-8Z | HDC15S3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-9F | HDC25S3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-9P | HDC25S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-9Z | HDC25S3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-10F | HDC37S3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-10P | HDC37S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-10Z | HDC37S3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-11F | HDC50S3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-11P | HDC50S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-11Z | HDC50S3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-13F | HDC9S3P00C-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-13P | HDC9S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-13Z | HDC9S3P000-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-14F | HDC15S3P00C-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-14P | HDC15S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-14Z | HDC15S3P000-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-15F | HDC25S3P00C-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-15P | HDC25S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-15Z | HDC25S3P000-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-16F | HDC37S3P00C-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-16P | HDC37S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-16Z | HDC37S3P000-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-17F | HDC50S3P00C-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-17P | HDC50S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-17Z | HDC50S3P000-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-19F | HDC9S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-19P | HDC9S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-19Z | HDC9S3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-20F | HDC15S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-20P | HDC15S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-20Z | HDC15S3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-21F | HDC25S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-21P | HDC25S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-21Z | HDC25S3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-22F | HDC37S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-22P | HDC37S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-22Z | HDC37S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-23F | HDC50S3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-23P | HDC50S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-23Z | HDC50S3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-25F | HDC9S5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-25P | HDC9S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-25Z | HDC9S5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-26F | HDC15S5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-26P | HDC15S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-26Z | HDC15S5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-27F | HDC25S5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-27P | HDC25S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-27Z | HDC25S5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-28F | HDC37S5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-28P | HDC37S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-28Z | HDC37S5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-29F | HDC50S5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-29P | HDC50S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-29Z | HDC50S5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-31F | HDC9S5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-31P | HDC9S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-31Z | HDC9S5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-32F | HDC15S5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-32P | HDC15S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-32Z | HDC15S5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-33F | HDC25S5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-33P | HDC25S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-33Z | HDC25S5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-34F | HDC37S5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-34P | HDC37S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-34Z | HDC37S5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-35F | HDC50S5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-35P | HDC50S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-35Z | HDC50S5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-37F | HDC9S5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-37P | HDC9S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-37Z | HDC9S5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-38F | HDC15S5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-38P | HDC15S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-38Z | HDC15S5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-39F | HDC25S5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-39P | HDC25S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-39Z | HDC25S5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-40F | HDC37S5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-40P | HDC37S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-40Z | HDC37S5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-41F | HDC50S5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-41P | HDC50S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-41Z | HDC50S5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-43F | HDC9S5B800C-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-43P | HDC9S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-43Z | HDC9S5B8000-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-44F | HDC15S5B800C-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-44P | HDC15S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-44Z | HDC15S5B8000-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-45F | HDC25S5B800C-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-45P | HDC25S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-45Z | HDC25S5B8000-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-46F | HDC37S5B800C-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-46P | HDC37S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-46Z | HDC37S5B8000-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-47F | HDC50S5B800C-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-47P | HDC50S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-47Z | HDC50S5B8000-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-49F | HDC9S5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-49P | HDC9S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-49Z | HDC9S5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-51F | HDC25S5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-51P | HDC25S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-51Z | HDC25S5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-52F | HDC37S5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-52P | HDC37S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-52Z | HDC37S5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-53F | HDC50S5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-53P | HDC50S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-53Z | HDC50S5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-55F | HDC9S5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-55P | HDC9S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-55Z | HDC9S5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-56F | HDC15S5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-56P | HDC15S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-56Z | HDC15S5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-57F | HDC25S5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-57P | HDC25S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-57Z | HDC25S5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-58F | HDC37S5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-58P | HDC37S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-58Z | HDC37S5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-59F | HDC50S5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-59P | HDC50S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-59Z | HDC50S5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-61F | DD15S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-61P | DD15S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-61Z | DD15S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-62F | DD26S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-62P | DD26S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-62Z | DD26S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-63F | DD44S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-63P | DD44S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-63Z | DD44S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-64F | DD62S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-64P | DD62S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-64Z | DD62S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-65F | DD78S3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-65P | DD78S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-65Z | DD78S3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-67F | DD15S32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-67P | DD15S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-67Z | DD15S32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-68F | DD26S32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-68P | DD26S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-68Z | DD26S32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-69F | DD44S32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-69P | DD44S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-69Z | DD44S32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-70F | DD62S32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-70P | DD62S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-70Z | DD62S32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-71F | DD78S32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-71P | DD78S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-71Z | DD78S32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-73F | DD15S4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-73P | DD15S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-73Z | DD15S4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-74F | DD26S4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-74P | DD26S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-74Z | DD26S4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-75F | DD44S4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-75P | DD44S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-75Z | DD44S4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-76F | DD62S4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-76P | DD62S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-76Z | DD62S4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-77F | DD78S4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-77P | DD78S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-77Z | DD78S4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-101 | HDC9S3P00-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-102 | HDC15S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-102Z | HDC15S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-103 | HDC25S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-104 | HDC37S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-105 | HDC50S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-107 | HDC9S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-108 | HDC15S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-109 | HDC25S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-110 | HDC37S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-110Z | HDC37S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-111 | HDC50S3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-113 | HDC9S3P000-MIL-403.46 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-114 | HDC15S3P000-MIL-403.46 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-115 | HDC25S3P000-MIL-403.46 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-116 | HDC37S3P000-MIL-403.46 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-117 | HDC50S3P000-MIL-403.46 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-119 | HDC9S3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-120 | HDC15S3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-121 | HDC25S3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-122 | HDC37S3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-123 | HDC50S3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-125 | HDC9S5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-126 | HDC15S5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-127 | HDC25S5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-128 | HDC37S5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-129 | HDC50S5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-131 | HDC9S5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-132 | HDC15S5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-133 | HDC25S5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-134 | HDC37S5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-135 | HDC50S5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-137 | HDC9S5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-138 | HDC15S5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-139 | HDC25S5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-140 | HDC37S5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-141 | HDC50S5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-143 | HDC9S5B8000-MIL-403.48 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-144 | HDC15S5B8000-MIL-403.48 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-145 | HDC25S5B8000-MIL-403.48 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-146 | HDC37S5B8000-MIL-403.48 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-147 | HDC50S5B8000-MIL-403.48 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-149 | HDC9S5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-150 | HDC15S5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-151 | HDC25S5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-152 | HDC37S5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-153 | HDC50S5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-155 | HDC9S5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-156 | HDC15S5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-157 | HDC25S5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-158 | HDC37S5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-159 | HDC50S5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-161 | DD15S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-162 | DD26S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-163 | DD44S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-164 | DD62S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-165 | DD78S3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-167 | DD15S32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-168 | DD26S32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-169 | DD44S32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-170 | DD62S32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-171 | DD78S32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-173 | DD15S4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-174 | DD26S4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-175 | DD44S4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-176 | DD62S4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-177 | DD78S4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-201F | HDC9F3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-201P | HDC9F3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-201Z | HDC9F3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-202F | HDC15S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-202P | HDC15S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-202Z | HDC15S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-203F | HDC25S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-203P | HDC25S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-203Z | HDC25S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-204F | HDC37S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-204P | HDC37S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-204Z | HDC37S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-205F | HDC50S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-205P | HDC50S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-205Z | HDC50S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-207F | HDC9S3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-207P | HDC9S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-207Z | HDC9S3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-208F | HDC15S3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-208P | HDC15S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-208Z | HDC15S3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-209F | HDC25S3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-209P | HDC25S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-209Z | HDC25S3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-210F | HDC37S3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-210P | HDC37S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-210Z | HDC37S3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-211F | HDC50S3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-211P | HDC50S3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-211Z | HDC50S3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-213F | HDC9S3P00C-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-213P | HDC9S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-213Z | HDC9S3P000-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-214F | HDC15S3P00C-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-214P | HDC15S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-214Z | HDC15S3P000-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-215F | HDC25S3P00C-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-215P | HDC25S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-215Z | HDC25S3P000-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-216F | HDC37S3P00C-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-216P | HDC37S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-216Z | HDC37S3P000-MIL-403.4 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-217F | HDC50S3P00C-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-217P | HDC50S3P00S-MIL-375.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-217Z | HDC50S3P000-MIL-403.47 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-219F | HDC9S3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-219P | HDC9S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-219Z | HDC9S3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-220F | HDC15S3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-220P | HDC15S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-220Z | HDC15S3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-221F | HDC25S3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-221P | HDC25S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-221Z | HDC25S3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-222F | HDC37S3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-222P | HDC37S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-222Z | HDC37S3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-223F | HDC50S3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-223P | HDC50S3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-223Z | HDC50S3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-225F | HDC9S5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-225P | HDC9S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-225Z | HDC9S5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-226F | HDC15S5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-226P | HDC15S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-226Z | HDC15S5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-227F | HDC25S5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-227P | HDC25S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-227Z | HDC25S5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-228F | HDC37S5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-228P | HDC37S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-228Z | HDC37S5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-229F | HDC50S5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-229P | HDC50S5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-229Z | HDC50S5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-231F | HDC9S5B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-231P | HDC9S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-231Z | HDC9S5B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-232F | HDC15S5B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-232P | HDC15S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-232Z | HDC15S5B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-233F | HDC25S5B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-233P | HDC25S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-233Z | HDC25S5B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-234F | HDC37S5B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-234P | HDC37S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-234Z | HDC37S5B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-235F | HDC50S5B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-235P | HDC50S5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-235Z | HDC50S5B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-237F | HDC9S5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-237P | HDC9S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-237Z | HDC9S5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-238F | HDC15S5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-238P | HDC15S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-238Z | HDC15S5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-239F | HDC25S5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-239P | HDC25S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-239Z | HDC25S5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-240F | HDC37S5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-240P | HDC37S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-240Z | HDC37S5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-241F | HDC50S5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-241P | HDC50S5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-241Z | HDC50S5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-243F | HDC9S5B800C-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-243P | HDC9S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-243Z | HDC9S5B8000-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-244F | HDC15S5B800C-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-244P | HDC15S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-244Z | HDC15S5B8000-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-245F | HDC25S5B800C-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-245P | HDC25S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-245Z | HDC25S5B8000-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-246F | HDC37S5B800C-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-246P | HDC37S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-246Z | HDC37S5B8000-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-247F | HDC50S5B800C-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-247P | HDC50S5B800S-MIL-376.2 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-247Z | HDC50S5B8000-MIL-403.49 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-249F | HDC9S5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-249P | HDC9S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-249Z | HDC9S5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-250F | HDC15S5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-250P | HDC15S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-250Z | HDC15S5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-251F | HDC25S5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-251P | HDC25S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-251Z | HDC25S5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-252F | HDC37S5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-252P | HDC37S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-252Z | HDC37S5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-253F | HDC50S5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-253P | HDC50S5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-253Z | HDC50S5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-255F | HDC9S5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-255P | HDC9S5B800S-MIL-376 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-255Z | HDC9S5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-256F | HDC15S5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-256P | HDC15S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-256Z | HDC15S5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-257F | HDC25S5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-257P | HDC25S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-257Z | HDC25S5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-258F | HDC37S5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-258P | HDC37S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-258Z | HDC37S5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-259P | HDC50S5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-259Z | HDC50S5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-261F | DD15S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-261P | DD15S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-261Z | DD15S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-262F | DD26S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-262P | DD26S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-262Z | DD26S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-263F | DD44S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-263P | DD44S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-263Z | DD44S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-264F | DD62S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-264P | DD62S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-264Z | DD62S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-265F | DD78S3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-265P | DD78S3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-265Z | DD78S3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-267F | DD15S32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-267P | DD15S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-267Z | DD15S32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-268F | DD26S32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-268P | DD26S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-268Z | DD26S32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-269F | DD44S32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-269P | DD44S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-269Z | DD44S32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-270F | DD62S32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-270P | DD62S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-270Z | DD62S32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-271F | DD78S32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-271P | DD78S32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-271Z | DD78S32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-273F | DD15S4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-273P | DD15S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-273Z | DD15S4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-274F | DD26S4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-274P | DD26S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-274Z | DD26S4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-275F | DD44S4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-275P | DD44S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-275Z | DD44S4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-276F | DD62S4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-276P | DD62S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-276Z | DD62S4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-277F | DD78S4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-277P | DD78S4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-277Z | DD78S4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-301 | HDC9S3P00C-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-302 | HDC15S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-303 | HDC25S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-304 | HDC37S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-305 | HDC50S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-307 | HDC9S3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-308 | HDC15S3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-309 | HDC25S3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-310 | HDC37S3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-311 | HDC50S3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-313 | HDC9S3P000-MIL-799.17 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-314 | HDC15S3P000-MIL-799.17 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-315 | HDC25S3P000-MIL-799.17 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-316 | HDC37S3P000-MIL-799.17 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-317 | HDC50S3P000-MIL-799.17 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-319 | HDC9S3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-320 | HDC15S3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-321 | HDC25S3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-322 | HDC37S3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-323 | HDC50S3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-325 | HDC9S5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-326 | HDC15S5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-327 | HDC25S5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-328 | HDC37S5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-328 | HDC50S5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-331 | HDC9S5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-332 | HDC15S5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-333 | HDC25S5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-334 | HDC37S5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-335 | HDC50S5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-337 | HDC9S5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-338 | HDC15S5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-339 | HDC25S5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-340 | HDC37S5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-341 | HDC50S5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-343 | HDC9S5B8000-MIL-799.18 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-344 | HDC15S5B8000-MIL-799.18 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-345 | HDC25S5B8000-MIL-799.18 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-346 | HDC37S5B8000-MIL-799.18 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-347 | HDC50S5B8000-MIL-799.18 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-349 | HDC9S5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-350 | HDC15S5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-351 | HDC25S5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-352 | HDC37S5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-353 | HDC50S5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-355 | HDC9S5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-356 | HDC15S5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-357 | HDC25S5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-358 | HDC37S5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-359 | HDC50S5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-361 | DD15S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-362 | DD26S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-363 | DD44S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-364 | DD62S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-365 | DD78S3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-367 | DD15S32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-368 | DD26S32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-369 | DD44S32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-370 | DD62S32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-371 | DD78S32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-373 | DD15S4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-374 | DD26S4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-375 | DD44S4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-376 | DD62S4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-377 | DD78S4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/23-1F | 443975-1 | 24308-127-97 | Tyco Electronics |
| M24308/23-1Z | 1757828-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-2F | 443975-2 | 24308-127-97 | Tyco Electronics |
| M24308/23-2Z | 1757828-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-3F | 443975-3 | 24308-127-97 | Tyco Electronics |
| M24308/23-3Z | 1757828-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-4F | 443975-4 | 24308-127-97 | Tyco Electronics |
| M24308/23-4Z | 1757828-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-5F | 443975-5 | 24308-339-76 | Tyco Electronics |
| M24308/23-5Z | 1757828-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-7F | 443976-1 | 24308-127-97 | Tyco Electronics |
| M24308/23-7Z | 1757830-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-8F | 443976-2 | 24308-127-97 | Tyco Electronics |
| M24308/23-8Z | 1757830-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-9F | 443976-3 | 24308-127-97 | Tyco Electronics |
| M24308/23-9Z | 1757830-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-10F | 443976-4 | 24308-127-97 | Tyco Electronics |
| M24308/23-10Z | 1757830-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-11F | 443976-5 | 24308-339-76 | Tyco Electronics |
| M24308/23-11Z | 1757830-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-13F | 443977-1 | 24308-127-97 | Tyco Electronics |
| M24308/23-13Z | 1757832-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-14F | 443977-2 | 24308-127-97 | Tyco Electronics |
| M24308/23-14Z | 1757832-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-15F | 443977-3 | 24308-127-97 | Tyco Electronics |
| M24308/23-15Z | 1757832-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-16F | 443977-4 | 24308-127-97 | Tyco Electronics |
| M24308/23-16Z | 1757832-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-17F | 443977-5 | 24308-339-76 | Tyco Electronics |
| M24308/23-17Z | 1757832-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-19F | 443978-1 | 24308-127-97 | Tyco Electronics |
| M24308/23-19Z | 1757834-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-20F | 443978-2 | 24308-127-97 | Tyco Electronics |
| M24308/23-20Z | 1757834-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-21F | 443978-3 | 24308-127-97 | Tyco Electronics |
| M24308/23-21Z | 1757832-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-22F | 443978-4 | 24308-127-97 | Tyco Electronics |
| M24308/23-22Z | 1757834-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-23F | 443978-5 | 24308-339-76 | Tyco Electronics |
| M24308/23-23Z | 1757834-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-25F | 1218434-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-25Z | 1757836-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-26F | 1218434-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-26Z | 1757836-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-27F | 1218434-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-27Z | 1757836-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-28F | 1218434-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-28Z | 1757836-4 | 24308-125-99 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/23-29F | 1218434-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-29Z | 1757836-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-31F | 1218408-1 | 24308-1057-84 | Tyco Electronics |
| M24308/23-31Z | 1757838-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-32F | 1218408-2 | 24308-1057-84 | Tyco Electronics |
| M24308/23-32Z | 1757838-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-33F | 1218408-3 | 24308-1057-84 | Tyco Electronics |
| M24308/23-33Z | 1757838-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-34F | 1218408-4 | 24308-1057-84 | Tyco Electronics |
| M24308/23-34Z | 1757838-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-35F | 1218408-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-35Z | 1757838-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-37F | 1218435-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-37Z | 1757842-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-38F | 1218435-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-38Z | 1757842-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-39F | 1218435-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-39Z | 1757842-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-40F | 1218435-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-40Z | 1757842-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-41F | 1218435-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-41Z | 1757842-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-43F | 1218436-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-43Z | 1757844-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-44F | 1218436-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-44Z | 1757844-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-45F | 1218436-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-45Z | 1757844-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-46F | 1218436-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-46Z | 1757844-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-47F | 1218436-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-47Z | 1757844-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-49F | 1218437-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-49Z | 1757840-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-50F | 1218437-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-50Z | 1757840-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-51F | 1218437-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-51Z | 1757840-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-52F | 1218437-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-52Z | 1757840-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-53F | 1218437-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-53Z | 1757840-5 | 24308-125-99 | Tyco Electronics |
| M24308/23-55F | 1218438-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-55Z | 1757846-1 | 24308-125-99 | Tyco Electronics |
| M24308/23-56F | 1218438-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-56Z | 1757846-2 | 24308-125-99 | Tyco Electronics |
| M24308/23-57F | 1218438-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-57Z | 1757846-3 | 24308-125-99 | Tyco Electronics |
| M24308/23-58F | 1218438-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-58Z | 1757846-4 | 24308-125-99 | Tyco Electronics |
| M24308/23-59F | 1218438-5 | 24308-1057-84 | Tyco Electronics |
| M24308/23-59Z | 1757846-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-149 | 115372-2140 | 24308-3535-12 | |
| M24308/24-1F | GPM-C10S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-1Z | GPM-Z10S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-2F | GPM-C10S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-2Z | GPM-Z10S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-3F | GPM-C10S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-3Z | GPM-Z10S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-4F | GPM-C10S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-4Z | GPM-Z10S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-5F | GPM-C10S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-5Z | GPM-Z10S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-7F | GPM-C10S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-7Z | GPM-Z10S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-8F | GPM-C10S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-8Z | GPM-Z10S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-9F | GPM-C10S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-9Z | GPM-Z10S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-10F | GPM-C10S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-10Z | GPM-Z10S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-11F | GPM-C10S-00050P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-11Z | GPM-Z10S-00050P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-13F | GPM-C11S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-13Z | GPM-Z11S-00009P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-14F | GPM-C11S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-14Z | GPM-Z11S-00015P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-15F | GPM-C11S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-15Z | GPM-Z11S-00025P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-16F | GPM-C11S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-16Z | GPM-Z11S-00037P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-17F | GPM-C11S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-17Z | GPM-Z11S-00050P-00 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-19F | GPM-C11S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-19Z | GPM-Z11S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-20F | GPM-C11S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-20Z | GPM-Z11S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-21F | GPM-C11S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-21Z | GPM-Z11S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-22F | GPM-C11S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-22Z | GPM-Z11S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-23F | GPM-C11S-00050P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-23Z | GPM-Z11S-00050P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-25F | GPM-C21S-00009P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-25Z | GPM-Z21S-00009P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-26F | GPM-C21S-00015P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-26Z | GPM-Z21S-00015P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-27F | GPM-C21S-00025P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-27Z | GPM-Z21S-00025P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-28F | GPM-C21S-00037P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-28Z | GPM-Z21S-00037P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-31F | GPM-C21S-00009P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-31Z | GPM-Z21S-00009P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-32F | GPM-C21S-00015P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-32Z | GPM-Z21S-00015P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-33F | GPM-C21S-00025P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-33Z | GPM-Z21S-00025P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-34F | GPM-C21S-00037P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-34Z | GPM-Z21S-00037P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-37F | GPM-C22S-00009P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-37Z | GPM-Z22S-00009P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-38F | GPM-C22S-00015P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-38Z | GPM-Z22S-00015P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-39F | GPM-C22S-00025P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-39Z | GPM-Z22S-00025P-06 | 24308-84-89 | ADI Electronics Incorporated |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-40F | GPM-C22S-00037P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-40Z | GPM-Z22S-00037P-06 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-43F | GPM-C22S-00009P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-43Z | GPM-Z22S-00009P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-44F | GPM-C22S-00015P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-44Z | GPM-Z22S-00015P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-45F | GPM-C22S-00025P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-45Z | GPM-Z22S-00025P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-46F | GPM-C22S-00037P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-46Z | GPM-Z22S-00037P-09 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-49F | GPM-C21S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-49Z | GPM-Z21S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-50F | GPM-C21S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-50Z | GPM-Z21S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-51F | GPM-C21S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-51Z | GPM-Z21S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-52F | GPM-C21S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-52Z | GPM-Z21S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-55F | GPM-C22S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-55Z | GPM-Z22S-00009P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-56F | GPM-C22S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-56Z | GPM-Z22S-00015P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-57F | GPM-C22S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-57Z | GPM-Z22S-00025P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-58F | GPM-C22S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-58Z | GPM-Z22S-00037P-12 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/24-1F | M2000/24-1F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-1K | M2000/24-1K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-1Z | M2000/24-1Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-2F | M2000/24-2F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-2K | M2000/24-2K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-2Z | M2000/24-2Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-3F | M2000/24-3F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-3K | M2000/24-3K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-3Z | M2000/24-3Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-4F | M2000/24-4F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-4K | M2000/24-4K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-4Z | M2000/24-4Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-5F | M2000/24-5F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-5K | M2000/24-5K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-5Z | M2000/24-5Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-7F | M2000/24-7F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-7K | M2000/24-7K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-7Z | M2000/24-7Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-8F | M2000/24-8F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-8K | M2000/24-8K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-8Z | M2000/24-8Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-9F | M2000/24-9F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-9K | M2000/24-9K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-9Z | M2000/24-9Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-10F | M2000/24-10F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-10K | M2000/24-10K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-10Z | M2000/24-10Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-11F | M2000/24-11F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-11K | M2000/24-11K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-11Z | M2000/24-11Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-13F | M2000/24-13F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-13K | M2000/24-13K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-59K | M2000/24-59K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-59Z | M2000/24-59Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-61F | M2000/24-61F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-61K | M2000/24-61K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-61Z | M2000/24-61Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-62F | M2000/24-62F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-62K | M2000/24-62K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-62Z | M2000/24-62Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-63F | M2000/24-63F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-63K | M2000/24-63K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-63Z | M2000/24-63Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-64F | M2000/24-64F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-64K | M2000/24-64K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-64Z | M2000/24-64Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-65F | M2000/24-65F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-65K | M2000/24-65K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-65Z | M2000/24-65Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-67F | M2000/24-67F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-67K | M2000/24-67K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-67Z | M2000/24-67Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-68F | M2000/24-68F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-68K | M2000/24-68K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-68Z | M2000/24-68Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-69F | M2000/24-69F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-69K | M2000/24-69K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-69Z | M2000/24-69Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-70F | M2000/24-70F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-70K | M2000/24-70K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-70Z | M2000/24-70Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-71F | M2000/24-71F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-71K | M2000/24-71K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-71Z | M2000/24-71Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-73F | M2000/24-73F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-73K | M2000/24-73K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-73Z | M2000/24-73Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-74F | M2000/24-74F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-74K | M2000/24-74K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-74Z | M2000/24-74Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-75F | M2000/24-75F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-75K | M2000/24-75K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-75Z | M2000/24-75Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-76F | M2000/24-76F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-76K | M2000/24-76K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-76Z | M2000/24-76Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-77F | M2000/24-77F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-77K | M2000/24-77K | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-77Z | M2000/24-77Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-101 | M2000/24-101 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-102 | M2000/24-102 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-103 | M2000/24-103 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-104 | M2000/24-104 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-105 | M2000/24-105 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-107 | M2000/24-107 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-108 | M2000/24-108 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-109 | M2000/24-109 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-110 | M2000/24-110 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-111 | M2000/24-111 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-113 | M2000/24-113 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-114 | M2000/24-114 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-115 | M2000/24-115 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-116 | M2000/24-116 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-117 | M2000/24-117 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-119 | M2000/24-119 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-120 | M2000/24-120 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-121 | M2000/24-121 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-122 | M2000/24-122 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-123 | M2000/24-123 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-125 | M2000/24-125 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-126 | M2000/24-126 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-127 | M2000/24-127 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-128 | M2000/24-128 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-129 | M2000/24-129 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-131 | M2000/24-131 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-132 | M2000/24-132 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-133 | M2000/24-133 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-134 | M2000/24-134 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-135 | M2000/24-135 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-137 | M2000/24-137 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-138 | M2000/24-138 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-139 | M2000/24-139 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-140 | M2000/24-140 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-141 | M2000/24-141 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-143 | M2000/24-143 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-144 | M2000/24-144 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-145 | M2000/24-145 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-146 | M2000/24-146 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-147 | M2000/24-147 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-149 | M2000/24-149 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-150 | M2000/24-150 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-151 | M2000/24-151 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-152 | M2000/24-152 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-153 | M2000/24-153 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-155 | M2000/24-155 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-156 | M2000/24-156 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-157 | M2000/24-157 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-158 | M2000/24-158 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-159 | M2000/24-159 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-161 | M2000/24-161 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-162 | M2000/24-162 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-163 | M2000/24-163 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-164 | M2000/24-164 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-165 | M2000/24-165 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-167 | M2000/24-167 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-168 | M2000/24-168 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-169 | M2000/24-169 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-170 | M2000/24-170 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-171 | M2000/24-171 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-173 | M2000/24-173 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-174 | M2000/24-174 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-175 | M2000/24-175 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-176 | M2000/24-176 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-177 | M2000/24-177 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-201F | M2000/24-201F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-201Z | M2000/24-201Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-202F | M2000/24-202F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-202Z | M2000/24-202Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-273F | M2000/24-273F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-273Z | M2000/24-273Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-274F | M2000/24-274F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-274Z | M2000/24-274Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-275F | M2000/24-275F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-275Z | M2000/24-275Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-276F | M2000/24-276F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-276Z | M2000/24-276Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-277F | M2000/24-277F | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-277Z | M2000/24-277Z | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-301 | M2000/24-301 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-302 | M2000/24-302 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-303 | M2000/24-303 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-304 | M2000/24-304 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-305 | M2000/24-305 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-307 | M2000/24-307 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-308 | M2000/24-308 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-309 | M2000/24-309 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-310 | M2000/24-310 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-311 | M2000/24-311 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-313 | M2000/24-313 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-314 | M2000/24-314 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-315 | M2000/24-315 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-316 | M2000/24-316 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-317 | M2000/24-317 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-319 | M2000/24-319 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-320 | M2000/24-320 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-321 | M2000/24-321 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-322 | M2000/24-322 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-323 | M2000/24-323 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-325 | M2000/24-325 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-326 | M2000/24-326 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-327 | M2000/24-327 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-328 | M2000/24-328 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-329 | M2000/24-329 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-331 | M2000/24-331 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-332 | M2000/24-332 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-333 | M2000/24-333 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-334 | M2000/24-334 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-335 | M2000/24-335 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-337 | M2000/24-337 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-338 | M2000/24-338 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-339 | M2000/24-339 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-340 | M2000/24-340 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-341 | M2000/24-341 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-343 | M2000/24-343 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-344 | M2000/24-344 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-345 | M2000/24-345 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-346 | M2000/24-346 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-347 | M2000/24-347 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-349 | M2000/24-349 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-350 | M2000/24-350 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-351 | M2000/24-351 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-352 | M2000/24-352 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-353 | M2000/24-353 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-355 | M2000/24-355 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-356 | M2000/24-356 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-357 | M2000/24-357 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-358 | M2000/24-358 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-359 | M2000/24-359 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-361 | M2000/24-361 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-362 | M2000/24-362 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-363 | M2000/24-363 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-364 | M2000/24-364 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-365 | M2000/24-365 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-367 | M2000/24-367 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-368 | M2000/24-368 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-369 | M2000/24-369 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-370 | M2000/24-370 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-371 | M2000/24-371 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-373 | M2000/24-373 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-374 | M2000/24-374 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-375 | M2000/24-375 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-376 | M2000/24-376 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-377 | M2000/24-377 | 24308-5115-18 | Amphenol Interconnect India PVT LTD |
| M24308/24-125 | 115372-2100 | 24308-3535-12 | C&K Components SAS |
| M24308/24-126 | 115372-2102 | 24308-3535-12 | C&K Components SAS |
| M24308/24-127 | 115372-2104 | 24308-3535-12 | C&K Components SAS |
| M24308/24-128 | 115372-2106 | 24308-3535-12 | C&K Components SAS |
| M24308/24-129 | 115372-2108 | 24308-3535-12 | C&K Components SAS |
| M24308/24-131 | 115372-2110 | 24308-3535-12 | C&K Components SAS |
| M24308/24-132 | 115372-2112 | 24308-3535-12 | C&K Components SAS |
| M24308/23-132 | 115372-2113 | 24308-3535-12 | C&K Components SAS |
| M24308/24-133 | 115372-2114 | 24308-3535-12 | C&K Components SAS |
| M24308/24-134 | 115372-2116 | 24308-3535-12 | C&K Components SAS |
| M24308/24-135 | 115372-2118 | 24308-3535-12 | C&K Components SAS |
| M24308/24-150 | 115372-2142 | 24308-3535-12 | C&K Components SAS |
| M24308/24-151 | 115372-2144 | 24308-3535-12 | C&K Components SAS |
| M24308/24-152 | 115372-2146 | 24308-3535-12 | C&K Components SAS |
| M24308/24-153 | 115372-2148 | 24308-3535-12 | C&K Components SAS |
| M24308/24-1F | 231-09-09-132 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-1Z | 231-09-09-132 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-2F | 231-15-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-2Z | 231-15-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-3F | 231-25-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-3Z | 231-25-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-4F | 231-37-09-142 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-4Z | 231-37-09-142 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-5F | 231-50-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-5Z | 231-50-09-143 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-7F | 231-09-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-7Z | 231-09-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-8F | 231-15-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-8Z | 231-15-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-9F | 231-25-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-9Z | 231-25-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-10F | 231-37-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-10Z | 231-37-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-11F | 231-50-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-11Z | 231-50-09-182 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-13F | 230-09-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-13Z | 230-09-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-14F | 230-25-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-14Z | 230-25-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-15F | 230-25-09-180 | 24308-454-74 | Cinch Connectors, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-15Z | 230-25-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-16F | 230-37-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-16Z | 230-37-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-17F | 230-50-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-17Z | 230-50-09-180 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-19F | 231-09-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-19Z | 231-09-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-20F | 231-15-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-20Z | 231-15-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-21F | 231-25-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-21Z | 231-25-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-22F | 231-37-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-22Z | 231-37-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-23F | 231-50-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-23Z | 231-50-09-181 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-25F | 231-09-09-149 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-25Z | 231-09-09-149 | 24308-65-149 | Cinch Connectors, Inc. |
| M24308/24-26F | 231-15-09-149 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-26Z | 231-15-09-149 | 24308-65-149 | Cinch Connectors, Inc. |
| M24308/24-27F | 231-25-09-149 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-27Z | 231-25-09-149 | 24308-65-149 | Cinch Connectors, Inc. |
| M24308/24-28F | 231-37-09-149 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-28Z | 231-37-09-149 | 24308-65-149 | Cinch Connectors, Inc. |
| M24308/24-31F | 231-09-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-31Z | 231-09-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-32F | 231-15-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-32Z | 231-15-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-33F | 231-25-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-33Z | 231-25-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-34F | 231-37-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-34Z | 231-37-09-184 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-37F | 231-09-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-37Z | 231-09-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-38F | 231-15-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-38Z | 231-15-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-39F | 231-25-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-39Z | 231-25-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-40F | 231-37-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-40Z | 231-37-09-147 | 24308-65-79 | Cinch Connectors, Inc. |
| M24308/24-49F | 231-09-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-49Z | 231-09-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-50F | 231-15-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-50Z | 231-15-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-51F | 231-25-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-51Z | 231-25-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-52F | 231-37-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-52Z | 231-37-09-185 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-55F | 231-09-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-55Z | 231-09-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-56F | 231-15-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-56Z | 231-15-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-57F | 231-25-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-57Z | 231-25-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-58F | 231-37-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-58Z | 231-37-09-186 | 24308-454-74 | Cinch Connectors, Inc. |
| M24308/24-1F | DEG9P3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-2F | DAG15P3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-3F | DBG25P3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-4F | DCG37P3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-5F | DDG50P3B-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-7F | DEG9P3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-8F | DAG15P3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-9F | DBG25P3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-10F | DCG37P3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-11F | DDG50P3E-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-13F | DEG9P3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-14F | DAG15P3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-15F | DBG25P3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-16F | DCG37P3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-17F | DDG50P3D-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-19F | DEG9P3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-20F | DAG15P3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-21F | DBG25P3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-22F | DCG37P3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-23F | DDG50P3C-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-25F | DEG9P5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-26F | DAG15P5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-27F | DBG25P5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-28F | DCG37P5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-29F | DDG50P5G-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-31F | DEG9P5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-32F | DAG15P5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-33F | DBG25P5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-34F | DCG37P5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-35F | DDG50P5J-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-37F | DEG9P5F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-38F | DAG15P5F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-39F | DBG25P5F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-40F | DCG37P5F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-41F | DDG50P5F-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-43F | DEG9PH-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-44F | DAG15P5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-45F | DBG25P5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-46F | DCG37P5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-47F | DDG50P5H-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-49F | DEG9P5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-50F | DAG15P5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-51F | DBG25P5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-52F | DCG37P5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-53F | DDG50P5L-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-55F | DEG9P5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-56F | DAG15P5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-57F | DBG25P5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-58F | DCG37P5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-59F | DDG50P5K-P6 | 24308-160-92 | Cristek Interconnects, Inc. |
| M24308/24-1F | M24308/24-1F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-1Z | M24308/24-1Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-2F | M24308/24-2F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-2Z | M24308/24-2Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-3F | M24308/24-3F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-3Z | M24308/24-3Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-4F | M24308/24-4F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-4Z | M24308/24-4Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-5F | M24308/24-5F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-5Z | M24308/24-5Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-7F | M24308/24-7F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-7Z | M24308/24-7Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-8F | M24308/24-8F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-8Z | M24308/24-8Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-9F | M24308/24-9F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-9Z | M24308/24-9Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-10F | M24308/24-10F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-10Z | M24308/24-10Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-11F | M24308/24-11F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-11Z | M24308/24-11Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-13F | M24308/24-13F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-13Z | M24308/24-13Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-14F | M24308/24-14F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-14Z | M24308/24-14Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-15F | M24308/24-15F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-15Z | M24308/24-15Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-16F | M24308/24-16F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-16Z | M24308/24-16Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-17F | M24308/24-17F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-17Z | M24308/24-17Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-19F | M24308/24-19F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-19Z | M24308/24-19Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-20F | M24308/24-20F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-20Z | M24308/24-20Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-21F | M24308/24-21F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-21Z | M24308/24-21Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-22F | M24308/24-22F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-22Z | M24308/24-22Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-23F | M24308/24-23F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-23Z | M24308/24-23Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-25F | M24308/24-25F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-25Z | M24308/24-25Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-26F | M24308/24-26F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-26Z | M24308/24-26Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-27F | M24308/24-27F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-27Z | M24308/24-27Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-28F | M24308/24-28F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-28Z | M24308/24-28Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-29F | M24308/24-29F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-29Z | M24308/24-29Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-31F | M24308/24-31F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-31Z | M24308/24-31Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-32F | M24308/24-32F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-32Z | M24308/24-32Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-33F | M24308/24-33F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-33Z | M24308/24-33Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-34F | M24308/24-34F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-34Z | M24308/24-34Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-35F | M24308/24-35F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-35Z | M24308/24-35Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-37F | M24308/24-37F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-37Z | M24308/24-37Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-38F | M24308/24-38F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-38Z | M24308/24-38Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-39F | M24308/24-39F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-39Z | M24308/24-39Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-40F | M24308/24-40F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-40Z | M24308/24-40Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-41F | M24308/24-41F | 24308-5440-19 | ITT Cannon LLC |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-41Z | M24308/24-41Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-43F | M24308/24-43F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-43Z | M24308/24-43Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-44F | M24308/24-44F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-44Z | M24308/24-44Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-45F | M24308/24-45F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-45Z | M24308/24-45Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-46F | M24308/24-46F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-46Z | M24308/24-46Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-47F | M24308/24-47F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-47Z | M24308/24-47Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-49F | M24308/24-49F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-49Z | M24308/24-49Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-50F | M24308/24-50F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-50Z | M24308/24-50Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-51F | M24308/24-51F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-51Z | M24308/24-51Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-52F | M24308/24-52F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-52Z | M24308/24-52Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-53F | M24308/24-53F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-53Z | M24308/24-53Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-55F | M24308/24-55F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-55Z | M24308/24-55Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-56F | M24308/24-56F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-56Z | M24308/24-56Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-57F | M24308/24-57F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-57Z | M24308/24-57Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-58F | M24308/24-58F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-58Z | M24308/24-58Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-59F | M24308/24-59F | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-59Z | M24308/24-59Z | 24308-5440-19 | ITT Cannon LLC |
| M24308/24-50F | HDC15M5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-50P | HDC15M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-50Z | HDC15M5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-1F | HDC9M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-1P | HDC9M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-1Z | HDC9M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-2F | HDC15M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-2P | HDC15M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-2Z | HDC15M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-3F | HDC25M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-3P | HDC25M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-3Z | HDC25M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-4F | HDC37M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-4P | HDC37M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-4Z | HDC37M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-5F | HDC50M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-5P | HDC50M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-5Z | HDC50M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-7F | HDC9M3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-7P | HDC9M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-7Z | HDC9M3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-8F | HDC15M3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-8P | HDC15M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-8Z | HDC15M3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-9F | HDC25M3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-9P | HDC25M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-9Z | HDC25M3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-10F | HDC37M3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-10P | HDC37M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-10Z | HDC37M3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-11F | HDC50M3P00C-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-11P | HDC50M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-11Z | HDC50M3P000-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-13F | HDC9M3P00C-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-13P | HDC9M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-13Z | HDC9M3P000-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-14F | HDC15M3P00C-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-14P | HDC15M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-14Z | HDC15M3P000-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-15F | HDC25M3P00C-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-15P | HDC25M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-15Z | HDC25M3P000-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-16F | HDC37M3P00C-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-16P | HDC37M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-16Z | HDC37M3P000-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-17F | HDC50M3P00C-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-17P | HDC50M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-17Z | HDC50M3P000-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-19F | HDC9M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-19P | HDC9M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-19Z | HDC9M3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-20F | HDC15M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-20P | HDC15M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-20Z | HDC15M3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-21F | HDC25M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-21P | HDC25M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-21Z | HDC25M3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-22F | HDC37M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-22P | HDC37M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-22Z | HDC37M3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-23F | HDC50M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-23P | HDC50M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-23Z | HDC50M3P000-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-25F | HDC9M5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-25P | HDC9M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-25Z | HDC9M5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-26F | HDC15M5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-26P | HDC15M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-26Z | HDC15M5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-27F | HDC25M5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-27P | HDC25M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-27Z | HDC25M5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-28F | HDC37M5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-28P | HDC37M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-28Z | HDC37M5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-29F | HDC50M5B800C-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-29P | HDC50M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-29Z | HDC50M5B8000-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-31F | HDC9M5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-31P | HDC9M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-31Z | HDC9M5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-32F | HDC15M5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-32P | HDC15M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-32Z | HDC15M5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-33F | HDC25M5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-33P | HDC25M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-33Z | HDC25M5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-34F | HDC37M5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-34P | HDC37M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-34Z | HDC37M5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-35F | HDC50M5B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-35P | HDC50M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-35Z | HDC50M5B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-37F | HDC9M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-37P | HDC9M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-37Z | HDC9M5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-38F | HDC15M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-38P | HDC15M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-38Z | HDC15M5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-39F | HDC25M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-39P | HDC25M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-39Z | HDC25M5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-40F | HDC37M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-40P | HDC37M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-40Z | HDC37M5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-41F | HDC50M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-41P | HDC50M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-41Z | HDC50M5B8000-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-43F | HDC9M5B800C-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-43P | HDC9M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-43Z | HDC9M5B8000-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-44F | HDC15M5B800C-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-44P | HDC15M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-44Z | HDC15M5B8000-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-45F | HDC25M5B800C-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-45P | HDC25M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-45Z | HDC25M5B8000-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-46F | HDC37M5B800C-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-46P | HDC37M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-46Z | HDC37M5B8000-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-47F | HDC50M5B800C-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-47P | HDC50M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-47Z | HDC50M5B8000-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-49F | HDC9M5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-49P | HDC9M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-49Z | HDC9M5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-51F | HDC25M5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-51P | HDC25M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-51Z | HDC25M5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-52F | HDC37M5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-52P | HDC37M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-52Z | HDC37M5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-53F | HDC50M5B800C-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-53P | HDC50M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-53Z | HDC50M5B8000-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-55F | HDC9M5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-55P | HDC9M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-55Z | HDC9M5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-56F | HDC15M5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-56P | HDC15M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-56Z | HDC15M5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-57F | HDC25M5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-57P | HDC25M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-57Z | HDC25M5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-58F | HDC37M5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-58P | HDC37M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-58Z | HDC37M5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-59F | HDC50M5B800C-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-59P | HDC50M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-59Z | HDC50M5B8000-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-61F | DD15M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-61P | DD15M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-61Z | DD15M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-62F | DD26M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-62P | DD26M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-62Z | DD26M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-63F | DD44M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-63P | DD44M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-63Z | DD44M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-64F | DD62M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-64P | DD62M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-64Z | DD62M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-65F | DD78M3P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-65P | DD78M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-65Z | DD78M3P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-67F | DD15M32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-67P | DD15M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-67Z | DD15M32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-68F | DD26M32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-68P | DD26M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-68Z | DD26M32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-69F | DD44M32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-69P | DD44M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-69Z | DD44M32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-70F | DD62M32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-70P | DD62M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-70Z | DD62M32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-71F | DD78M32P00C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-71P | DD78M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-71Z | DD78M32P000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-73F | DD15M4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-73P | DD15M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-73Z | DD15M4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-74F | DD26M4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-74P | DD26M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-74Z | DD26M4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-75F | DD44M4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-75P | DD44M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-75Z | DD44M4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-76F | DD62M4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-76P | DD62M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-76Z | DD62M4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-77F | DD78M4B800C-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-77P | DD78M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-77Z | DD78M4B8000-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-101 | HDC9M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-102 | HDC15M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-103 | HDC25M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-104 | HDC37M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-105 | HDC50M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-107 | HDC9M3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-108 | HDC15M3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-109 | HDC25M3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-110 | HDC37M3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-111 | HDC50M3P000-MIL-403.28 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-113 | HDC9M3P000-MIL-403.30 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-114 | HDC15M3P000-MIL-403.30 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-115 | HDC25M3P000-MIL-403.30 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-116 | HDC37M3P000-MIL-403.30 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-117 | HDC50M3P000-MIL-403.30 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-119 | HDC9M3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-120 | HDC15M3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-121 | HDC25M3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-122 | HDC37M3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-123 | HDC50M3P000-MIL-403.32 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-125 | HDC9M5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-126 | HDC15M5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-127 | HDC25M5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-128 | HDC37M5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-129 | HDC50M5B8000-MIL-403.34 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-131 | HDC9M5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-132 | HDC15M5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-133 | HDC25M5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-134 | HDC37M5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-135 | HDC50M5B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-137 | HDC9M5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-138 | HDC15M5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-139 | HDC25M5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-140 | HDC37M5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-141 | HDC50M5B8000-MIL-403.38 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-143 | HDC9M5B8000-MIL-403.40 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-144 | HDC15M5B8000-MIL-403.40 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-145 | HDC25M5B8000-MIL-403.40 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-146 | HDC37M5B8000-MIL-403.40 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-147 | HDC50M5B8000-MIL-403.40 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-149 | HDC9M5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-150 | HDC15M5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-151 | HDC25M5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-152 | HDC37M5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-153 | HDC50M5B8000-MIL-403.42 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-155 | HDC9M5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-156 | HDC15M5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-157 | HDC25M5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-158 | HDC37M5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-159 | HDC50M5B8000-MIL-403.44 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-161 | DD15M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-162 | DD26M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-163 | DD44M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-164 | DD62M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-165 | DD78M3P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-167 | DD15M32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-168 | DD26M32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-169 | DD44M32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-170 | DD62M32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-171 | DD78M32P000-MIL-403.27 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-173 | DD15M4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-174 | DD26M4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-175 | DD44M4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-176 | DD62M4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-177 | DD78M4B8000-MIL-403.36 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-201F | HDC9M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-201P | HDC9M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-201Z | HDC9M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-202F | HDC15M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-202P | HDC15M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-202Z | HDC15M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-203F | HDC25M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-203P | HDC25M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-203Z | HDC25M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-204F | HDC37M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-204P | HDC37M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-204Z | HDC37M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-205F | HDC50M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-205P | HDC50M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-205Z | HDC50M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-207F | HDC9M3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-207P | HDC9M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-207Z | HDC9M3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-208F | HDC15M3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-208P | HDC15M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-208Z | HDC15M3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-209F | HDC25M3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-209P | HDC25M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-209Z | HDC25M3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-210F | HDC37M3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-210P | HDC37M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-210Z | HDC37M3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-211F | HDC50M3P00C-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-211P | HDC50M3P00S-MIL-375.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-211Z | HDC50M3P000-MIL-403.29 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-212F | HDC37M3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-213F | HDC9M3P00C-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-213P | HDC9M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-213Z | HDC9M3P000-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-214F | HDC15M3P00C-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-214P | HDC15M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-214Z | HDC15M3P000-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-215F | HDC25M3P00C-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-215P | HDC25M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-215Z | HDC25M3P000-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-216F | HDC37M3P00C-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-216P | HDC37M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-216Z | HDC37M3P000-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-217F | HDC50M3P00C-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-217P | HDC50M3P00S-MIL-375.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-217Z | HDC50M3P000-MIL-403.31 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-219F | HDC9M3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-219P | HDC9M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-219Z | HDC9M3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-220F | HDC15M3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-220P | HDC15M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-220Z | HDC15M3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-221F | HDC25M3P00C-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-221P | HDC25M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-221Z | HDC25M3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-222P | HDC37M3P00S-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-222Z | HDC37M3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-223F | HDC50M3P00C-MIL-375.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-223Z | HDC50M3P000-MIL-403.33 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-225F | HDC9M5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-225P | HDC9M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-225Z | HDC9M5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-226F | HDC15M5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-226P | HDC15M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-226Z | HDC15M5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-227F | HDC25M5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-227P | HDC25M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-227Z | HDC25M5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-228F | HDC37M5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-228P | HDC37M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-228Z | HDC37M5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-229F | HDC50M5B800C-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-229P | HDC50M5B800S-MIL-376.6 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-229Z | HDC50M5B8000-MIL-403.35 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-231F | HDC9M5B800C-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-231P | HDC9M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-231Z | HDC9M5B8000-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-232F | HDC15M5B800C-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-232P | HDC15M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-232Z | HDC15M5B8000-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-233F | HDC25M5B800C-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-233P | HDC25M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-233Z | HDC25M5B8000-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-234F | HDC37M5B800C-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-234P | HDC37M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-234Z | HDC37M5B8000-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-235F | HDC50M5B800C-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-235P | HDC50M5B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-235Z | HDC50M5B8000-MIL-403.37 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-237F | HDC9M5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-237P | HDC9M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-237Z | HDC9M5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-238F | HDC15M5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-238P | HDC15M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-238Z | HDC15M5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-239F | HDC25M5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-239P | HDC25M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-239Z | HDC25M5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-240F | HDC37M5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-240P | HDC37M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-240Z | HDC37M5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-241F | HDC50M5B800C-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-241P | HDC50M5B800S-MIL-376.5 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-241Z | HDC50M5B8000-MIL-403.39 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-243F | HDC9M5B800C-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-243P | HDC9M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-243Z | HDC9M5B8000-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-244F | HDC15M5B800C-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-244P | HDC15M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-244Z | HDC15M5B8000-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-245F | HDC25M5B800C-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-245P | HDC25M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-245Z | HDC25M5B8000-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-246F | HDC37M5B800C-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-246Z | HDC37M5B8000-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-247F | HDC505M5B800C-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-247P | HDC50M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-247Z | HDC50M5B8000-MIL-403.41 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-249F | HDC9M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-249P | HDC37M5B800S-MIL-376.3 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-249P | HDC9M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-249Z | HDC9M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-250F | HDC15M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-250P | HDC15M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-250Z | HDC15M5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-251F | HDC25M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-251P | HDC25M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-251Z | HDC25M5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-252F | HDC37M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-252P | HDC37M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-252Z | HDC37M5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-253F | HDC50M5B800C-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-253P | HDC50M5B800S-MIL-376.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-253Z | HDC50M5B8000-MIL-403.43 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-255F | HDC9M5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-255P | HDC9M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-255Z | HDC9M5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-256F | HDC15M5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-256P | HDC15M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-256Z | HDC15M5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-257F | HDC25M5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-257P | HDC25M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-257Z | HDC25M5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-258F | HDC37M5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-258P | HDC37M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-258Z | HDC37M5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-259F | HDC50M5B800C-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-259P | HDC50M5B800S-MIL-376.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-259Z | HDC50M5B8000-MIL-403.45 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-261F | DD15M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-261P | DD15M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-261Z | DD15M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-262F | DD26M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-262P | DD26M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-262Z | DD26M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-263F | DD44M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-263P | DD44M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-263Z | DD44M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-264F | DD62M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-264P | DD62M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-264Z | DD62M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-265F | DD78M3P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-265P | DD78M3P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-265Z | DD78M3P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-267F | DD15M32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-267P | DD15M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-267Z | DD15M32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-268F | DD26M32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-268P | DD26M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-268Z | DD26M32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-269F | DD44M32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-269P | DD44M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-269Z | DD44M32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-270F | DD62M32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-270P | DD62M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-270Z | DD62M32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-271F | DD78M32P00C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-271P | DD78M32P00S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-271Z | DD78M32P000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-273F | DD15M4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-273P | DD15M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-273Z | DD15M4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-274F | DD26M4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-274P | DD26M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-274Z | DD26M4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-275F | DD44M4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-275P | DD44M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-275Z | DD44M4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-276F | DD62M4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-276P | DD62M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-276Z | DD62M4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-277F | DD78M4B800C-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-277P | DD78M4B800S-MIL | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-277Z | DD78M4B8000-MIL-403.0 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-301 | HDC9M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-302 | HDC15M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-303 | HDC25M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-304 | HDC37M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-305 | HDC50M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-307 | HDC9M3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-308 | HDC15M3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-309 | HDC25M3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-310 | HDC37M3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-311 | HDC50M3P000-MIL-799.8 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-313 | HDC9M3P000-MIL-799.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-314 | HDC15M3P000-MIL-799.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-315 | HDC25M3P000-MIL-799.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-316 | HDC37M3P000-MIL-799.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-317 | HDC50M3P000-MIL-799.9 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-319 | HDC9M3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-320 | HDC15M3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-321 | HDC25M3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-322 | HDC37M3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-323 | HDC50M3P000-MIL-799.10 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-325 | HDC9M5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-326 | HDC15M5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-327 | HDC25M5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-328 | HDC37M5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-329 | HDC50M5B8000-MIL-799.11 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-331 | HDC9M5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-332 | HDC15M5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-333 | HDC25M5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-334 | HDC37M5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-335 | HDC50M5B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-337 | HDC9M5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-338 | HDC15M5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-339 | HDC25M5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-340 | HDC37M5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-341 | HDC50M5B8000-MIL-799.13 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-343 | HDC9M5B8000-MIL-799.14 | 24308-3137-11 | Positronic Industries, Inc. |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-344 | HDC15M5B8000-MIL-799.14 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-345 | HDC25M5B8000-MIL-799.14 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-346 | HDC37M5B8000-MIL-799.14 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-347 | HDC50M5B8000-MIL-799.14 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-349 | HDC9M5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-350 | HDC15M5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-351 | HDC25M5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-352 | HDC37M5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-353 | HDC50M5B8000-MIL-799.15 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-355 | HDC9M5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-356 | HDC15M5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-357 | HDC25M5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-358 | HDC37M5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-359 | HDC50M5B8000-MIL-799.16 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-361 | DD15M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-362 | DD26M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-363 | DD44M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-364 | DD62M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-365 | DD78M3P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-367 | DD15M32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-368 | DD26M32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-369 | DD44M32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-370 | DD62M32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-371 | DD78M32P000-MIL-799.7 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-373 | DD15M4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-374 | DD26M4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-375 | DD44M4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-376 | DD62M4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-377 | DD78M4B8000-MIL-799.12 | 24308-3137-11 | Positronic Industries, Inc. |
| M24308/24-1F | 1218124-1 | 24308-127-97 | Tyco Electronics |
| M24308/24-1Z | 1757827-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-2F | 1218124-2 | 24308-127-97 | Tyco Electronics |
| M24308/24-2Z | 1757827-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-3F | 1218124-3 | 24308-127-97 | Tyco Electronics |
| M24308/24-3Z | 1757827-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-4F | 1218124-4 | 24308-127-97 | Tyco Electronics |
| M24308/24-4Z | 1757827-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-5F | 1218124-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-5Z | 1757827-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-7F | 1218125-1 | 24308-127-97 | Tyco Electronics |
| M24308/24-7Z | 1757839-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-8F | 1218125-2 | 24308-127-97 | Tyco Electronics |
| M24308/24-8Z | 1757839-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-9F | 1218125-3 | 24308-127-97 | Tyco Electronics |
| M24308/24-9Z | 1757839-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-10F | 1218125-4 | 24308-127-97 | Tyco Electronics |
| M24308/24-10Z | 1757839-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-11F | 1218125-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-11Z | 1757831-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-13F | 1218126-1 | 24308-127-97 | Tyco Electronics |
| M24308/24-13Z | 1757831-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-14F | 1218126-2 | 24308-127-97 | Tyco Electronics |
| M24308/24-14Z | 1757831-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-15F | 1218126-3 | 24308-127-97 | Tyco Electronics |
| M24308/24-15Z | 1757831-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-16F | 1218126-4 | 24308-127-97 | Tyco Electronics |
| M24308/24-16Z | 1757831-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-17F | 1218126-5 | 24308-340-76 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-17Z | 1757831-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-19F | 1218127-1 | 24308-127-97 | Tyco Electronics |
| M24308/24-19Z | 17578331 | 24308-125-99 | Tyco Electronics |
| M24308/24-20F | 1218127-2 | 24308-127-97 | Tyco Electronics |
| M24308/24-20Z | 1757833-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-21F | 1218127-3 | 24308-127-97 | Tyco Electronics |
| M24308/24-21Z | 1757833-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-22F | 1218127-4 | 24308-127-97 | Tyco Electronics |
| M24308/24-22Z | 1757833-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-23F | 1218127-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-23Z | 1757833-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-25F | 1218440-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-25Z | 1757835-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-26F | 1218440-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-26Z | 1757835-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-27F | 1218440-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-27Z | 1757835-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-28F | 1218440-4 | 24308-340-76 | Tyco Electronics |
| M24308/24-28Z | 1757835-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-29F | 1218440-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-29Z | 1757835-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-31F | 1218441-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-31Z | 1757837-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-32F | 1218441-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-32Z | 1757837-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-33F | 1218441-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-33Z | 1757837-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-34F | 1218441-4 | 24308-340-76 | Tyco Electronics |
| M24308/24-34Z | 1757837-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-35F | 1218441-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-35Z | 1757837-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-37F | 1218442-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-37Z | 1757841-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-38F | 1218442-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-38Z | 1757841-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-39F | 1218442-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-39Z | 1757841-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-40F | 1218442-4 | 24308-340-76 | Tyco Electronics |
| M24308/24-40Z | 1757841-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-41F | 1218442-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-41Z | 1757841-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-43F | 1218443-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-43Z | 1757843-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-44F | 1218443-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-44Z | 1757843-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-45F | 1218443-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-45Z | 1757843-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-46F | 1218443-4 | 24308-340-76 | Tyco Electronics |
| M24308/24-46Z | 1757843-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-47F | 1218443-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-47Z | 1757843-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-49F | 1218444-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-49Z | 1757839-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-50F | 1218444-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-50Z | 1757839-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-51F | 1218444-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-51Z | 1757839-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-52F | 1218444-4 | 24308-340-76 | Tyco Electronics |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/24-52Z | 1757839-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-53F | 1218444-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-53Z | 1757839-5 | 24308-125-99 | Tyco Electronics |
| M24308/24-55F | 1218445-1 | 24308-340-76 | Tyco Electronics |
| M24308/24-55Z | 1757845-1 | 24308-125-99 | Tyco Electronics |
| M24308/24-56F | 1218445-2 | 24308-340-76 | Tyco Electronics |
| M24308/24-56Z | 1757845-2 | 24308-125-99 | Tyco Electronics |
| M24308/24-57F | 1218445-3 | 24308-340-76 | Tyco Electronics |
| M24308/24-57Z | 1757845-3 | 24308-125-99 | Tyco Electronics |
| M24308/24-58F | 1218445-4 | 24308-340-76 | Tyco Electronics |
| M24308/24-58Z | 1757845-4 | 24308-125-99 | Tyco Electronics |
| M24308/24-59F | 1218445-5 | 24308-340-76 | Tyco Electronics |
| M24308/24-59Z | 1757845-5 | 24308-125-99 | Tyco Electronics |
| M24308/25-9F | ADI-C000-204190-28 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/25-9Z | ADI-Z000-204190-28 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/25-10F | ADI-C000-204200-28 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/25-10Z | ADI-Z000-204200-28 | 24308-1225-05 | ADI Electronics Incorporated |
| M24308/25-9F | 318-15-99-270 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/25-9Z | 318-15-99-270 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/25-10F | 318-15-99-272 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/25-10Z | 318-15-99-272 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/25-6F | D00000E20-MIL-462-31 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/25-6P | D00000E20-MIL-462-23 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/25-6Z | D00000E20-MIL | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/25-6P | 211883-5 | 24308-362-78 | Tyco Electronics |
| M24308/26-1F | ADI-C000-204180-31 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/26-1Z | ADI-Z000-204180-31 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/26-2F | ADI-C000-204180-62 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/26-2Z | ADI-Z000-204180-62 | 24308-84-89 | ADI Electronics Incorporated |
| M24308/26-1F | 318-15-99-273 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/26-1Z | 318-15-99-273 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/26-2F | 318-15-99-260 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/26-2Z | 318-15-99-260 | 24308-845-84 | Cinch Connectors, Inc. |
| M24308/26-1F | D00000T20-MIL-462.33 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-1P | D00000T20-MIL-462.7 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-1Z | D00000T20-MIL-462.32 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-2F | D00000T30-MIL-462.33 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-2P | D00000T30-MIL-462.7 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-2Z | D00000T30-MIL-462.32 | 24308-1051-87; 24308-1210-85 | Positronic Industries, Inc. |
| M24308/26-1P | 212447-1 | 24308-363-78 | Tyco Electronics |
| M24308/26-1Z | 5205817-8 | 1140, DTD 23 MAY 69 | Tyco Electronics |
| M24308/27-01F | CWR-281-9-0022 | 24308-148-85 | C W Industries |
| M24308/27-01F | FCC-281-9A | 24308-148-85 | C W Industries |
| M24308/27-01Z | CWR-281-9-0022 | 24308-148-85 | C W Industries |
| M24308/27-01Z | FCC-281-9A | 24308-148-85 | C W Industries |
| M24308/27-02F | CWR-281-15-0022 | 24308-148-85 | C W Industries |
| M24308/27-02F | FCC-281-15A | 24308-148-85 | C W Industries |
| M24308/27-02Z | CWR-281-15-0022 | 24308-148-85 | C W Industries |
| M24308/27-02Z | FCC-281-15A | 24308-148-85 | C W Industries |
| M24308/27-03F | CWR-281-25-0022 | 24308-148-85 | C W Industries |
| M24308/27-03F | FCC-281-25A | 24308-148-85 | C W Industries |
| M24308/27-03Z | CWR-281-25-0022 | 24308-148-85 | C W Industries |
| M24308/27-03Z | FCC-281-25A | 24308-148-85 | C W Industries |
| M24308/27-04F | CWR-281-37-0022 | 24308-148-85 | C W Industries |
| M24308/27-04F | FCC-281-37A | 24308-148-85 | C W Industries |

PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|---|---------------------------------|--|
| M24308/27-04Z | CWR-281-37-0022 | 24308-148-85 | C W Industries |
| M24308/27-04Z | FCC-281-37A | 24308-148-85 | C W Industries |
| M24308/28-01F | CWR-280-9-0022 | 24308-148-85 | C W Industries |
| M24308/28-01F | FCC-280-9A | 24308-148-85 | C W Industries |
| M24308/28-01Z | CWR-280-9-0022 | 24308-148-85 | C W Industries |
| M24308/28-01Z | FCC-280-9A | 24308-148-85 | C W Industries |
| M24308/28-02F | CWR-280-15-0022 | 24308-148-85 | C W Industries |
| M24308/28-02F | FCC-280-15A | 24308-148-85 | C W Industries |
| M24308/28-02Z | CWR-280-15-0022 | 24308-148-85 | C W Industries |
| M24308/28-02Z | FCC-280-15A | 24308-148-85 | C W Industries |
| M24308/28-03F | CWR-280-25-0022 | 24308-148-85 | C W Industries |
| M24308/28-03F | FCC-280-25A | 24308-148-85 | C W Industries |
| M24308/28-03Z | CWR-280-25-0022 | 24308-148-85 | C W Industries |
| M24308/28-03Z | FCC-280-25A | 24308-148-85 | C W Industries |
| M24308/28-04F | CWR-280-37-0022 | 24308-148-85 | C W Industries |
| M24308/28-04F | FCC-280-37A | 24308-148-85 | C W Industries |
| M24308/28-04Z | CWR-280-37-0022 | 24308-148-85 | C W Industries |
| M24308/28-04Z | FCC-280-37A | 24308-148-85 | C W Industries |

Manufacturer and Supplier Location Information

Manufacturer: ADI Electronics, Inc. (CAGE Code: 60430)

Location: 3920 Bryan Street, Dallas, TX 75204-6506, US

Assembly Plants:

1. ADI Electronics, Inc., 3920 Bryan Street, Dallas, TX 75204-6506, US)

Manufacturer: Amphenol Interconnect India Pvt. Ltd. (CAGE Code: SF116)

Location: 105, Bhosari Industrial Area, Pune, 411026, India

Assembly Plants:

1. Amphenol Interconnect India PVT LTD, 105 Bhosari Industrial Area, Pune 411 026, India)
2. PEI Genesis, 4747 Cleveland Rd Ext, South Bend, IN 46628,)

Manufacturer: C W Industries (CAGE Code: 79727)

Location: 130 James Way, Southampton, PA 18966-3838, US

Assembly Plants:

1. C W Industries, 130 James Way, Southampton, PA 18966-3818, US)

Manufacturer: C&K Components SAS (CAGE Code: F3132)

Location: 2 rue Berthollet, 39100 Dole, France

Assembly Plants:

1. C&K Components SAS, 2 rue Berthollet, 39100 Dole, France)

Manufacturer: Cinch Connectors, Inc. (CAGE Code: 71785)

Location: 1700 Finley Road, Lombard, IL 60148-4890, US

Assembly Plants:

1. Arrow Nogales, Blvd. Luis Donaldo Colosio, #1179 Interior, Entre Calle 5 de Febrero y Calle General Victoriano Huerta, Nogales, Sonora, 84048, Mexico)
2. Cinch Connectors de Mexico, SA de CV, Carretera Riberena KM 9, Reynosa, Tamaulipas, 88615, Mexico)
3. P.E.I. Genesis, 4747 W. Cleveland Road, South Bend, IN 46628, US)

Manufacturer: Cristek Interconnects, Inc. (CAGE Code: 67720)

Location: 5395 E. Hunter Avenue, Anaheim, CA 92807, US

Assembly Plants:

1. Cristek Interconnects, Inc., 5395 E. Hunter Avenue, Anaheim, CA 92807, US)

Manufacturer: Glenair, Inc. (CAGE Code: 06324)

Location: 1211 Air Way, Glendale, CA 91201-2497, US

Assembly Plants:

1. Glenair, Inc., 1211 Air Way, Glendale, CA 91201, US)

Manufacturer: ITT Cannon LLC (CAGE Code: 71468)

Location: 56 Technology Drive, Irvine, CA 92618,

Plants:

1. ITT Cannon, Nogales, Avenida del Libre Comercio S/N, Parque Industrial Nuevo Nogales, Nogales Sonora, Mexico 84093, Mexico

Manufacturer: Positronic Industries, Inc. (CAGE Code: 28198)

Location: 423 North Campbell, Springfield, MO 65801-8247, US

Plants:

1. Plant: Same Address as Manufacturer
2. Positronic Industries, Inc., 1325 North Eldon Ave, Springfield, MO 65803, US
3. Positronic Industries, Inc., 601 West Hayward Drive, Mount Vernon, MO 65712, US

Manufacturer: Souriau (CAGE Code: F0225)

Location: 9, rue de la Porte de Buc, 78000 Versailles, France

Assembly Plants:

1. Nihon Maruko Co., LTD., 2-8-8 Shinyokohama, Kouhoku-Ku, Yokohama, 222-003, Japan)
2. Souriau Champagne, RD323, 72470 Champagne, France)
3. Souriau Components Facility, Bat. A, Ilot 13, Lot 12, Zone Franche Aeroportuaire de Tanger, Route de Rabat, Tanger, 90000, Morocco)
4. Souriau Marolles, 3, rue du Vallon, 94440 Marolles-en-Brie, France)

Manufacturer: TE Connectivity Corporation (CAGE Code: 00779)

Location: 2800 Fulling Mill Road, Middletown, PA 17057-3163, US

Assembly Plants:

1. Arrow Electronics, Inc., Blvd. Luis Donaldo Colosio, #1179 Interior Entre Calle 5 de Febreo y Calle General Victoriano Huerta, Nogales, Cp 84048, Sonora Mexico, Mexico)

Manufacturer and Supplier Location Information

Manufacturer: TE Connectivity Corporation (CAGE Code: 00779)

Location: 2800 Fulling Mill Road, Middletown, PA 17057-3163, US

2. TE Connectivity Corporation / AMP Amermex (ADM), Blvd. Doctor Antonio Quiroga #22, Colonia El Llano C.P. 83210, Hermosillo, Sonora, Mexico)
3. TE Connectivity Corporation, 1250 East Main Street, Mt. Joy, PA 17522, US)

Authorized Distributors:

- 1.